

# Schmitt's Auto Repair

8470 Patel Pine Suite 636

## SERVICE INVOICE

Date: 2025-12-24

Invoice #: SVC-47435

**Vehicle:**

2015 Toyota Malibu

**Services:**

Brake Pad Replacement	\$255.48
Labor (2 hours)	\$174.36

**Total:** **\$429.84**