## **Universal Control 3.6.4**

Please read these notes carefully before proceeding.

Universal Control 3.6.4 PreSonus control and driver software.

Universal Control 3.6.4 PreSonus DSP USB Series Driver.

Universal Control 3.6.4 requires macOS version 10.13 or newer.

Universal Control 3.6.4 will:

Provide the latest audio drivers and control software for the following devices:

- StudioLive 64S Series III
- StudioLive 32S Series III
- StudioLive 32SX Series III
- StudioLive 32SC Series III
- StudioLive 32 Series III
- StudioLive 24 Series III
- StudioLive 16 Series III
- StudioLive 32R Series III
- StudioLive 24R Series III
- StudioLive 16R Series III
- StudioLive AR8 USB
- StudioLive AR12 USB
- StudioLive AR16 USB
- StudioLive AR22 USB
- StudioLive 16.0.2 Classic
- StudioLive 16.0.2 USB
- StudioLive 32.4.2AI
- StudioLive 24.4.2AI
- StudioLive 16.4.2AI
- StudioLive RM32AI
- StudioLive RML32AI
- StudioLive RM16Al
- StudioLive RML16AI
- Firmware for these products is available in your my.presonus.com account.

## Provide the latest firmware for the following devices:

- Studio 24
- Studio 26
- Studio 68
- Studio 1810
- Studio 1824
- FaderPort 8
- FaderPort 16
- FaderPort
- · ioStation 24c
- Studio 192
- Studio 192 Mobile
- Quantum
- Quantum 2
- Quantum 4848
- Quantum 2626
- ATOM
- ATOM SQ
- AudioBox 1818VSL\*\*
- AudioBox 44VSL\*\*
- AudioBox 22VSL\*\*
- AudioBox iTwo
- AudioBox iOne
- AudioBox USB 96
- Revelator
- SW5E

This Universal Control 3.6.4 Installer will remove any previously installed version of Universal Control AI and AudioBox VSL software.

\*NOTE: SMAART uses a firewire stream for the room analysis and firewire is not supported for AI/RM on M1.

\*\*NOTE: AudioBox USB is a class compliant audio interface and does not require a special driver in order to function. It works without installing any software, and it will not appear in the Universal Control device browser. It will only appear in Sound Preferences and in Audio MIDI Setup.

\*\*\*NOTE: Due to changes made by Apple in OS X 10.11 and later, the AudioBox VSL software will no longer function as designed. In order to continue to use the AudioBox 22VSL, 44VSL or 1818VSL on macOS 10.13 (or later), AudioBox VSL software must be completely removed from your computer. The AudioBox VSL software has been discontinued on all platforms, and Universal Control 3.6.4 does not include any VSL software mixing interface for the AudioBox products.

If you desire to use the Audiobox VSL software mixing interface features on OSX 10.8, 10.9 or 10.10, you will need to uninstall Universal Control 3.6.4 using the PreSonus Hardware Uninstaller script included with Universal Control 3.6.4 before proceeding with the re-install of older AudioBox VSL software.

For for more info: <a href="http://support.presonus.com/hc/en-us/articles/210044533-AudioBox-VSL-Software-Discontinuation-Notice">http://support.presonus.com/hc/en-us/articles/210044533-AudioBox-VSL-Software-Discontinuation-Notice</a>

Products not supported by Universal Control 3.6.4:

- StudioLive 24.4.2 Classic
- StudioLive 16.4.2 Classic
- FireStudio Project
- FireStudio Mobile
- FireStudio Lightpipe
- FireStudio Tube
- These products must use Universal Control 1.7.6

For more information on how to co-install Universal Control 3.6.4 and Universal Control 1.7.6 products, please visit our knowledge base at: <a href="https://support.presonus.com">https://support.presonus.com</a> and search the word "co-install"

If installing drivers, a restart of your system will be necessary after installation completes.

NOTE: Universal Control 1.7.6 ends at macOS 10.14 (Mojave).

For more information on PreSonus products visit <a href="http://www.presonus.com">http://www.presonus.com</a>