Refusal of MOT test certificate

① Vehicle identification number

QQIDAAAAAAA058568

Registration number
© Country of registration

GU09TRS GB

Make and model

Audi TT

S Vehicle categoryMileageM171,611 miles



7 Fail

© Do not drive until repaired (dangerous defects)



- Brake lining or pad missing or incorrectly mounted [reference 5.1.1 (a)]
- Brakes imbalance across an axle such that the braking effort from any wheel is less than 50% of the maximum effort recorded from the other wheel on a steered axle [reference 5.1.1 (a)]
- Steering gear casing fixing holes in chassis elongated to the extent that attachment is seriously affected [reference 5.1.1 (a)]

© Repair immediately (major defects)

- Relative movement between steering wheel and column indicating looseness [reference 5.1.1]
- Windscreen or window damaged or seriously discoloured and affecting the driver's view of the road or of an obligatory external mirror [reference 5.1.1 (a)]

3b Date of the test

10.06.2018

39 Location of the test

53, Call Road, Worthing BN12 6PB, United Kingdom

Testing organisation and inspector name

VTS004004 MILKE GROUP LIMITED R.DREWNO

MOT test number

3995 7555 7274

Check that this document is genuine by visiting www.gov.uk/mot-history

If any of the details are not correct, please contact DVSA by email at **enquiries@dvsa.gov.uk** or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at **www.gov.uk/mot-reminder** or by telephone on 0300 1239000.