

Box Speed: 200

1 Stop Slower: 100

2 Stops Slower: 50



# Minolta Hi-Matic F Meter Test Fuji 200

Sets of Three Bracketed  
(200, 100, 50)

Sets of Two Bracketed  
(100, 50)

Batteries were fresh

