

## ROUTE INFORMATION MANUAL EMERGENCY ESCAPE ROUTES

**WIDE BODY** 

Chapter: **10.3**Page: **39 - 94**Date: 17 SEP 14


G325 35nm NE GT - PS

CHART REFERENCES:

• ME (H/L) 5

• OPPS (Peshawar) DEST 1 ALT MES

• OPRN (Islamabad) DEST 1 ALT MES



**SEE INSTRUCTIONS NEXT PAGE** 



## ROUTE INFORMATION MANUAL EMERGENCY ESCAPE ROUTES

**WIDE BODY** 

Chapter: **10.3** Page: **40 - 94** 

Date: 17 SEP 14

## G325 35nm NE GT - PS

ENGINE FAILURE	DEPRESSURIZATION	ENGINE FAILURE + DEPRESSURIZATION
Apply OBSTACLE STRATEGY,      Continue on G325	<ul> <li>Continue to PS VOR on G325,</li> <li>Descend initially</li> </ul>	Apply OBSTACLE STRATEGY,      Continue to PS
to PS VOR.  • 100nm NE PS resume FIXED or	FL290,  • At GT descend FL200.	VOR on G325, • Descend FL290
STANDARD SPEED STRATEGY  • At PS divert to	100nm NE PS descend FL140      At 50nm NE PS	At GT initiate     EMERGENCY     DESCENT FL200      100nm NE PS
Peshawar (OPPS) or Islamabad (OPRN).	descend FL100 and divert to Peshawar (OPPS) or Islamabad (OPRN).	descend FL140  • At 50nm NE PS descend FL100 and divert to Peshawar (OPPS) or Islamabad (OPRN).