

OPERATIONS REVIEW

# Cutting changeover time on Line 4

What we changed, what it delivered, and what we need next.

# Agenda

|    |                        |    |
|----|------------------------|----|
| 01 | Where we started       | 3  |
| 02 | <b>What we changed</b> | 5  |
| 03 | Results so far         | 7  |
| 04 | Decision needed        | 10 |

01

# Where we started

Changeovers were the largest single source of lost capacity.

■ 01 · BASELINE

# Changeovers cost us almost a shift every week

---

**94 min**

AVERAGE CHANGEOVER

Target: 45 min

---

**11**

CHANGEOVERS PER WEEK

Up from 7 last year

**17 h**

CAPACITY LOST WEEKLY

≈ 2 shifts

SRC · Line 4 MES data, Jan–Mar, illustrative

## ■ 02 · METHOD

# We moved setup work outside the stoppage



Only the highlighted step still needs the line stopped.

■ 02 · METHOD

# A four-step method made the gain repeatable

01

## Film

Record three changeovers.

02

## Split

Mark each task internal or external.

03

## Shift

Move external tasks ahead of the stop.

04

## Standardise

Kit carts, checklists, quick clamps.

### LESSON


Kitting delivered the biggest gain.

03 · RESULTS

# Changeover time fell 41% in eight weeks

Average changeover time, minutes

Line 4, weekly



SRC · Line 4 MES, weekly average, illustrative

03 · RESULTS

# Only Line 5 still worsens

| LINE   | BEFORE  | NOW    | CHANGE | STATUS    |
|--------|---------|--------|--------|-----------|
| Line 2 | 88 min  | 71 min | -19%   | WATCH     |
| Line 3 | 102 min | 84 min | -18%   | WATCH     |
| Line 4 | 94 min  | 55 min | -41%   | GOOD      |
| Line 5 | 79 min  | 81 min | +3%    | OFF TRACK |



■ 03 · RESULTS

# Write the standard so anyone can follow it

---

## DO

Torque clamps to 40 Nm, then verify with the gauge on cart B.

---


## DON'T

Tighten the clamps properly before restarting.

Kitting delivered **more than half** of  
the gain — and costs almost nothing.

■ 04 · DECISION

## Expand to three lines by Q3



■ Pilot results reviewed with plant leadership

□ Approve €40k for six kit carts

□ Name a changeover lead per line

■ DECISION NEEDED

# Approve the Q3 roll-out?