
E1 LoE: Misclassification Destination Breakdown (Missed vs Confused)
SHAPE-CWT
Torque-CWT
GMO-CWT
EO-CWT
Missed (Nominal)
Confused (Other Fault)
Error Destination (%)
0
10
20
30
40
[0.02, 0.05)
[0.05, 0.10)
[0.10, 0.20)
[0.20, 0.30]
Severity [s_LoE (fractional torque loss)]