
E3 Overall Accuracy vs Excitation Quartile (Q1=Lowest, Q4=Highest)
Overall Accuracy (%)
100
90
80
70
60
50
40
Q1
(N=782)
Q2
(N=676)
Q3
(N=774)
Q4
(N=768)
Operating Excitation Quartile [Joint 2 RMS Velocity]
SHAPE-CWT
Torque-CWT
GMO-CWT
EO-CWT
SHAPE-Temporal
SHAPE-FFT