

Fryers: Frymaster H52

Card No. **FR032**

Fryer Boil Out

Frequency

Quarterly

Models

Frymaster H52 (Electric)

Estimated Time to Complete

90 Minutes

Health & Safety Hazards



Slippery Floors / Tripping



Hot Surfaces



Hot Oil



Chemicals

Food Safety























Wash and dry hands **after** performing this task




Inspect equipment. Do not use if damaged

Equipment





17




When cleaning is complete turn OFF Fryer using the **ON/OFF** button.



Allow to cool to below 50°C


18




Place the metal Bucket under Drain Nozzle. Do not drain into Filter Pan or Disposal Cart (SDU). Carefully open Drain Valve under the Frypot to be drained. Allow the Solution to Drain from the Vat then close Drain Valve. Carefully pour solution into backroom sink. **NB** Fill bucket 2/3 full at a time.

19

Scrub Frypot walls with Green Scouring Pad, Fry maintenance tool and Mcd Fry Cleanser to remove any remaining carbon build up.




20




Rinse Fryer at least twice with lukewarm water.

21



Ensure Drain Valve is closed.

22




Thoroughly dry the Frypot using kitchen roll.

23




Repeat process for other Frypots.

24




(Where applicable) Replace Fryer Capping Piece.

25



Install the filtering cart back into position using the handles provided. Close the doors.

26



Once the Frypots have been completed refill with McDonald's cooking oil to the fill line.