

Steamers: MEC - 1200

Temperature Calibration/Timer Cycle

Frequency	Weekly
Models	MEC-1200
Estimated Time to Complete	15 Minutes

Health & Safety Hazards



Hot Surfaces

Food Safety



Critical Control Point



Ensure nuts, bolts & screws are tight




Inspect equipment. Do not use if damaged




Wash & dry hands **after** performing task


Equipment



1 Pyrometer & Surface Probe



2 Extended Gauntlets



3 Stopwatch



