

RFQ Test Case B - Missing Attachments / Incomplete Package

Supplier-side internal validation document

1. Project Overview

Customer	Program	Part Name	Part Number	SOP	Annual Volume
NorthBridge Automotive	NB-EV Crossover	Rear Floor Mounting Bracket	NB-RF-2388	2027-05-15	220,000 pcs

This RFQ is intentionally incomplete for test purposes. The main RFQ references packaging and test standards, but those files are not included in the package.

2. Technical Requirements

- Manufacturing process: stamping plus restrike.
- Material: SPHC, 1.60 mm nominal thickness.
- General tolerance +/-0.10 mm unless otherwise specified.
- Surface finish: e-coat ready, oil-free condition required.
- Visible edge burrs not acceptable after secondary deburr.

3. Quality Requirements

- PPAP Level 3 required.
- Appearance sample approval required prior to PPAP.
- DV and PV test requirements per customer specification NB-QA-118.

4. Commercial Requirements

Incoterm	Payment Terms	Annual Cost Reduction	Quote Currency
FOB Shanghai	Net 75	2 percent after Year 1	USD

5. Referenced Attachments

- Attachment B1 - Cost_Template.xlsx
- Attachment B2 - Part_Drawing.pdf
- Attachment B3 - Packaging_Spec.pdf (missing on purpose)
- Attachment B4 - DV_PV_Test_Standard.pdf (missing on purpose)

Review expectation

The completeness checker should flag at least two missing attachments. Gap analysis should also identify risk around appearance approval and undefined packaging cost assumptions.