TASK_SOLENOID

Start

WAITING
The solenoid task doesn't do anything until another task wants the solenoid to be pressed

take_picture() called

timer = 0

TAKE_PIC
Turns on solenoid, then counts down for the length of the timer variable. When timer hits 0, releases solenoid