

$$z[n] = \boldsymbol{w}^{H}[n]\boldsymbol{x}[n] = \begin{bmatrix} w_{0}[n] \\ w_{1}[n] \\ \vdots \\ w_{M-1}[n] \end{bmatrix}^{H} \begin{bmatrix} x_{0}^{\Delta}[n] \\ x_{1}^{\Delta}[n] \\ \vdots \\ x_{M-1}^{\Delta}[n] \end{bmatrix}.$$
(1)