


HOW TO MAINTAIN THE EINSCAN - SP V2 3D SCANNER



Machine Maintenance



Machine Maintenance of 3D Scanner

- Keep well-ventilated. Environment temperature shall be below 40°C, and do not use the device under an environmentwith flammable or corrosive gas or another environment.
- Please grab and place gently in the proper position, and do not squeeze it. Prepare precautions like sunscreen, rain-proof, shock-proof, etc. No matter on sunny or rainy days.
- If the device could not function properly, fixing the device by opening it by yourself is not allowed. The device shall be repaired by professional techniciansor under their instructions.
- You should send the device to facilities with qualification for recycling it instead of dropping into the household garbage when it's scrapped.

Machine Maintenance

2

Cleaning the Machine

Prepare a clean cloth or microfiber cloth. you can also used tissues to clean the machine if cloth is not available



3

Cleaning the Calibration Board

Use plain water in cleaning the Calibration Board, do not use alcohol or any other chemical liquid to clean it