

HOW TO OPERATE CNC SHOPBOT-PR-SAlpha (ATC 120-60-8)



Machine Maintenance

CLEAN UP!

- **Store** all the drill bits and any other tools used in their designated storage area
- **Double-check** if the CNC machine and the surrounding areas are clean and tidy before leaving

