Task Scheduler

Check Button State (200ms)	- - - →	Read Temperature State (500ms)	- - - →	Update LED and UART State (1000ms)

Continous Scheduled Loop