Checkpoint #3 Obstacle Avoidance

Demo Due: 11/11/2022


Report Due: 11/18/2022

Outline

- CP 3 Supplies
- Checkpoint #3 Assignment
- Hardware Configuration
- GPIO of Raspberry Pi
- Light Sensor and Touch Sensor

CP 3 Supplies

Checkpoint#3 Material List			
14	1₽ Photo resistor sensor x1₽		
2↵	2₽ Touch sensors x3₽		
3₽	3₽ 47KΩ resistance x3₽		
4₽	4.₽ Breadboard.₽		
Team₽			
÷			




Checkpoint #3 Assignment

- The purpose of this checkpoint is to make sure you can control your robot to move in the arena. The mobile robot needs to detect an obstacle in front of it and take action to avoid the obstacle in order to continue its motion.
- Finally, your robot can find the assigned target. In this checkpoint, the target is a ring of LED lights.


Checkpoint #3 Grading Policy


- 1. Please start to arrange the space configuration of your robot, make sure every and each component such as circuit boards and sensors is settled **firmly and stable** on the chassis and all the robot functions will not be affected by wires. **(15%)**
- 2. Make sure that your robot can move freely. It means that you do not need to use keyboard to control it anymore. (20%)
- 3. Integrate a light sensor and three touch sensors to the robot and program your robot to find and move toward the LED light. (30%)
- 4. The time for you robot to find and touch the LED light (in 90 sec). (35%)

Checkpoint #3




Hardware Configuration





GPIO of Raspberry Pi

• GPIO: General-Purpose Input/Output



Wiring Pi: GPIO interface library

- WiringPi is an attempt to bring Arduino-wiring-like simplicity to the Raspberry Pi.
- The goal is to have a single common platform and set of functions for accessing the Raspberry Pi GPIO across multiple languages.
- Installation:
 - C: \$ sudo apt-get install wiringpi
 \$ sudo apt-get install libwiringpi2-dev
 - Python: \$ sudo pip install wiringpi2
- Check:
 - · \$gpio-v

pi@raspberrypi ~ \$ gpio -v
gpio version: 2.31
Copyright (c) 2012-2015 Gordon Henderson
This is free software with ABSOLUTELY NO WARRANTY.
For details type: gpio -warranty


Raspberry Pi Details:
 Type: CM, Revision: 02, Memory: 512MB, Maker: Sony
 Device tree is enabled.
 This Raspberry Pi supports user-level GPIO access.
 -> See the man-page for more details

Reference: http://wiringpi.com/download-and-install/

WiringPi's Pin number

Prints a table of WiringPi's Pin number on terminal.
 \$ gpio readall

Website Reference: https://pinout.xyz/pinout/wiringpi



Example Code

Sensor's pin is connected to Header pin 15

and the WiringPi pin is 3.

Include the Head file #include <wiringPi.h>

• Library setup function.

wiringPiSetup ();

Setup pin mode

int sensor_pin = 3; //wiringpi's pin
pinMode (sensor_pin, INPUT);

Read pin's data

sensor_data = digitalRead(sensor_pin) ;

```
WiringPi Pin Name
                                   Name
                                            WiringPi Pin
                        Header
              3.3v
                                     5v
                         3
     8
                            4
                                     5v
              SDA
                         5
                            6
                                     0v
             GPIO7
                            8
                                                 15
                                                 16
               0v
                         9
                            10
                                   GPI01
             GPI00
                        11
                            12
     0
     2
             GPI02
                        13
                            14
                                     0v
             GPIO3
                        15
                            16
                                   GPIO4
              3.3v
                                   GPI05
                                                 5
                        17
                            18
             MOSI
                        19
    12
                            20
                                     0v
    13
             MISO
                        21
                            22
                                   GPI06
                                                 6
             SCLK
                        23
                                    CE<sub>0</sub>
                                                 10
    14
                            24
                        25
                                    CE<sub>1</sub>
                                                 11
                            26
               0v
WiringPi Pin Name
                                   Name
                                            WiringPi Pin
                        Header
```


Photo resistor sensor


- Use Photo resistor sensor to detect the LED light.
- V_{cc} connect to Pi3's 5V.
- GND connect to Pi3's GND.
- D_0 connect to GPIO Pin.
- You can change the Variable Resistor to increase the sensitivity of the sensor. If the brightness is bright enough, D_0 will be 0.



Touch sensor

 Integrate touch sensors to avoid an obstacle and walls of the area.





Deadline

- Checkpoint#3 Demo: 11/11
- Checkpoint #3 Report : 11/18

Demo Time

Group A 09:30 ~ 10:30	Group B 10:30 ~ 11:30
Team 13	Team 7
Team 12	Team 6
Team 11	Team 5
Team 10	Team 4
Team 9	Team 3
Team 8	Team 2
	Team 1