



## Kingsway Guarantee Document:

**All Kingsway products are guaranteed by Kingsway Group from date of delivery, and at that time, to be of good material and workmanship and to be free of defects which would render said products unserviceable for the ordinary, recommended use.**

| Product Range                              | Guarantee Duration |
|--------------------------------------------|--------------------|
| Vision Panels (Duralux brand)              | 1 year             |
| Vision Panels (Pyrolux and Visilux brands) | 1 year             |
| Door Hardware                              | 1 year             |
| Washroom Items                             | 1 year             |
| Timber Doorsets                            | 1 year             |

**Kingsway Group will consider claims where failure or damage has occurred due to manufacturing defects or component failure, this would include poor workmanship and incorrect installation of components.**

**Limitations and Exclusions - All of these are subject to our 'Terms & Conditions of Sale' - all copy of which is available on our website <https://www.kingswaygroup.co.uk/terms/>**

- The guarantee is made to the original purchaser only and does not extend to subsequent purchasers during the period of this warranty.
- For a claim to be considered written notice must be sent to Kingsway Group within ten years from date of delivery.
- A site inspection must be performed by Kingsway Group prior to any claim being honoured.
- Whilst Kingsway products have been manufactured for mental healthcare environments the guarantee does not provide against malicious or deliberate damage being caused by the use of a weapon or implement or where negligence in the staff has resulted in a sustained physical attack.
- Natural variations in the colour or texture of wood are not to be considered as defects.
- Warp/bow/cup/twist (as set out in the relevant British Standard) shall not be considered a defect unless it exceeds 1/4" (6.35mm) in the plane of the door itself.
- Warp is any distortion in the door itself and does not refer to the relationship of the door to the frame or jamb in which it is hung.
- Kingsway Group will not accept responsibility for the development of warp/shrinkage
- or swelling when the moisture content of the timber falls below 12% or exceeds 18%.
- Kingsway Group shall not be liable for any Kingsway doorsets repaired, returned or replaced without prior consent.