

Thermal Survey Report

Property: Not specified

Inspector: Not specified

Survey Date: 2026-02-26

Executive Summary

1

TOTAL FINDINGS

0

CRITICAL ISSUES

0

HIGH PRIORITY

Detailed Findings

Finding 1: Heat loss at Window #7

Severity: MEDIUM | **Type:** Window

Temperature: Max 20.0°C / Avg 20.0°C / Min 20.0°C

Heat loss detected at window location. Temperature readings range from 20.0°C to 20.0°C, averaging 20.0°C. This represents moderate heat loss that should be addressed.



Recommendations

Window #7 (HIGH priority)

- Install thermal curtains or cellular shades
- Add weather stripping around frame
- Consider secondary glazing or window film
- Check for gaps and seal with appropriate caulk

Estimated savings: 10-20% on heating costs

Recommendations & Resources

Loading...

Your Survey Organisation

<https://example.com> | contact@example.com

Report generated on 2026-02-26 02:48