08HB048 – Standardized differences between Q.stat and E.Stat
P99 - P98 - P95 - P90 - P85 - P90 - P90 - P85 - P90 -

P80 -P75 -P70 -Variables showing Proportion of abs(diff) to mean P65 -P60 -P55 -P50 -P45 -P40 -P35 -P30 -P25 -P20 -P15 -P10 -P05 -

May

Jun

Month

Jul

Apr

Sep

Oct

Nov

Dec

Aug

P01 -

Feb

Jan

Mar