## Standardized differences between Q.stat and E.stat P99 -P95 -P90 -P85 -P80 -P75 -P70 -P65 -Variables showing Proportion of abs(diff) to mean P60 -Proportional difference P55 -0.0000 P50 -0.0025 P45 -0.0050 0.0075 P40 -0.0100 P35 -P30 -P25 -P20 -P15 -P10 -P05 -P02 -P01 -May Sep Feb Mar Apr Jun Jul Aug Oct Nov Dec Jan Month