

## TODO:

- Fix slider pot mechanical pins (L/R switch)
  Can we support either the SU or MU ATTINY variants simultaneously with overlapping footprints?
  Consider adding 3x AAA battery holder? Keystone 2479 looks like it could fit.

## CHANGELOG

## v1.1 -> v1.2

- Removed unnecessary solder jumpers
   Removed unnecessary solder jumpers
   Fixed incorrect placement of JP1. Now correctly disconnects slider pot from SCK for programming.
   Removed LED decoupling caps (not needed)
   Moved USB connector closer to board edge to solve mech interference
   Remove R1 (Mixed LED jumper pullup), use internal pullups in firmware
   Moved C1, C2 farther apart to ease assembly