



SW/FW Release note 2019.08.01

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release. The released software and firmware is applicable for AX32, DX32, Penta 720, Penta 721 and Avid MTRX, generally denominated AX32 in this document.

DADman control software	v.5.3.4 build 3
Compatible with Windows 7, 8 and 10 and Mac OS X, 10.10 to 10.14	
AX32 Main board firmware	v.2.3.0.1
AX32 Brooklyn II firmware	No update, still v.1.0.2.1

New features

DADman software v.5.3.4 has added functionality for having labels attached to the different digital interfaces installed in the card slots. The label applies for each port on the actual card, so for example for a dual MAD1 card installed in slot 4, each of the four ports, two input and two output ports can have an individual text label attached. The labels are entered in the set-up tab for the card and shown in the DADman matrix view. All labels are stored in the AX32.

Also support for the DigiLink Card provided for the Avid MTRX has been added. The DigiLink card is a exclusive product for Avid and can not be installed in AX32 or Penta 720.

Note: The new features requires the new Firmware V. 2.3.0.1 to be installed in the AX32.

The Application is loading faster on OS X, as well the general CPU load of the DADman applications is a few % less than before.

Support for Mojave. The previous version of DADman for OS X does not properly support Mojave. A workaround has been to enable the specific sRGBIEC699106-21 or GeneralRGB color profile for the screen. With DADman 5.3.4 working on Mojave works without any issues.

Bug fixes.

Some optimisations has been made in the Monitor Profile edit environment. The previous DADman version did have a risk to enter some dead lock modes in relation with the configuration of the SPQ functionality.

A small bug in the view related to the DigiLink card has also been fixed.



New features, DADman:

1. Support for Labelling the Digital Interface ports of the I/O cards.
2. Support for Mojave
3. Faster application load on OS X

Bug fixes, software:

1. Improvements in monitor profile and SPQ config