



SW/FW Release note 2020.08.20

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release of DADman control software Product firmware. The released DADman is applicable for the products AX32, DX32, Penta 720, Penta 721, Avid MTRX and Avid MTRX Studio, generally denominated the Products in this document. The Firmware is divided into a version dedicated MTRX studio and a common version for the other Products.

DADman control software:	v.5.4.3 build 2
Compatible with Windows 7, 8 and 10 and Mac OS X, 10.10 to 10.15	
Main board firmware:	
AX32, DX32, Penta 720, Penta 721, Avid MTRX	v.2.3.2.1
MTRX Studio	v.1.0.3.1
Brooklyn II firmware	No update, still v.1.0.2.1 (Dante version 4.0.9.1)

New features

DADman software v.5.4.3 has support for Max OS X Catalina and supports all products.

Some new functionality is also added, and it is recommended that the Products are updated with the latest firmware.

The new features are:

- ☐ Tool tips on buttons and knobs in the DADman GUI.
- ☐ Auto assignment of successive channels in the Monitor Profile Groups dialog.
- ☐ State of AD/DA/Mon/Con/Conf section in the DADman window is now stored in Preferences/Registry
- ☐ Checkmarks for selected values in popup menus.
- ☐ Warning added when a user tries to download older or already installed firmware to a unit
- ☐ Peak/hold on meters for AX32,Penta and MTRX (requires a firmware upgrade v.2.3.2.1)
- ☐ Text truncation on long channel labels

Bug fixes:

- ☐ Bass management not handled correct on MTRX Studio when the sub channels are not the last channels in a group
- ☐ Cue mix not handled correct
- ☐ Fixed weird display of delay rotary knobs when pressing "Remove unused groups"