



SW/FW Release note 2024.09.25

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release of the DADman control software and the updated firmware. The released functionality is applicable for the products AX32, DX32, Penta and DAD Thunder|Core series, MOM, Avid MTRX, Avid MTRX Studio, Avid MTRX II and Dynaudio Control 01, generally denominated the Products in this document.

This new release address various enhancements and bug fixes in DADman and in the Firmware for all Products except the MOM. This also include enhancements on various I/O Cards.

The details are listed below.

DADman control software:	MacOS	New
Compatible with MacOS 10.13 to 10.15 and MacOS 11, 12, 13, 14 and 15 with Intel or Apple silicon processor	v.5.7.2 build 1	
Windows 10 and 11	Windows	New
	v.5.7.2 build 1	
Thunder Core driver software:	MacOS	No change
DAD Thunderbolt 3 Core Audio Driver:	v.1.1.26	
Compatible with macOS 11, 12, 13, 14 and 15 Apple Silicon and Intel Computers		
	Windows	No change
DAD Thunderbolt 3 Windows ASIO driver	v. 1.1.2	
Compatible with Windows 10 and 11		
Main board firmware for:		
AX32, DX32, Penta 720, Penta 721s, Avid MTRX	v.2.4.3.1	New
Brooklyn 2 Dante module (Dante version 4.0.9.1)	v.1.0.2.1	No change
Brooklyn 3 Dante module (Dante version 4.2.3.8)	v.1.1.0.2	No change
Main board firmware for:		
MTRX Studio	v.1.0.4.2	New
MTRX Studio Dante 64 IPCore (Dante version 1.3.7.1)	v.1.0.0.4	No change



Main board firmware for:

AX64, AX Center, Core256 and Avid MTRX II	v.1.0.6.3	New
Dante 256 IPCore (Dante version 4.1.1.1)	v.1.0.2.1	No change

New in DADman

Added functionality

- Support for Thunderbolt 722150B module.
- The section buttons in the main window ("AD", "DA", "Mon", "Con" and "Conf") now have tool tips indicating the section contents and that clicking will collapse/expand the corresponding section.
- The "About DADman" now has a "Copy Information" button that copies version information to the clipboard. This includes a list of the connected devices, OS information and DAD Thunderbolt driver versions.
- The main menu now has an "Open Recent Profile" menu that allows reopening the most recently used profiles.
- **macOS:** Improvements to the Monitor Profile window:
 - The window is now resizable.
 - The last active tab in the Monitor Profile is restored when reopening the window.
 - The "Groups" tab:
 - A divider between the groups overview on the left and the details on the right can be dragged to change their sizes.
 - Monitor groups are expanded by default when the window opens.
 - When adding a new entry, it is automatically expanded, and its name is selected for editing.
 - New meter sets will be named "New meter set" instead of "New output set".
 - A confirmation dialog is shown before deleting all unused monitor groups.
 - A confirmation dialog is shown before deleting a single monitor group.
 - The "Group Formats" tab:
 - The top level "Preset" / "Custom" groups are now expanded by default. When collapsed, their state will be restored the next time the window is opened.
 - When copying or creating a new format, it is selected automatically.



- The "Move Up" / "Move Down" buttons are only enabled for custom presets and when the selected channel can actually be moved.
- Data validation in the "Create new format..." dialog is improved. The Enter key now saves the format.
- The "MOM" tab:
 - MOM entries are always expanded.
 - When the MOM list is updated, the selected entry will be restored if possible.
- **Windows:** The "Minimize to Tray" option is replaced by a "Show In" with three possible values:
 - "Taskbar only (default)": DADman behaves like a normal Windows application.
 - "Taskbar and system tray": DADman behaves like a normal Windows application but also shows an icon in the system tray.
 - "System tray only": When DADman launches, it will only show up in the system tray. To show the DADman window, left-click the DADman tray icon. The window can be hidden again by either minimizing it or right-clicking the tray icon and clicking "Hide".

In this mode, the DADman interface will be shown again if:

 - a. DADman is launched again.
 - b. A .dms or .dmpref file is opened.
 - c. DADman is told to exit (via the tray icon "Quit" menu item).
 - If "Minimize to Tray" was enabled in the previous DADman version, this setting will be set to "System tray only".

Changed

- When changing the firmware on a unit, the warning dialog now includes advice about backing up settings before proceeding.
- The phase invert buttons on AD channel strips now use a "Ø" symbol. This avoids the ambiguity of the previous "Ph" which could mean both "**Ph**antom power" and "**Ph**ase invert".

Fixed

- Fixed an error in mapping of monitor eq parameters when switching between monitor output sets.
- Windows: On some systems, DADman would fail to launch because of a missing VCRUNTIME140_1.DLL file.
- The networking stack has been improved to avoid device lock-ups in certain IP ranges when using the BitDefender firewall on Windows.
- **macOS:** DADman now alerts when failing to read or write files.



- Corrected Madi "Output frame rate" reporting for "DSD over PCM" output format is selected.
- Fixed out of bound access to monitor profile eq resource map after sample rate changes.
- Accumulated bass management sum input assignments to output channels with no channel assignment.
- **macOS:** File names in the "Open Recent" menu were URL encoded, turning spaces into "%20".
- **macOS:** When deselecting entries in the Monitor Profile window, the detailed areas on the right side did not always update.
- **Windows:** The keyboard shortcuts for "Import Profile..." and "Close Profile" now work.
- **macOS:** DADman now properly saves files on log out, restart and shutdown when the "Menu Bar Only" option is enabled, and the window is hidden.

New in the firmware

Native functionality for Thunder Core products and MTRX II

ADAT (Thunder Core only):

- ADAT ch. 3 @ 88.2/96 kHz problem corrected.
- ADAT input PLL improved.
- Improved ADAT input locking.

DigiLink (MTRX II only):

- Corrected potential problems on DigiLink interface (observed on MTRX I)

Dante:

- Corrected false card error alarm on Dante Cards.
- Added supervision of Xilinx FPGA for main board Dante and Dante Cards. Restart Dante if failing.

DADLink:

- Corrected DADLink sample rate output filtering (only transmit samples with the same sample rate as the transmitting unit).
- Changes to the sync word handling.

Thunderbolt:

- Support for 722150B Thunderbolt Module.

MADI:

- MADI coax output slew rate reduced.
- Corrected error in Madi native DSD format (main board).

DA (AX Center only):

- Corrected phase error on Analog base board.



- Delayed PLL base rate changes to avoid DA output clicks at sample rate changes.

Processing:

- Corrected conversion error of 0xffffffff fixed point to floating point.
- Corrected error in delay processing
- Corrected delay handling for channel numbers higher than 16 (not set after startup and sample rate changes)

Others:

- Communication to NIOS processor is now interrupt based
- Sector based flash protection was missing since the introduction of MTRXII. Has now been added again.
- Increased the number of allocated ethernet packages to prevent a crash when no buffers were available.

Native functionality for MTRX Studio

ADAT:

- ADAT ch. 3 @ 88.2/96 kHz problem corrected.
- ADAT input PLL improved.
- Improved ADAT input locking.

Dante:

- Added supervision of Xilinx FPGA for main board Dante. Restart Dante if failing.

Thunderbolt:

- Support for 722150B Thunderbolt Module.

DigiLink:

- Corrected potential problems on DigiLink interface (observed on MTRX I)

Processing:

- Corrected conversion error of 0xffffffff fixed point to floating point.
- Corrected error in delay processing

Others:

- Increased the number of allocated ethernet packages to prevent a crash when no buffers were available.
- Increased package size of output ethernet packages

Native functionality for Penta, AX32 and MTRX 1

DADLink:

- Corrected DADLink sample rate output filtering (only transmit samples with the same sample rate as the transmitting unit).



- Changes to the sync word handling.

Others:

- Automatic sending of edev notifications on UDP broadcast port if no client connected to the device.

I/O Cards for Thunder Core, Penta, AX32, MTRX II and MTRX I

Changes implemented in firmware for the cards. The firmware is a native part of the firmware on the respective base units. The cards themselves do not carry the firmware

DA Card:

- Corrected phase error on channel 8 on DA boards and AX Center Analog base board.
- Delayed PLL base rate changes to avoid DA output clicks at sample rate changes.

MADI Card:

- Improved sample rate conversion

AES/EBU card:

- Improved sample rate conversion.

Dante card:

- Improved sample rate conversion.

SDI card:

- Improved sample rate conversion.
- Support for device (internal) sample rates up to 96 kHz when using SDI output SRC.