



SW/FW Release note 2026.01.19

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release of the DADman control software and the updated firmware. The released functionality is applicable for the products AX32, DX32, Penta and DAD Thunder | Core series, MOM, Avid MTRX, Avid MTRX Studio, Avid MTRX II and Dynaudio Control 01/02, generally denominated the Products in this document.

This new release includes updated functionality for support of ST 2110-30 functionality on the Dante implementation of all our products as well as support for the new Card-Ravenna Ravenna/AES67/ST 2110 card. Furthermore, minor bugs have been fixed in DADman and the DADman settings for the Sample Rate Converter on the Dante and Ravenna Card has been expanded.

The details are listed below.

DADman control software:	MacOS	New
Compatible with MacOS 10.13 to 10.15 and MacOS 11, 12, 13, 14 and 15 with Intel or Apple silicon processor	v.5.8.2 build 2	
Please see note below on MacOS 15 compatibility		
Windows 10 and 11	Windows	New
	v.5.8.2 build 2	
Thunder Core driver software:	MacOS	No change
DAD Thunderbolt 3 Core Audio Driver:	v.1.2.2	
Compatible with macOS 11, 12, 13, 14 and 15 Apple Silicon and Intel Computers		
DAD Thunderbolt 3 Windows ASIO driver	Windows	No change
Compatible with Windows 10 and 11	v. 1.1.2	
Main board firmware for:		
AX64, AX Center, Core256, Avid MTRX II and Control 01/02	v.1.1.2.4	New
Dante 256 IPCore (Dante version 4.2.7.7)	v.1.0.3.1	New
Dante 256 IPCore version for MTRX II (Dante version 4.2.7.7)	v.1.0.3.1	New



Main board firmware for:

AX32, DX32, Penta 720, Penta 721s, Avid MTRX	v.2.4.6.4	New
Brooklyn 2 Dante module (Dante version 4.2.8.2)	v.1.0.3.1	
Brooklyn 3 Dante module (Dante version 4.3.1.8)	v.1.1.0.3	New

Main board firmware for:

MTRX Studio	v.1.1.6.3	New
MTRX Studio Dante 64 IPCore (Dante version 4.2.7.7)	v.1.0.3.1	New

Dante firmware for:

Dante Card (Dante version 4.2.7.7)	v.1.0.3.1	New
---------------------------------------	-----------	-----

New in DADman

- The Ravenna Card is supported
- In the settings dialogue for the Dante Card and the Ravenna Card, it is now possible to set the network related sample rate for the Dante and Ravenna network node when sample rate conversion is enabled.
- The number of meters shown in Eucon applications is increased to 16.

New in the firmware

The firmware for all base units supports the new Dante Firmware applicable for the base unit, and for modular units also the new Ravenna Card.

All Dante Firmware has been updated to the newest available versions. ST2110 and enhanced AES67 are now available for all Dante implementations when using DDM. For the Brooklyn-3 module you can use ST2110 without DDM which will require the newest version of the Dante Controller.

General

- Base unit Firmware supports the new versions of Dante Firmware
- Support for new versions of Dante Firmware providing ST 2110 functionality and enhanced AES67 functionality
- Support for the new Ravenna Card
- For more details on the Audinate functionality related to Dante, AES67 and ST 2110, and the Ravenna Card please refer to our website, www.digitalaudio.dk/2110-30-network-capabilities.



Bug Fix, Main fixes:

- DADman mac: Talkback menu not showing the correct selected value in the monitor profile configuration dialog.
- EuControl: Control Room level not enabled after switching Ref level in the monitor profile off.
- DADman mac: Improved communication between DADman and the units when connecting via Thunderbolt.
- A number of minor bug fixes

Note

You can install the Dante updates using the Dante Updater available in the Dante Controller. To install the Dante Firmware, you have to "Allow Imported Firmware" in "Advanced Settings" of the Dante Updater. Next import the relevant dnt-files by selecting "Imported Files" in the library tab. Finally select "Imported Firmware Files" in the Home tab and select the Dante unit you want to upgrade.

To install new firmware in the base units, find the unit in the device list in DADman, and right click, and select Update Firmware and load the new Firmware file.