

FAX

To: Rich Donnelson

Company: **MMSA**

Fax number: 714-373-1021

Phone number: 714-372-6141

From: Gary Forgue

Company: ASC

Telephone number: 313-246-0258

Fax number: 313-285-8557

Date: 31 January 1996

Pages: 7

Rich,

)

As requested in our meeting pesterday, following is a copy of our service database sorted in reverse order according to service date.

Let me know if the quality of this fax is inadequate for your use and we can forward you a clean copy.

Best Regards,

Jorce woke copy Carlos in PE Proce govis and full Rick fallata

٩	§								_												1295				282					1295			8 8	8 8		1295	-		1295			1295					1295	_		-	ç
إشارا	COS																				458.20				383.25				88	1642.50			8 2	66 097	1400 38	1482 34	542.50		1478.00	2155.97	715.00	732.95				88	271.00				3
1	ż	٥	ပ	۵	٥	٥	┙		Δ	٥	ပ	۵	۵	O	۵	ပ	U	۵	۵	٥	٥	ပ	۵	۵	۵	۵	O	ပ	٥	۵	٥	0	ما	ی اد	ء د	ی اد	۵	ပ	ပ	ပ	۵	ပ	۵	٥	ပ	۵	۵	۵	۵	٥	2
TE - 31	PROBLEM & KEPAIK	REPLOTS	REPLOTS ADJISHIM L TONN LATCH PADSIVELORO STOP	BENT OTR ARM: REPL TOP PUMP/MOTOR; OTR& TONN LAT	REPL HDR MOTOR: OTR & TOWN LAT TSB	ADJ TONN LATCH OTR WIN TSB, RE-ALIGN SASH SEAL	ADJ TONN LATCH-REPL, OTS	REPL PON CBL, AD., ULTCH MTR. MOD OTS. OTR WIN TSB&	REPL WEATHERSTRIPS-APPEARANCE	OTR WINDOWS BIND-PERFORM ISB	REPL OTS	LEAKS-WIND NOISE-REPR SEALS, REPLOTS, ADJ BAL LIN	REPAIR OTR WINDOWS-GRIND HEADER TRIM SCREWS	ADJ TONN LATCH OTR GLASS, ECU UPDATES	TOP HYD CYL LEAKING-REPL CYL-PERFORN GTR TSB	ADJ TONNEAU FLIPPERS AND LIMIT SWITCHES, CHK QTR	LEAKS-WIND NOISE-REPR SEALS REPOTS WIRE, CHK QT	REPAIR QTR WINDOWS	DENTED SAIL PANEL; ADJ RT FILPPER DOOR	REPAIR OTR WINDOWS-REVERSED OTR WIN SENSOR S	RT OTR GLASS INOP	WATER LEAKS REPL HEADER SEAL AND GMP MOLDING	REPLACE OTS	OTR WINDOW & TONN, LATCH TSB. REPL GMP MOLDING	REPAIR TOP ACTUATOR MOTOR	OTR GLASS TSB; ADJ SKIRT FROM TAIL LIGHT	NOISY OPERATION-LUBE ALL POINTS AND HINGES	REPLOTR GLASS&RT TONN, LATCH, PERFORM TSB, REP	HT TICKING NOISE WHEN OPENCLOSE	REPL ECU.ADJ TOP	TOP STOPS, WATER LEAKS AND NOISE-REPL SEALS AND	REPLOTR GLASS; 1SB(7); ADJ WIND SENSOR; REPLRT T	QIR GLASS SENSOR ADJUST	CEARCHER WEATHER STRINGER STANDARD	SQUEERS & RAILLES-AUSUSIMENI & PAUDING	PASSENGER WINDOW (FAKS OTR WINDOW 1SB	OTR WINDOW OUT OF TRACK	LEAK AT TOP SEAM, RATTLE ON PASS SIDE	WATER LEAK: REPL GMP MOLDING	HT WILL NOT OPERATE-R&R HYDRALICS	RH QTR GLS INOP-ADJ TONEAU LATCH AND SWITCH	NOT OPENING REPAIR HARD TOP AND A PILLAR	OTR GLS TRACK OUTSD AT BOTT-RUDDER MODIF	RATTLE IN TONEAU AREA-ADJ TONEAU LATCHES	WATER LEAK, REPL WEATHER STRIPS	ADJUST TONNEAU AND HEADER LATCHES AND OTR GLA	QTR&DR GLS INOPADJ LIMIT SWCHS.	RR HT SEAL LOW-HOR SEAL FOLDED-ORDERED SEALS	SAIL PNL INSERTS DENTED-R&R PARTS	WATER ON RESEAT SHIM HT WX SL RR OF OTR GLS	OTR WINDOW OUTSIDE OF TRIM-ADJUST
ORT	SMCD			_		_											_										S-7							ŗ	ر د	ā				S.7	9.1		Ş.1	85			ķ	\$17	\$17	\$-14	_
E REI	500 10	01/25/96				_	01/15/96		01/23/96				01/10/96		01/12/96							1227195	12/26/95	12/20/95		12/21/95	12/13/95	12/18/95			1228/95	12/14/95		100000	C6/51/21	12/14/95		12/06/95	12/08/95	iiiiii	12/5/95		12/7/95	12/8/95	01/02/96	12/07/95	12/4/95	12/5/95	12/5/95	12/1/35	
SER	DATE	01/24/96	01/23/96	01/22/96	51722/96	01/16/96	91/11/96	01/11/96	01/11/96	01/10/96	01/08/96	01/08/96	01/08/96	01/05/95	01/05/96	01/04/96	01/03/96	01/03/95	12/27/95	12/26/95	12/22/95	12/20/95	12/20/95	12/18/95	12/15/95	12/14/95	12/12/95	2/12/95	12/12/95	12/11/95	12/11/95	12/1/95	12/1/95	C6/90/21	CS//O/7	12/05/06	12/05/95	12/04/95	12/04/95	12/04/95	12/04/95	12/04/95	12/04/95	12/04/95	12/04/95	12/04/95	12/01/95	12/01/95	12/01/95	11/30/95	11/30/95
2	2	SY829354	SY819850	SY820124	SY820301	SY828539	SY810593	SY816508	SY828521	SY829555	SY828566	SY829061	SY829202	SY829576	SY829807	SY828566	SY828409	SY828925	SY829011	SY829548	SY829331	SY828805	SY829696	SY818836	SY817432	SY829861	SY812766	SY828415	SY829287	SY816247	SY817463	SY819153	SY828459	57614139	57810633	SY814618	SY819422	SY817126	SY819553	SY819850	SY828878	SY828911	SY829523	SY829631	SY829950	SY830856	SY817247	SY628568	SY829011	SY817 (26)	SY828935
			5348 (ANCASTER P SY819850	5106 VISALIA CA			OAKDALE MITSUBIS 35004 OAKDALE NY	44002 HOUSTON TX	COLONIAL MITSUBIS 46054 CHESAPEAKE	STEVE FOLEY MITS 15014 NORTH BROO	MCGINNIS MITSUBIS 44154 HOUSTON TX	19028 IMETAIRIE LA			45002 MURRAY UT	44154 HOUSTON TX	19028 INETAIRIE LA	۱.	20052 WOBURN MA	ORS	36003 PARMA OH	10015 CGHTHSE PT F	ш	MIAMI LAKES MITSU 10252 MIAMI LKS FL		49009 KENOSHA WI		10015 LGHTHSE PT F SY828415		JOLPH N.	BOISEID	46043 TAZEWELL VA SY819153	25019 ROLLA MO	51	SEURCINGIO	10097 CI FARWATER	15028 KIRKWOOD M	10195 DELRAY BCH	LESTER RAINES MIT 50001 CHARLSTON	5348 LANCASTER P SY819850	CLEARWATER MITS 10097 CLEARWATER	24002 MAPLEWOOD	ĕ			교	44013 IRVING TX			DELRAY MITSU 10195 DELRAY BCH	15028 K!RKWCOU M
MITSUBISHI 3000 GT	MITSU DEALER	MANHASSET MITSU	LANCASTER MITSU	LONG BEACH CA RAZZAR! MITSUBISH	MMSA	SANTA MONICA MIT		THOMAS MITSUBISH	COLONIAL MITSUBIS		MCGINNIS MITSUBIS	ROYAL MITSUBISHI			KEN GARFF MITSUB 45002 MUR	MCGINNIS MITSUBIS	ROYAL MITSUB SHI	BOULDER MOTORS			SPITZER MITSUBISH 36003 PARMA OH	KING MISTUBISHI	SUPERIOR MITSUBI		HUGGINS MITSUBIS	MAURO AUTO MALL	MANHASSET MITSU	KING MISTUBISH	RON BUCHARDS MI	SALERNO DUANE	TARGET MITSUBISH	MCCANN MITSU	SELLERS: SEXTON M 25019 ROLLA MO	RAMSEY MITSUBISH 32010 RAMSEY NJ	MOUNTANVIEW MIS	_		DELRAY MITSU	LESTER RAINES MIT	LANCASTER MITSU	CLEARWATER MITS	KLINE MITSUBISHI	MITS OF PLEASANT	TOWN NORTH #ITS	FRANK PARRA AUT	WHEATLEY MOTORS	FRANK PARRA AUT		WOBURN MITSU	DELRAY MITSU	AUFFENBURG MITS
	IC# LIC/CTY/ST	6209 WESTBURY NY	5215 CINMNSON NJ	9999 LONG BEACH CA	9999 LONG BEACH CA MMSA	9999 LONG BEACH CA	6209 WESTBERRY NY	HOUSTON TX	5325 ROANOKE VA	\$136 NORTHBROOK IL	HCUSTON TX	HCUSTON TX	5136 NORTHBROOK IL	ALITO RESTYLING CONC.ST. OUIS PARK N	5270 ISA: TIK CTY UT	HOUSTON TX	XT NOTSTON TX	SUNR DENVER CO	5207 BROCKTON MAS	SUNRIDENVER CO	WARREN OH	5168 BOCA RATON FL	SA TULSA OK	5168 BOCA RATON FL		5136 NORTHBROOK, IL MAURO AUTO MALL	6209 WESTBURY NY	5168 BOCA RATON FL KING MISTUBISHI	6869 PAWTUCKET RI	5214 BOGATA NU		5325 ROANOAK VA		5214 BOGATA NU	5207 BROCKTON WAS MOUNTANVIEW MIS IU	6/61 DALLAS IX	5150 ST LOUIS MO	5168 STUART FL	5325 ROANOAK VA	5215 CINMNSON NJ	5:68 STUART FL	ONCIST LOUIS PARK	5654 PACHECO CA	6761 DALLAS TX	5761 DALLAS TX	5325 ROANOAK VA	3751 DALLAS TX	5207 BROCKTON MAS	5207 BROCKTON MAS	5168 STUAR" FL	5150 ST LOUIS MO
	ER	SUPERIOR	0196 AUTO S/R CINN	0198 LBII	0199 LBII	0197 LBII	0165 SUPERIOR 6	0194 TOP KING	0195 MAXEY SEAT CV	LANG'S AUTO	TOP KING	O193 TOP KING	2	0185 AUTO RESTYLING	D186 ATD OF UTAH	┪	0191 TOP KING	10181 ROCKY MOUNTAIN SUNRIDENVER CO	0179 AUTO DESIGNS I	ιz	NR WARREN AUTO	0182 KELLEYS CUST T 5168 BOCA RATON FL KING MISTUBISHI	0170 AUTO TOPS OF THISA TULSA OK	0174 KELLEYS CUST T	NR	٥			AUTO S	NR PURICH 5	Z٨I	MAXEY SEAT CV		-		0466 WINSLOWS TRIM 6	٠	+	0177 MAXEY SEAT CV 5	AUTO S/R CINN	0161 KELLEYS CUST T 5	AUTO RESTYLING	0164 DSI	D168 WINSLOWS TRIM 6	0178 WINSLOWS TRIM 6761 DALLAS TX	0171 MAXEY SEAT CV 5	L.	0157 AUTO DESIGNS 1 5	l	0150 KELLEYS CUST T 5168 STUAR" FL	NR ICENTRAL SERVI 5

9	S				1295	8 8	253			1295	1295	1295	1195		1195		1195			7		8			8	193		ş	300	1295	200	8 8	G G	38			1195	1195	38	8	ß			40,	500	S2	T	1	1204	1.05	
	cost				220.18		8					1659.00	1454 50		1420.50		120.40				000	1038.00			98 40	424.00		479.00	3 6	147.55	20 2500	2007	2004.00	20100			1498.94	80.08	1455.12	722 60	576 20			200	300	00.512			25 28	7875 37	1
NUAR	OWN.	٥	٥			۵ د	1	S	٥	9	٥	ပ	ပ		_	_	U	٥	S	٥	١		اد	۵	را	١	٥	2	1	2	١	3 6	ם	20	۵	٥	υ	۵		ری	١	2	٥ (ے ر	٥	2	ľ	ے اد	2	7
SORT BY	1 - 1	HT WON'T ALIGN WITH HDR-SHIM HDR MLDING	HT&TONEAU NOT OPENING-ADJLIMIT SW-WIRE PINCHE	HT WON'T OPEN-HDR LATCH ROLL PIN BENT-R&R PIN	REPAIR OTR GLASS	OTR GLASS OUT OF TIME	ADJOTR WINDOWS	R&R GIMP SEAL	RH DR GLS INOP-BOTTOM OF 1/4 GLS OUTSIDE CHANN	REPAIR ALL LATCHES	HT INOP-RAISE STALL LIMITS-ADJ OTR SEAL-ADJ TON S	ADJOTR WINDOW, HEADLINER	ADJUATCHES AND REPROGRAM ECU	OTR GLS NOT CLOSING R&R ECU	WATER LEAKS QUARTER GLASS	114 GLS NOT FULLY CLSD-ADJ POSIT SENSORS	ADJUST TONNEAU LATCH	HT INTERMIT - NO STALL PERAMS AS PER TSB M003	1/4 GLASS CROSSOVER AT BOTTOM	HT WILDN'T RETRACT-R&R 1/4 GLS LIMIT SWITCHES	1/4 GLASS CROSSOVER AT BOTTOM	ADJUST QUARTER WINDOW	LH DOOR TO 1/4 GLS&LHA POST-ADJ SEALS & 1/4 GLS	OTR GLS NOT CLOSING-ADJ LATCHES & LIMIT SWTCHS	INOP GTR WINDOWS-REPL TOWN LATCHES	REPAIR QUARTER WINDOW	SEALS DISTORTED R&R AND ADJ SEALS ADJ DR GLS	REPL WEATHERSTRIP & GMP MOLLANG; LOWERED LOO	KEPAIK BROKEN WIRING	LEAKS BET RF PNLS-TOP OF A POST-LH 1/4 GLS AT SASH	KEPL DIS	WATER LEAK	TON LAICHES LET GO-REN LA LICHEROU LIMIT SWITCHS	1/4 GIS WOUNT RETRACT—RHI IMIT SWITH WIRE DAMA	OTR WINDOW INOP.PERFORM TSB-ADJ TOWN LATCH& LI	TONNEAU NOT STAYING LATCHED-R&R LATCHES	REPLACED ECU	IMPROPER FUNTION-RESET PERAMS & AUTO CONFIG	REPLOTS		1	HT WOULD'NT RETRACT PAST 1/2-RER OBJECT SENSOR	RIGHT OTR WDO OUT OF ADD. ADD SHIM	HT MANIFOLD LEAKING-R&R MANIFOLD	TIGHTENED LOCKNUTS ON RUDDER GDES.	ADJ TONN LATCH	TONNEAU PAINT - ASC ENG REQ RET TON-RPL TONN	IMPROPER FUNTION OF HT-RESET PERAMEAUTOCONF	TON WON'T ATCH-R&K TON LICHS AND ALS	ECUINOPERALIVE-REPAIR 10F	A4 WINDOWS WOOM CLOSE-SIC LIMIT CONTRACTOR
ORT	SMCD	5.7	8.5	2.5				814	S:1		2.7			S.1		S.1		2-5	S:1	8.	ę,		814	દ્ધ			2:5			S-14		;	3	7		8.5		25			ဖ၂	. 1	3	2.5	۶.		- 1	- [જુ	1	å
E REPORT	DTOUT	12/4/95	12/4/95	12/1/95				12/4/95	12/1/95		11/30/95			12/1/95		11/22/95		11/22/95	11/22/95	11/22/95	11/21/95		11/17/95	11/17/85			11/22/95	11/22/95		11/17/95			11/1/95	110105	11/17/05	11/13/95		11/14/95		11/13/95	11/13/95	11/17/95	11/8/35	יהייה	11/9/95		11/8/95	11/8/95	11/14/95	1000	2/1/2/11
`,	DATE IN	11/30/95	11/30/95	11/29/95	11/29/95	11/29/95	11/29/95	11/28/95	11/28/95	11/28/95	11/27/95	11/22/95	11/21/95	11/21/95	11/21/95	11/20/95	11/20/95	11/20/95	11/20/95	11/20/95	11/17/95	11/17/95	11/17/95	11/17/95	11/16/95	11/15/95	11/15/95	11/15/95	11/15/95	11/14/95	11/14/95	11/14/95	11/13/95	11/13/05	11/11/05	11/10/95	11/10/95	11/10/95	11/10/95	11/03/95	11/09/95	11/08/95	11/03/95	11/08/95	11/07/95	11/07/95	11/06/35	1106/95	11/06/95	11/03/95	CE/SOAL
3000 GT SPYDER SER	DEIC MITSU/CTY/ VIN	20017 HYANNIS MAS SY829034	20017 HYANNIS MAS SY829178	10012 ORLANDO FL SY814318		TUR AL	39089 ERIE PA SY829488	46043 TAZEWELL VA SY819153	AURORA CO SY819992	11072 ROME GA SY828424	5348 LANCASTER N.SY817264	35095 JACKSON HEI SY816079	10097 CLEARWATER SY813719	44096 N. RICHLANO HSY829085	43038 MEMPHIS TN SY829630	1 .		10009 MIAMI FL SY820147	DOYLESTOWNSY829973	_	VENTURA CA	5311 SHREVEPORT SY819483	2020 BIRMINGHAM \$7829944	35122 NEW ROCHEL	15002 SCHANSBURG SY812239		T			آ۵	19030 SLIDELL LA SY828451		_	HRMINGHAM SY828885	1.	_	1 -			PATRICK MITSUBISH 15002 SCHANSBURG SY812239		IRVING TX	¥	39087 PHILA PA SY829377	RILIVILE		9007 WIL MINGTON SY815816	SG		•	46013;FREDRICKSB SY828417
MITSUBISH	MITSU DEALER DEIC MITSU/CTY/			TSU		ᇷ	ROTH MITSUBISHI	MCCANN MITSU	MILE HIGH MITSU	=	<u> </u>	1-	_	_	_	NORMAN L/M MITSU	DENNIS MITSUBISHI	GOLD COAST MITSU: 10009 MIAMIFL	FRED BEANS MITSU	OKLAHOMACTYO NORMAN UM MITSU	TODEY MITSUBISHI	CHAMPION MITSUBI	TAMERON MITSU	PREMIUM MITSU	동	LOJ FUSZ MITSUBIS	KEN GARFF MITSUB 45002 MURRAY UT	KEN GARFF MITSUB	쯦	-			WHEATLEY MOTORS	SERRA MITSU	T	17		1_	WOBURN MITSU	PATRICK MITSUBISH	STOHLMAN MITSUBI				2	MILER MITSU	DELEWARE WITSU		PIONEER PARK MIT	MENTOR MITSUBISH 36033 MENTOR OH	ROSNER MITSU
	LIC/CTY/ST	BROCKTON MAS	5207 BROCKTON MAS HYANNIS MITSU	STUART FL		5177 CONYERS GA		5325 ROANOAK VA	6716 DENVER CO		5215 CINMNSON NJ	5201 ARCHMNT NY	5.58	CALLAS TX		REZA OKI AHOMACTYO		S168 STUART FL	Z	6624 OKLAHOMACTYO	5101 WAN NUYS CA		\$177 CONYERS GA	5201 NEW ROCHE NY		5150	1 1	5270 SALTIK CTY UT		5207 BROCKTON MA		1	ROANOAK VA	5177 CONYERS GA	SOLA CALCANDA COLONIA SOLO MITEL	5325 KOANOAN VA	ALL DOWN HOSE	S177 CONYERS GA		5139 PALATINE IL	5211 CAPITAL HTS MD STOHLMAN MITSUBI	6764 DALLAS TX	6763 SAN ANTONIO TX GILLMAN MITSU		5136 NORTHBROOK.IL		5215 CINMNSON NJ				5325 ROANOAK VA
	RP # ASC DEALER ILIC #	0154 AUTO DESIGNS I	+	↓_	1	NR KISER	22	0147 IMAXEY SEAT CV	1		AUTO S/R CINN	-	Ł	MINIST OWS TRIM	ك	VINY TOP SEECH	i	KEI EYSCUST T	AUTC S/R CINN	崇			0132 KISER-WAYNE B	┸			\vdash	0173 ATD OF UTAH	NR.	AUTO DESIGNS I	NR DEALER	NR.	(SEAT CV		_+	0169 MAXEY SEA! CV	⅃	KISER	DEALER	TUCKER AUTOM		15	.0115 CLASSIC	CINN		-	AUTO S/R CINN	ļ	R AUTOM		0135 MAXEY SEAT CV

9	Q ¥	1195	158		1195	S2	\$	2	1295	2	1295		1195		S	- 4		3 5	3 2	<u>7</u>	1295				8	,	28.5	5601	1095	1295	8	292	3	1295	1195	1095	135	1295		4005	3	1295	8	1195	195	1095	_]
)	COST	350 00	1422.92	687.16	818 8	353.30	15.	200	1990.65	385 40	61.50		505.01	200	70.00	307.30	2 6	30.00	1277 83	771.55	2185.96				803.00	00,000	314.51	1666.17	534.60	26.02	275.00	692 00	3	1082.63	677.25	1425.74	292.25	1323 65		2574 00	3	37100	588.00	SEE#098	2179.82	266.00	1
NUAR	OWN. C	۵	٥	۵	O	ء د	عاد	o o	O	U	٥	۵	O	O d	اد	ا د	,	ی ر	0	U	O	۵	O	۵	o l	S)	ء اد	٥	۵	υ	۵	ی د	3 0	O	۵	٥	۵	ن د		ء د	, (ם	۵	П	S	۵	2
E REPORT SORT BY SERVICE DATE - 31 JANUARY	PROBLEM & REPAIR	CABLE SYNCRONIZATION	REPLACED OTS	OTR WDO WISTR WRINKLED-RPLC W-STRIP	REPAIRED LATCH AND SWITCH	OPER, TOO NOISY: REAR WINDOWS CLOSE IN WRONG UIT	OTO WOOS INDO AD SWINE AD TOHES	OTR WIND MISA GN- AD OTR WIND & ADJ TON SW BUT.	1	1	POOR FIT TOP AND WISHIELD PILLAR	OTR EDOS WILL NOT CLOSE: ADJ TONNEAU LATCHES	REPLACE TONNEAU LATCH	OTR WDOS INOP. TRNK TRIM PNLS REST MEC-TRIMMED	OTR WDOS CLS O/S OF SEAL. ADJUIR WDOS	REPLACED ECU HARNESS	WARNING LIGHT WHILE DRIVING	WATER LEAK DR SIDE OVER DOOR- ALS DOOR GLASS	re complete call loc	OTR WDOS INDP 84DR LTCH INT- BUL #008 & ADJ RODS	REPL TOP MOTOR ADJ TONN-REP HEADLINER	TOP STOPS 1'2 OPEN. NOT OTS -TEC FROM PLT 11/2	BEND LH RUDDER ARM-R&R RH 1/4 GLS-R&R HT WX ST	MINER RATTLE: REATTACH VELCRO FASTENERS	WATER LEAKS	TOP STOPS 1/2 CLOSE. R&R HYD PUMP	QUARTER GLASS REPAIR	- - -	REATTACH & ADJ 1/4 GLS SEALS-ADJ 1/4 GLS GDES	REPAIR TPO-REPL SENSOR (OFS?)	OTR WINDOWS ALIGNMENT	HDR LTCH NOISE & SQUEEK, ADJ LTCH & PADDED	I GAY AT TOD 1/4 CIS PHRI LIAD I SEAL SEREND PLADER	OTR WDOS INOP-RPL ACTUATOR & ADJ TON LTCH	ADJUST SWITCHES	WATERLEAKS	TOP CYC NOT COMPLETING. ADJ TON LATCHES	QTR GLS INOP. ADJ TONNEAU LATCHES-REPLOTS	IQTR GLS INOP. ADJUTCHES TO NEW BULLETIN	MISALLIGNMENT DOOR & OTR GLASS. ADJ BOTH	т	OTS WIRE I COSE & OTR WIDG INOP. SOULDER & ADJ	CTR WINDOWS INDP	1 —	WATER LEAK & TON FUNCT-RPLC HOR SEAL & ADJ TON	TOP MALFUNCTION	OTR GLS STUCK ON SEAL. ADJOTR GLS
ORT	SMCD			ş		;	ة د	5 6	\$5.15			8.1		Ŷ.	Ġ		,	4		51.3		2-5	ب	Ÿ		S:7	2.14.15		<u> </u>			છે.	L.				S-7	5.1	ડે	\$ 12	2	y of		\$7-14	\$5-14		51
E REP	DTOUT			11/7/95		30,000	20105	117705	11/8/95	205		10/27/95		10/29/95	10/27/95			11/01/95		1007/95		10/25/95	11/3/95	10/23/95		10/31/95	40.07.05	10/23/95	10/23/95			10/19/95	30,04,04	10/19/95			10/18/95	10/16/95	10/13/95	10/13/95	C6101	50/21/04		10/24/95	10/24/95		10/1/95
_	DATE IN	11/03/95	11/03/95	11/02/95	11/02/95	11/02/95	50/10/11	110105	11/01/95	10/30/95	10/30/95	10/27/95	10/27/95	10/26/95	10/26/95	10/26/95	10/25/95	10/25/95	200000	1004/95	10/24/95	10/24/95	10/24/95	10/23/95	10/23/95	10/23/95	10/23/95	10/19/95	10/19/95	10/18/95	10/18/95	10/17/95	50,41,01	10/16/95	10/13/95	10/12/95	10/12/95	10/11/95	10/11/95	10/11/95	56/01/01	10/10/95	10/10/95	10/10/95	10/10/95	10/10/95	10/09/95
3000 GT SPYDER SEK	DE/C MITSU/CTY/ VIN	39002 PHILADELPHIA SY828475	39091 READING PA SY829394)	7041 GREENWICH	INE CA	COLD SPUS U. SY829378	48043 TAZEME! VA.SYR19153	STORY MENTINGHAM SYSDOMA	32027 FI FMINGTON	24002 MAPLEWOOD	5338 SANTA MONIC SY815548	COLLINS MITSUBISH 16003 INDIANAPOLIS SY828771	BAY RIDGE MITSUBI 35007 BROOKLYNN SY815007	ICHTHSE PT F	JACKSON HE	RCY NY	JAMES NY	BAY KILGE MILSUBIL SOUP BROOKLININ STRISM	SOUZ MANNASSEL IN	44001 HOUSTON TX	SNO CA	21025 ANNAPOLIS, M SY829962	32016 RANDOLPH NJ SY816247	VIENNA VA	44017 DALLAS TX	5086 BAKERSFIELD SY828695	4]_	RC	SHEEHEY MITSUBIS 46045 MANASSAS VA SY816885	35002 MANHASSET NSY814750	32016 RANDOLPH NJ SY816247	Z	44084 FORT WORTH	PATRICK MITSUBISH 15002 SCHANSBURG SY819509	WEST LOOP MITSUB 44084 FORT WORTH SY829449	35024 MARCY NY SY810369	35095 JACKSON HEI			1 44142 MESQUITE TX SY817481	387	T]	20054 DANVERS MA SY829371	32010 RAMSEY N. SY810387
MITSUBISHI 30do	MITSU DEALER DE/C MI	FAULKNER MISTUBI 39002 PHI	TOM MASANO MITS	GLOBAL MITSU	GREENWICH MITSU	TUTTLE CLICK WITS	PHIL LONG MITSU	ARI MORAN MILSO 10028 LAN	TAMEDON MITEL	EL FAINGTON MITSU	KLINE MITSUBISHI	SANTA MONICA MIT	COLLINS MITSUBISH	BAY RIDGE MITSUBI	KING MISTUBISHI	KOEPPEL MITSUBIS 35095	POLOZZI MITSU	SMITHTOWN MITSU 35054 ST	BAY KILCE MILSUBI	MANHASSEI MITSU	GILL MAN MITSURIS	MICHAEL MITSU	ANNAPOLIS MITSUBI	SALERNC DUANE	STOHLMAN MITSUBI 46001	EWING MITSU	HADDAD MITSUBISH	MILE FISH MILEO			SHEEHEY MITSUBIS	MANHASSET MITSU	SALERNO DUANE	STUMENAN MITSUS	WEST LOOP MITSUB	PATRICK MITSUBISH	WEST LOOP MITSUB	PCLOZZI MITSU	KOEPPEL MITSUBIS	ROCKVILLE MITSU	WANTAGH MITSU	BARRETT 1 44142 MESQUIT	I AND ASTER WITS!	CROWN MITSU	CROWN MITSU	DANVERS MITSU	RAMSEY MITSUBISH, 32010 RAMSEY N.
	LIC # LIC/CTY/ST	L		5214 BOGATA NJ			5715 DENVER CO	5158 BOCA KATON HL	5323 ROAMONE VA	DITI CONTERS OF	A TO BESTYLING CONCIST LOUIS PARK	5100 LOS ANGELES C	Sa	14 BOGATA NJ	5168 BOCA RATON FL KING MISTUBISHI			WESTBERRY NY	5214	CEES CANTACT ADA CA TO CASANTON MITS!	TO STONE TO		5211 CAPITAL HTS, MD ANNAPOLIS MITSUBI 21025 ANNAPOLIS, M	5214 BOGATA NJ	5211	6761 DALLAS TX	5101	5/16 DENVER CO	5211 CAPITAL HTS MD		5209	WESTBERRY NY	5214 BOGATA NU	5211 CAPITAL HIS MU SIOHLMAN MITSUEL 46001 VIENNA VA	6761 DALLAS TX		6761 DALLAS TX	6516 SYRACUSE NY				6761 DALLAS TX	JIDG BOCK KA CONTL	S168 ROCA RATON FL			5214 BOGA A NJ
	RP # ASC DEALER I			0114 PURICH	NR.	<u>۳</u>	0145 HIGH COUNTRY T	0112 KELLEYS CUST T	0113 MAXEY SEAL CV	O111 KISER	NP NITO PESTYLING		NR CLASSIC AUTO TOPS	0104 PURICH	0100 KELLEYS CUST T	AN.	NR RAYCOAUTO	0110 SUPERIOR	₹N	NR Sees Called Try Called	NED TOP VING		0118 CREATIVE CUST	0097 PURICH	NR.	0109 WINSLOWS TRIM	A.R.	0144 HIGH COUNTRY	0.034 MISER	NR	ADLER & MANDE	œ	0091 PURICH	0123 CREATIVE CUST	NP MINISTON'S TRIM		DOR WINSI OWS TRIM	0085 RAYCO AUTO					0078 KELLEYS CUST I	KELLEYS CLIST T	DOG KELLETS CUST T		0085 -PURICH

96	S			1195		5	1095		5 5	58	1095					2	1295	1195	1000	3	900	8	ş	3 5	3 2	1295	<u>-</u> 35		1195	1095	135	8	2 2	1095	88 895	1095	1195	38	<u> </u>	395	586	0995			9995			2882
`	COST			450.00		350.00	780.00		462.00	840.15	3165.46					814.50	1379.50	430.00	1,004	1461.01	20,020	3/0/6	21.2	475.00	2 2 2	495 00	867.53		509.39	2167.92	770 90	91.50	0 22 22	2207 95	773.45	875 66	3275.97	941.00	278 F2	3000	326 50	255.00			595.77			20 20 20 20
NUAR	OWN.	ပ	٥	۱	0 6	عاد	2	0	U	۵	O	U	ပ	۵	υ	Δ	ပ	۵	υ t	1	ء د	2	عاد	3 6	ماد	ם	٥	Ų	O	۵	O	O (مار	ם כ	0	٥	۵	٥	ے د	2		۵	۵	O	U	a	۵	۵
ORT SORT BY SERVICE DATE - 31 JANUARY	PROBLEM & REPAIR	S-16 CHIME COMES BK ON- ADJ TONN LTCHES PER BULLETIN	S-1 OTR WINDOWS INOP. ADJ TONNEAU LTCH SWITCHES		8:4	INICIAN IO DEALER IO 1290	ROOF STORS RING IN MANIJAL RELEASE CARLE	S.7.17 RF OP INT & OTR WDO DAMAGED. NOT FOUND & RPLCD	1	ů,	\$14.3	1	Т	T	1-	S-1 OTR WINDOWS ON RUBBER. ADJ WDOS & STOP	S-5-1 TON JAMMED & QTR WDOS INOP. ADJ TON & TON SWITH	ELECTRICAL PROBLEMS		\$17	ران ا	T	S./ KAN UPG & CTCLED FUR 3 DATS CLUNO! DUPE FROM	COLE YWINCOYN ALIGNMENT	WATER LEARS OF FROM WINDOW TALLOND	LINE LATOL AND COOR ON TRANSPORT	S-9 OBJECT IN TRUNK SENSOR BAD- REPLACED OTS	1	-	S-1 OTR WDOS INOP. ADJ TONNEAU LIMIT SWITCHES	FLIPPER DOOR REPAIR	T	S-3 HEADER LATCH INOP. LH HORLICH SW FELL OFF: RP	C 1 OTD WINDS OF SEAL SEAL CLIT, ANIMPERAIR	Т	ELECTRICAL FAILURE	S.7 HARDTOP OPP INT. REPLACE HYD SYSTEM	ヿ	OTR WINDOWS ALIGNMENT	DEINGTALL OF OTO CLASS	TOP STODE WILL EOPENING AND CLOSING	PEPI LATCH SWITCH	S-1 IDTR WINDOW CLOSING O/S OF SEAL- ADJ WINDOW	Τ.,	S.7 TOP STALLING ON CLOSING- INCREASED STALL PARM	S-5 TONNEAU WOULD NOT UNLATCH - ADJUATCH	S-9 OTS INOP - REPLACE OTS	ı
JE REPORT	DTOUT	10/17/95	10/10/95		10/13/95	10/10/35		10/12/05	2	40/13/95	10/8/05	10/5/95	10/6/95	10/6/95	10/5/95	10/4/95	10/4/95		10/3/95	10/6/95	10/4/95	502735	10/4/95				10/2/95	9/29/95		9728795			9727795	30,500	21712		9/27/95	9721/95					9/15/95	9721/95	9/18/95	9/14/95	9/15/95	9720735
	Z U	50/00/01 10/09/95	5208 10/09/95	-	_	_	520 40,000	4_		-	1	╄	4.	1_	L	↓_	L	1318 10/02/95	1	4	4	_		4	4	239 09/28/95	4-	┶	ļ.,	1	<u> </u>			387 09/21/95	1	<u> </u>	1	4			277 00/15/95		٫.	4		 _	L	3382 09/13/95
1 3000 GT SPYDER SE	TSUC	BAY RIDGE MITSUB! 35007 BROOKLYN N SY815007	1 10015 LGHTHSE PT F SY816208		46001 VIENNA VA SY816968	: [ب	FAULKNER MISTUBL 39002 PHILADELPHIA 51629473	3500 MANHASSET N	35007 BBOOKI YN N \$Y845007	ACOUT VIEWNA VA	40006 ST PETE EI	7041 CREENWICH	10007 CI EARWATER	20054 DANVERS MA SY829371	7"-	Ιż	7035 NEWBRITION SY819746	DON MEALEY MITSU! 10012 ORLANDO FL SY814318	5348 LANCASTER C	15011 DWN GROVE I	46001 VIENNA VA	MIAMI LAKES MITSU 10252 MIAMI LKS FL SY818836	32011 OCEAN TWINP	_	10177 LAKELANDFL	15002 PEORIA IL SY812239	2	2	P WA	32011 OCEAN TWNP	5091 SAN DIEGO C SY819307	CLEARWATER MITS 10097 CLEARWATER SY829936	10098 WEST PALM F SY818	MSEV N	SHAFFER MILSO 10028 MERRILLVILLE 318 14007	35007 MANHASSET NSY829034		32016 RANDOLPH NJISY816247	≸[MCGINNIS MITSUBIS 44154 HOUSIUN IX STOLISSON	150m HOMENOVIEL STRIESOS			32040 FREEHOLD N	35002 MANHASSET NSY829034	15010 NORMAL IL ,SY829382
MITSURISH 3000	MITSU DEALER				STOHLMAN MITSUB	SEA COAST MITSU	FAULKNER MISTURI	MANUACCET MITCH	DAY OFFICE MITCHES	ETOLI MAN MITCH	ODCIMENTAL MITCH					WANTAGH MITSU	SCHALLER MITSU	DON MEALEY MITSI	LANCASTER MITSU	IMAX MADSEN MITS	STOHLMAN MITSUB		SEA COAST MITSU	CANNON MITSUBISH	CANNON MITSUBISH		GOLD COAST MITSU TUDUS MIAMI FL	COLOCOAST MITSH 10009 MIAMI FI	KORUM MITSUBISH	SEA COAST MITSU	SAN DIEGO MITSUBI	CLEARWATER MITS	WEST PALM MITSU	RAMSEY MITSUBISH 32010 RA	SHAFFER MILSO	MANHASSET MITSU	PARKWAY MITSU	SALERNO DUANE	SHEEHEY MITSUBIS	PARKWAY MITSU	COURTESY MITSU	MCGINNIS MITSUBI	CUNICE MITCH	DENINIS MITS IBISE	PARRA MITSU	FREEHOLD MITSU	MANHASSET MITSU	PARKWAY MITSU
	C# LIC/CTY/ST	1214 BOGATA NJ	5168 BOCA RATON FL		5211 CAPITAL HTS.MD STOHLMAN MITSUBI 46001 VIENNA VA	5214 BOGATA NJ	1000	SESSA PACHECO CA	SOUS WESTBERRING	2	SZTI CAPITAL HIS MU	S165 BOCK RATON F.	SZOL CARCHIMINI NI	STORE BOCK ROLLOW TO	SEAR EYDACINE NY	SOI LARCHMIT NY	YOU I ARCHMINT NY		5101 VAN NUYS CA	5136 NORTHBROOK IL IMAX MADSEN MITS	5211 CAPITAL HTS,MD	5168 BCCA RATON FL	5214 BOGATA NJ	5273		5139 PALATINE IL	KELLEYS CUST T 5168 BOCA RATON FL	5450 BOCK BATONE	שומים שומים	S214 POCATA N.			5168 BOCA RATON FL		5136 NOR THBROOK IL	DW SICOL STOCK	5136 NORTHBROOK IL PARKWAY MITSU	5214 BOGATA NJ	5209 SHEEHEY MITSUB	5136 NORTHBROOK IL			I ACCOUNT OUT	A SOUND HORITON IL	STEI DAILAS TX	5214 BOGATA NJ	6209 WESTBERRY NY MANHASSET MITSU	5135 NORTHBROOK IL PARKWAY MITSU
	RP # ASC DEALER LIC#	DOR9 PURICH 5	٦	-			AUTO SUNROOF I	2	¥	+	┵	00/4 KELLETS CUS) 1 3		DOIZ RELLETS CUST : 3	1	ONRI MITO SIR LARCH	MANUAL TO SEE LABOR SOOT LABORHANT NY	S S S S S S S S S S S S S S S S S S S	I ASC VALLEY	Н	Н	Н	1	NR ASCFLORIDA 5	N.S.		NR KELLEYS CUST T	DOGS PURICH		DOIN IN DIO			KELLEYS CUST T		LANG'S AUTO	NR CENIKAL SERVI	I ANG'S AUTO	PURICH	ADLER & MANDE	NR LANG'S AUTO 5	œ	XX.	†	+	OOSS AUTO CATE TOTAL B		æ	2

TD: JAN 31 90 10:43 No.019 1.

96	ΘM	9889	988	0895		0895	0895	0995					0895	0895			1095		0895	0995		0795	0895	0795	2895	0795	0895	0895		0695	0795				0895	T
^	COST	182.00	1769.36	187.50		340.00	340.00	1187,70					485.50	475.00			942.76		663.00	170.00		342.25	516.25	542.00	409.28	645.00	432.78	527.18		289.50	470.00				325.00	134617.92
NUAR	OWN. COST	ပ	ပ	٥	۵	۵	۵	ပ	a	۵	٥	Q	٩	ً ا	۵	a	3	ပ	٥	ပ	S	O	۵	۵	۵	۵	Δ	۵	Δ	۵	٥	۵	Δ	ပ	U	
GT SPYDER SEK. JE REPORT SORT BY SERVICE DATE - 31 JANUARY	D PROBLEM & REPAIR	HALINER RATTLE - ADJ HALINER & TIGHTENED SCRS	S-14-5 WATER LEAK TOP A-PIL-TON FUNCT- RP SEAL& CYL	JADJ OTR GLASS	TON LATCH INT-HIT STALL 1/3 -ADJ LTCH-RRSTL PAR	DOOR GLS CROSSING OTR GLS- ADJ DOOR GLS	QTR WINDOWS MISALLIGNED- ADJ QTR WINDOWS	REPL TOP PUMP AND MOTOR	SECOND TIME IN SENT TO PLANT - CHG ECU	H/T STOPS 1/3 OUT OF TRUNK. ADJ RRSTL PAR	GTR WINDOWS INCP. ADJ TONN LIMIT SWITCHES	PAS DOOR GLS INOP. INST 60 AMP FUSE	TOP FUNCT INT. HOR LIMIT SWITCH WIRE ROUTING	TONN JERKY AND WIND NOISE	OTR WINDOWS MISALLIGNED- ADJOTR WINDOWS	HAT INOP. DIAGPINPOINT TESTS- CHG ECU	HAT SEAL POPPING OUT @ CTR. RINVD CARPET DIN STP	OTR WDOS INOP-NOISE IN HITOP ADJ TON LTCH	HDR LATCHES NOT GENING. ADJ HDR LATCHES	TON LATCH INOP & HOR LATCH INT -ADJ & MVD WIRE	4 LEAK & NOISE ADJ TONNEAU & RAN AUTOCHFG	HDR LTCH INT. REPLACED MOTOR ASSY & ADJ	OTS INOP. REPLACE OTS	OTR WIDOS INOP - ADJ TONNEAU LATCH SWITCHES	RET WITH OTR WDOS INOP- ADJ TON LATCH SWITCH	Q1R WDOS OPER INTERMITTENT. ADJ TON SWITCHES	RH TONNEAU LATCH WILL NOT LATCH - ADJ LATCH	DEFECTIVE OTS -REPLACED	HAT OPER INTERMITTENT: PLANT REPAIRED	BROKEN FLIPPER DOOR CABLE- REPLACED	LH GTR WDG 0/S OF OUTER SEAL - ADJ WDG	A-PILLAR SEAL SHINGLE BROKEN (DEALER REPLACED)	HT WOULDN'T RETRACT R&R PUMP & CYLINDERS	HT INTERMIT-CHGED PERAMS PER TSB M009	OTS INOP VEH HAD BEEN TO BENEFIT OTHER PROBS	
OR1	SMICI	\$4	\$14.5		\$5.7	P.13	S-1		S7	S-7	5.	\$ 12	<u>ئ</u>		S-1	S-7	S-17	S-1-7	မှ	\$53	\$5-14	S-3	8.9	S.	<u>?</u>	s-1	S-5	8-9	<u>ئ</u>	S-10	<u> </u>	817	5.7	S-7	8	
EREP	DT OUT SM/CD	8/11/95	8/17/95		877/95	87785	97795		877/95	8/4/95	873/95	8/4/95	8/3/95		56/97/2	82/95	707795	8/3/95	7/25/95	7/13/95	7/12/95	56/21/2	7/6/95	6/26/95PM	M426/92/9	6/26/95AM	M456/12/9	M9591129	96/6Z/9	Md96/17/9	6/14/95PM	Wd56/8/9	11/29/95	w	8/16/95	
SER	DATE IN	08/10/95	26/03/95	08/07/95	08/07/95	08/04/95	08/04/95	08/02/95	08/02/95	08/02/95	08/01/95	08/01/95	07731/95	07/28/95	07/25/95	07/25/95	07/24/95	07/21/95	07/21/95	07/12/95	07/10/95	07/06/95	07/03/95	06/26/95	06/23/95	06/22/95	06/20/95	06/20/95	06/20/95	06/19/95	06/08/95	06/07/95	uiui	ш		
YDER	NIN	SY819636	SY810562	SY813719	SY819322	SY813995	SY816907	SY814616	SY815246	SY817264	SY816618	SY817126	SY816230	SY819286	SY816168	SYB16247	SY810554	SY815348	SY816054	SYB18917	SYBISIAB	SY819843	SY814616	SY814948	SY814668	SY810477	SY814668	SY815039	SY815246	SY812756	SY810615	SY814750	SY828498	SY829365	SY810554	
		3003 SLT LK CTY U SY819636	1001 ROCKVILLE M	097 CLEARWATER SY813719	39087 PHILADEL PHIA SY819322	15037 ELGIN IL	15037 ELGIN :L	10097 CLEARWATER SY814616	5338 SANTA MONIC SY815246	32001 MAPLE SHADE SY817264	15029 CRYSTAL LK I	10195 DELRAY BCH	15014 NORTH BROO	2013 ORLANDO FL	32016 RANDOLPH NJ SY816168	32016 RANDOLPH NJ SYB16247	20017 HYANNIS MA	5338 SANTA MONIC SY815348	3007 BROOKLYN N	5002 VAN NUYS CA SYB18917	338 SANTA MONIC	10006 ST PETE FL SY819843	10097 CLEARWATER SY814616	5340 CTY OF IND C SY814948	5274 RIVERSIDE CASY814668	5259 IRVINE CA	5274 RIVERSIDE CASY814668	5317 NORCO CA	338 SANTA MONIC	5291 TUSTIN CA SY812756	32016 RANDOLPH NJ SY810615	35002 MANHASSET NSY814750	44013 IRVING TX	20052 WOBURN MA SY829365	20017 HYANNIS MA	
MITSUBISHI 30d0	MITSU DEALER IDE/C M	JERRY SEINER MITS 45003 SL	ROCKVILLE MITSU 21001 ROCKVILLE M SY810562	CLEARWATER MITS 10097 CL	METRO MITSU 36	BIGGERS MITSU 1	BIGGERS MITSU 15	IIS	SANTA MONICA MIT	HOLMAN MITSU	TSU	 	MITS	FOUNTAIN MITSUBIS 10013 ORLANDO FL			1-	SANTA MONICA MIT	BAY RIDGE MITSUBI 35007 BROOKLYN N SY816054	MILLER MITSU	TIM A	⊢	E S	ı		TUTTLE CLICK MITS :	QUAID MITSU	NORCO MITSU	A MIT	MAC PHERSON MIT	(-)	2	 	Г		
	LIC/CTY/ST	SLTLKCTYUT	L	ı.	5215 CINMNSON NJ	Γ			5100 LOS ANGELES C	5215 CINMNSON NJ	Ī	Ä	5 NORTHBROOK IL		5214 BOGATA NJ		2	5100 LOS ANGELES C	5214 BOGATA NJ	Ą) LOS ANGELES C	5273 CLEARWATER FLICROWN MITSU	3 CLEARWATER FL	5103 SANTA ANA CA		5103 SANTA ANA CA	5103 SANTA ANA CA	1	17		Π	9 WESTBERRY NY	1 DALLAS TX	7 BROCKTON MAS WOBURN MITSU	5207 BROCKTON MAS HYANNIS MITSU	
_	LIC #	5270	L.,	1	5216	1_	←	-	5100	5215	┿	<u> </u>		L	5214	5214	↓	μ.	5214	5101	5100	527	527.	5100	510	5103	510	510	5100	5103	5214	9208		4—	\bot	
	RP # ASC DEALER LIC #	0095 ATD OF UTAH	0027 ADLER & MANDE	EN.	0031 AUTO S/R CINN	0020 TUCKER AUTOM	0019 TUCKER AUTOM	NR.	DO16 ASC LA	0030 AUTO S/R CINN	DO18 ITUCKER AUTOM	0021 KELLEYS CUST T	0017 LANG'S AUTO	N.	0015 PURICH	0034 PURICH	0105 BENEFIT AUTO S	0022 ASC LA	0014 PURICH	0013 ASC VALLEY	0011 ASC LA	0012 ASC FLORIDA	DO10 ASC FLORIDA	DO09 ASC BRITAX	DOOG ASC BRITAX	DOOR JASC BRITAX	DODS ASC BRITAX	DOCA ASC BRITAX	0007 ASC LA	0003 ASC BRITAX	DOO! PURICH	0002 SUPERIOR	0140 WINSLOWS TRIM	0155 AUTO DESIGNS 1	0023 AUTO DESIGNS	



6400 KATELLA AVENUE CYPRESS, CALIFORNIA 90630-5208 (714) 372-6000 (310) 493-1235 TELEFAX (714) 373-1020

MAILING ADDRESS: P.O. BOX 6400 CYPRESS, CALIFORNIA 90630-0064

June 9, 1995

To:

All Mitsubishi Motors Dealers

From:

Dan Betian

Technical Information Manager

Subject: ASC Authorized Repair Facilities for 3000GT Spyder

Technical Service Bulletin TSB-95-42A-001 (issued April, 1995) contains a list of ASC authorized convertible repair facilities for the 3000GT Spyder convertible hardtop as of April 1, 1995. Since then, ASC has trained additional facilities. Therefore, an <u>updated</u> ASC authorized convertible repair facilities for the 3000GT Spyder is provided on the attached list. The attached updated list contains all ASC authorized convertible repair facilities for 3000GT Spyder as of June 1, 1995.

In the next few months, ASC plans to train additional facilities in 3000GT Spyder convertible hardtop repairs. We will send future updates of this list to you.

Regards.

Dan Betian

cc: MMSA TSB Distribution

Enclosure