



Name of Employee	EPC Trailer driver (Bab	A(I)   D		Г <u>а</u>			,
Name of Employee	EFC Italier driver (Bab	N N	adge o.	Contractor Driver		Actual Severity:	3
Safety Awareness Training Date	4-8-2020		roof of raining	Induction		Worst Potential Severity:	5
Name of Line Manager	Engr. Ahmed Fattah		adge o.		Profession/ Designation	Civil Engine	er
Name of Supervisor	Sohail		adge o.				
Division / Department	Civil Department		oject ame	097-C76R	Project JUC Location		
Place of the Incident/Injury	Auditorium, Part 1		ate of cident	4/29/2021	Time of Incident	08.10	-
Nature of the Incident/Injury	Occupational Incident/Injury			Near Miss	Other, Please specify:		
	Road Traffic Incident/ Injury	No		No			
Brief Description of the Incident/Injury  Details of the Injury (Specify affected	from the road side of trailer slightly tilted to unbalanced and it fell Fortunately no injury was completely dama	to the right s I down from th occurred as n	side that ne trailer.	made one of to	the precast page of the contract of the contra	anel on the r	ight side
body parts)							
First Aid Given?	No	Name of Fi	rst Aidei	-			
Name of Hospital where patient was treated/transferred	N/A			Address/Lo of the hospi			
Medical leave given by administering Hospital/Clinic or Doctor	No	Number of Days		Hospitalization		No	
Property damage	No	Estimated percentage of damage	100 %	Estimated Cost of damaged (SAR)			
Property Details	Type / Function of the property	Precast Wall panel		Location of affected property (		Completely da	maged
	Name of EPC Manufacturer						
	Model of the Property	N/A		Plate Number N,		/A	
	Vehicle Registration Number			Company Flo Number	eet	i/A	





Was Pre- Task / Toolbox meeting conducted			Yes	re Pi	as the person quired Person otective Equip PE)	al	Yes		
Specify the Personal P (PPE)	rotective Equipme	ent	Helmet, Sai	fety Shoes	Vest, Goggles				
What was the injured time of the incident?	person/employee	doin	g at the	N/A					
What was the machine the incident?	e/equipment doing	g at t	he time of	Trailer v	as transferring	Pre Cast wa	all panel into the	site	
What was the material/s / substance/s doing at the time of the incident				Precast wall panel was on the trailer					
Immediate Cause/s of	the Incident/injur	<b>y</b> :							
Due to jerk by crossing t	the uneven road, the	wall	l panel got un	balanced a	and fell from its	resting fran	me.		
	People: Lack of Supervision. No one to verify the correct tying of the precast panel.								
Root Cause/s of the Incident/injury:	<b>Process / Procedure:</b> Load was tied by the driver, who is not the competent person to tie the load. Chain was not tied safely as it got unlocked during the transfer.								
	Equipment: Trailer was ok.								
	<b>Workplace:</b> Workplace was not OK as the road was not levelled. Potholes and uneven surfaces were present on the road.								
	Elimination: N/A	1	V						
	Substitution: N/A								
Corrective Action to prevent reoccurrence:	ent trailers. The load must be tied with chain by a skilled person and additional belt must be tied							precast tied with rigging	
Were there any witnesses?	Yes		Type of witness/s	Employee			Public (Contractor)	<b>√</b>	
Witness Details EPC Trai	ler driver (Babar Ali)	<b>-</b>		Badge Number	Trailer driver	Mobile Number			





Witness Statement: As I was driving the trailer to the designated location, the trailer went over the unlevelled surface and I noticed the sound of precast falling. I immediately stopped the trailer.

Initial Investigation Conducted by: Wagas Cillan Noted by: Date 4/29/2021

## **Additional Details:**







Investigation Report Verified by:	Noted by:	Date	4/29/2021