

REZAYAT GROUP Health and Safety



Initial Incident/Accident Report

Fill the Information Below	N							
Company: Rezayat Company Limited						Date: 17-01-2021		
Location: Area 1					Time: 10:15 AM			
Project/ Site Name: Catering A	udit	orium & Recreation Facilities :	097	-C76R				
Person(s) Involved:	✓	Employee		Contractor		Others		
1. Kalaichelvan Jeyapalan (300	385	11)	3.					
2.			Oth	ner(s).				
Type of Incident:								
Fatality		Lost Time Injury	Ι	Dangerous Occurrence	T	First Aid	Т	
Injury Location by Body F	Parto	, , ,	ev):	Dangerous occurrence		1113(1110		
	ai ta		yj.					
Head		Chest		Hand		Eyes		
Face		Leg		Arm		Hip		
Neck		Abdomen		Wrist		Ankle/Foot		
Back		Stomach		Elbow		Knee		
Nose/ Ears		Shoulder		Fingers/ Thumb		Toes		
Type of Injury Sustained	(Sele	ct one or more if necessary):						
Fracture		Cut/ Laceration		Scalping	l.	Bruising	T-	
Loss of Sight		Loss of Consciousness		Heat		Amputation	-	
Dislocation		Crush Injury		Cold		Other(s) (Near miss)	1	
		Suffocation				other(s) (wear miss)	+	
Abrasion	_			Burn			_	
Immediate Cause(s) (Selec	t one	or more if necessary):						
Safety Rule Violated	✓	Lack of Resources		Drugs/ Alcohol Related		Inadequate Visibility		
Lack of Task Skill	✓	Method Deviation		Poor Housekeeping		Employee Morale		
Lack of Supervision	1	Poor Weather Conditions		Inadequate Lighting		Employee Attitude	1	
Improper Lifting (MH)		Lack of Task Knowledge	1	Poor Team Work	1	Behavior Problem	1	
Not Paying Attention		Lack of Communication		No Risk Assessment	Ť	Poor Ground Conditions	-	
Human Error	1	Incorrect Tools/Equip		Defective Equipment		Improper Lifting (crane)	-	
Inadequate PPE	<u> </u>	Defective Tools		Unprotected excavation		Unprotected Edge	-	
Animals		Violence		Horseplay		Improper/ Poor Slinging	-	
Heat Stress		STF Above Ground		STF on the Same Level			-	
Misuse of Hand Tools		Grinding/ Welding				Manual Handling Hit by Vehicle	-	
				Knives/ Sharps Splashes from C.P.O.L.		Other(s)	-	
Hit by Static Machinery Stress		Heavy Equipment		Vandalism		Other(s)	-	
		Fatigue		Vallualisiii				
Equipment(s) Involved:								
Light Vehicle:		Heavy Vehicle:		Plant Equipment:		Static Plant Equipment:		
Building:		Structure:		Scaffold:	✓	Excavation:		
Other(s):					1			
Description of the Event:								
•								
of chain block. The chain I While tightening one of the wheels slightly in the air. T and it was brought back to	olock pip he v	was tied with the mobile ses, the scaffolding raised for worker on the scaffold grab standing position by the wo	scaf from obed orke	folding to tighten the PVC pi the backside as a result of p the pipe support. Fortunate r on the ladder after loosenir	pe. pullir ly th	e scaffolding did not fell dow		
Immediate Action(s) Tak	en to	o Prevent Reoccurance (If	f Any	/) :				
Follow the approved methor Instructed them to use man	with od st oufac	the plumbing department a atement for the safe installa cturer made wall hooks to s	and t ation uppo	he near miss and its precaution of pipes.				
Person Created the Repor	rt:							
Name: Waqas Gillani		Position: Safety Engineer		Signature:	2	Date: 17/01/2021		

Note: This form is to be submitted four (4) hours after the incident occurred.



REZAYAT GROUP Health and Safety



Initial Incident/Accident Report







REZAYAT GROUP Health and Safety



Initial Incident/Accident Report

