

Incident and Injury Investigation Report



Name of Employee	Mr. Tahir Majeed			Bad	lge No.					Profess Design						
Safety Awareness Training Date	Jan-04-2020				100000000000000000000000000000000000000	Proof of Training		SAFETY ORIK		RIKI	NTAT	ITATION THAT		4		
Name of Line Manager	Mr. Joey C. Taguba				Bad	Badge No. 30040066										
Name of Supervisor	Mr. Muhammad Khan				Bad	Badge No. 30037034										
Division / Department	Maintenance / Construction (Civil)					Project Name		Façade Repairing Building #61		ng	Project Location		JHAH Dhahran		an	
Place of the Incident/Injury	Building # 61, Smoking area				Date of Incident		14.06.2022			Time of Incident		06:00 AM				
Nature of the	Occupational Incident/Injury				Yes	No			Near Miss Other,			Other,	Please specify:			
Incident/Injury	Road Traffic Incident/ Injury		Yes	No		Yes	~	No								
Brief Description of the Incident/Injury	roof the i	to the nstrucaffo	ne 2 nd action olding	floor fron mat	of the buns of the bun safety erial who cause d	uildir offic ich h	ng on the er not to as the p	e stor	ed so ow a tial 1	caffol ny to to cau	ding ols : ise !	g materi from he narm to	al ever ght. I the w	n after Hamm vorkers	receiv er slip s stand	ving ped ling
Details of the Injury (Specify affected body parts)	N/A															
First Aid Given?	Yes		No	-	Name of First Aider			N/A	1							
Name of Hospital where patient was treated/ transferred	N/A				maci				Address/Location N/A of the hospital			Λ				
Medical leave given by administering Hospital/Clinic or Doctor	Yes		No	-	Numbe Days	er of	N/A	Hospitalization				Yes		No	-	
Property damage	Yes		No	-	Estima percen of dam	ntage Estimated Cost of N/				N/A						
	Type / Function of the property				N/A			Location of affected property			N/A					
Property Details	Name of Manufacturer				N/A											
	Model of the Property				N/A	N/A			Plate Number				N/A			
	Vehicle Registration Number				N/A			Con	Company Fleet Number N/A							



Incident and Injury Investigation Report



Was Pre- Task / Toolbo	ox meeting		Yes	-	No	re Pr	as the person u quired Person otective Equip PE)	al	Yes	~	No			
Specify the Personal Protective Equipment (PPE) Safety glass							asses, helmet, glove, cover all, safety shoes, face mask							
What was the injured person/employee doing at the time of the incident?						N/A								
What was the machine/equipment doing at the time of the incident?							N/A							
What was the material/s / substance/s doing at the time of the incident							Scaffolding Material was stored there on the ground							
Immediate Cause/s of t	he Incident			ving t	he to	ol from h	eight							
Root Cause/s of the Inci	ident/injur	y:												
People: Poor Safety Beh	navior by th	e work	er											
Process / Procedure: Bucket with rope was not used														
Equipment: N/A														
Workplace: OK														
Corrective Action to pre	event reocc	urrence):											
Elimination:														
Substitution:														
Engineering Control: Bu	icket with i	ope to l	be use	d for l	oweri	ng tools fi	om height							
Administrative Control:	Disciplina	ry action	to be t	aken,	and co	ounseling h	as been done to	all worker	s on tl	he spo	t			
PPE:														
Were there any witnesses?	Yes	None		Type witn	of ess/s	Employee			Pu	ıblic				
Witness Details Mr. Muhammad Khan				Badge Numbe	r 30037034	Mobile Number	050	0 619	44 03					
Witness Statement:							•							
He borrowed the hammer							urned hammer l	oy throwing	g from	2 nd ro	of to first			

Initial Investigation Conducted by:	1 Mary	Noted by:		Date	
Adeel Khan (Safety Officer 30040391)	March				14.06.2022
			Yvu		



Incident and Injury Investigation Report



Additional Details:

For shifting material from height to ground, Bucket have to be used which will be lowered with rope. Similarly, when shifting the material from ground to height same procedure should be followed by the workers. Any type of material should not be thrown, it should be passed hand to hand or using rope bucket tools for shifting material. Ensure area is barricaded and make eye to eye contact with the colleagues and stop the unauthorized entry in area where work at height is in progress

Investigation Report Verified by:	Noted by:	Date	16.06. 2022
01			