

Incident and Injury Investigation Report



Name of Employee	Rahul Amin	Ba No	adge o.	30040554		Actual Severity:	3	
Safety Awareness Training Date	3/25/2019		roof of raining	Induction	nduction		Worst Potential Severity:	3
Name of Line Manager	Adham Alkhayat		adge o.	30037979	037979 Profession/ Designation		Project Manager Waleed Zaky	
Name of Supervisor	Waleed Zaghary		adge o.	30041023)41023			
Division / Department	HVAC		roject ame	C76R	Project Location		JUC	
Place of the Incident/Injury	Laydown 1		ate of cident	10/24/2021	0/24/2021 Time of Incident		10.00 am	
Nature of the Incident/Injury	Occupational Incident/Injury			Near Miss	Other, Please specify:			
	Road Traffic Incident/ Injury	No		Yes				
Brief Description of the Incident/Injury Details of the Injury (Specify affected	The employee recei of going to the properthe rod his hand sle	er machine	he deci	ded to use an ii				
body parts)	Nail is broken.							
First Aid Given?	Yes	Name of Fi	irst Aide	r				
Name of Hospital where patient was treated/transferred	Gulf Asia			Address/Lo of the hosp			city	
Medical leave given by administering Hospital/Clinic or Doctor	Yes	Number of Days		Hospitaliza	Hospitalization		No	
Property damage	No	Estimated percentage of damage	e	Estimated (Estimated Cost of damaged (SAR)		zero	
Property Details	Type / Function of the property	n/a		Location of property	Location of affected property		n/a	
	Name of Manufacturer	n/a						
	Model of the Property	n/a		Plate Number		n	n/a	
	Vehicle Registration Number	n/a		Company Fleet n Number			n/a	



Incident and Injury Investigation Report



Was Pre- Task / Toolbox meeting conducted			Yes		Was the person using required Personal Protective Equipment (PPE)		Yes	
Specify the Personal Protective Equipment (PPE)			Helmet, glas	lelmet, glasses & gloves.				
				Bending rod on table at workshop.				
incident?				Manual bender.				
What was the material/s / substance/s doing at the time of the incident				Steel thread rod.				
Immediate Cause/s of the His hand slept hit the tab								
	People: not using the proper equipment							
Root Cause/s of the Incident/injury:	Process / Procedure improper procedure for bending rod							
	Equipment: improper use of table clamp.							
	Workplace:c-76 fabrication workshop in laydown area-1							
	Elimination: Refresher training for workers not to use improper equipment.							
	Substitution: Provided alternative equipment for bending rod							
Corrective Action to prevent reoccurrence:	Engineering Control: Use designated bending machine to perform the activity.							
	Administrative Control: Tool box meeting and verbal warning to him.							
	PPE: leather gloves in workshop							
Were there any witnesses?	None		Type of witness/s	Emp	loyee		Public	
Witness Details -				Bada Num	_	Mobile Numbe	r	
Witness Statement:					L			



Incident and Injury Investigation Report



Initial Investigation Conducted by: Engr. Mahmoud Al Hassan Khalil



Noted by: Waleed Zaki

Date

10/25/2021

Additional Details:





Investigation Report Verified by:	Noted by:	Date	