

## **Incident and Injury Investigation Report**



Name of Employee	Mr. Ferdinand Mandasoc Naron					Badge No.						Profession/ Designation		Heavy Duty Driver			
Safety Awareness Training Date	09. 07. 2019					Proof of Training		RCL SAFETY ORIENTATIO				ON	aww.		*****		
Name of Line Manager	Mr. ESLAM ELSAYED ELARABY MOHAMED ALI MOUSTA				′	Badge No.		30039081									
Name of Supervisor	Mr. AYUB YUSUF BORKAR				Badge No.		31030670				, , , , , , , , , , , , , , , , , , ,						
Division / Department	Maintenance / Construction (Civil)					Name			SERVICES			Project Locat	ion	on DHAHRAN			
Place of the Incident/Injury	DHAHRAN ARAMCO INSIDE ROAD					Date of Incident		19.06.2022			Time Incide						
Nature of the	Occupational Incident/Injury				Yes		No		Near Miss			Other	Other, Please specify:				
Incident/Injury	Road Traffic Incident/Injury			Yes		No		Yes		No							
Brief Description of the Incident/ Injury	vehicle driver red sig second side of	e RTE was or mal at l our b bus tl	-1943, n duty Dhahi us wa hat tim	, Asho to br ran A s pass ne left	ok Ling I RAN sing t side	eylan back 2 MCO. throu e of ca	d bus 2nd sl Whe gh the ar hit	orted or s get acc hift man en green e green our bus nd headl	ident powe signa signa right	with or fro al tur l sud corr	n priven Dan Dan Dan Dan Dan Dan Dan Dan Dan Da	rate chahran, at the young the	ar insid in JHAI hat time car ove in in fro	e Dhahr H to Car e first or ertakes f	an AR mp, he ne vehi from ba	AMCO stoppe cle pas ack rig	Our don seed,
Details of the Injury (Specify affected body parts)									N/A	1		,					
First Aid Given?	Yes		No		1	Vame Nider	of Fi	rst	N/A							·	
Name of Hospital where patient was treated/ transferred	N/A							Address/Location N/A of the hospital									
Medical leave given by administering Hospital/Clinic or Doctor	Yes		No	N/A		lumb of Day		N/A	Hos	pita	lizati	ion		Yes		No	N/ A
Property damage	Yes		No		d p	istima l percei ge of lamag	nta	30%	Estimated Cost of damaged (SAR)			700	7000 SAR				
Property Details	, , ,					ASHO LEYL		Location of affected property			N/A						
	Name of Manufacturer A				Ashok Leyland			<b></b>									
	Model of the Property				_ 2	2012			Plate Number			VLA	VLA 7475				
	Vehicle Registration Number				7	VLA 7475			Company Fleet Number			RTE	RTE 1943				



## **Incident and Injury Investigation Report**

Was the person using



Was Pre- Task / Toolbo conducted	- Task / Toolbox meeting ed		Yes		No		uired Perso tective Equi E)		Yes		No	
Specify the Personal Protective Equipment (PPE)  Safety Shoes and uniform												
What was the injured p of the incident?	erson/emp	loyee d	loing at	time	Travelling back from project site to camp after duty finish							
What was the machine, the incident?	equipment/	of	Bus was bringing people back from project site to camp after duty finish									
What was the material, of the incident	/s / substan	me	N/A									
Immediate Cause/s of the Incident/injury:												
2 <sup>nd</sup> party car owner hit RCL Bus RTE 1943 on traffic light												
Root Cause/s of the Incident/injury:												
People: 2 <sup>nd</sup> party vehicle owner not followed traffic rules and overtakes on our bus which resulted this accident.												nt.
Process / Procedure: RCL Bus RTE 1943 was following the traffic signals properly.												
Equipment: BUS was als	Equipment: BUS was also okay for travelling											
Workplace: Road was also okay for driving vehicles on it												
Corrective Action to prevent reoccurrence:												
Elimination:	Elimination:											
Substitution:												
Engineering Control: Ensure all vehicle drivers follow the speed limits and traffic signals.  Administrative Control: Driver must to ensure to drive safe and keep safe distance from other vehicles on traffic signals. And wait for 2 seconds on signal when it turns green.  PPE:												
Were there any witnesses?	Yes	None		Type witn	of ess/s	Employe	e		Pub	lic		
Witness Details:		Badge Number N/A		Mobile Number	N/A							
Witness Statement: N/A												
Initial Investigation Con		Noted by:  Date 23.06.2022  MUHAMMAD AMJAD						2				



## **Incident and Injury Investigation Report**




## Additional Details & Recommendations:

- Always keep your eyes moving, constantly looking at your side and rear view mirrors, up, behind and to both sides of the vehicle.
- Maintain a visual of two to three car lengths in front of you.
- When changing lanes, physically turn your head to check your blind spot, followed by checking your side and rear view mirrors.
- Vehicle shall be drive on Aramco roads as per the allowed speed limits.
- Leave at least two car lengths between you and the car in front of you. During inclement weather, increase this to five car lengths.
- Stop prior to stop signs and then roll forward slightly to get a better look in each direction.
- Always use signal lights and be sure to signal ahead of time to communicate your intensions to other drivers.
- Avoid using a cell phone.
- Never try to overtake other vehicles on traffic signals.
- Keep watching others for overtaking on you on traffic signals.
- Only competent and authorized drivers shall drive vehicles.
- Driver must not take any medicine or drugs which make him dizzy or sleepy during driving.









Investigation Report Verified by:  MUHAMMAD AMJAD	Noted by:	Date	23.06.2022
---	-----------	------	------------

الامتية (١١/٤٠/٢٤) اليلاد ١١/٩٠/٢٧١ للهنة سالق شامنة الديانة غير ذنك KINGDOM OF SAUDI ARABIA MINISTRY OF INTERIOR تاریح الاصدار ۲۰۱۰،۸/۲۰ ISS 01/08/2010 SSI تاريح للبلاد ۱۳۹۷/۰۹/۱۷ DOB 11/09/1976 ارىخ الإنتهاء ١٤٤٦/٠٨/٦٠ وEXP 19/02/2025 الملكة العربية السعودية المطلكة العربية السعودية رخصية سياقة قزارة الباخلية يقلم FERDINAND - MANDASOC NARON فرديناند - مانداسوك نارون الرفم ١٢٠٥٥٩٠٦٠ النسخة VER CAT HEAVY TRANSPORT NAL PHILIPPINES KINGDOM OF SAUDI ARABIA MINISTRY OF INTERIOR

م الرقم . ۲۲، ۲۸۰۰ الرقم ، ۲۲، ۱۰۰۰ ۲۲ نسخه ۷ مكال الاصدار الخدمات الالكترونية

فرديناند - مانداسوك نارون

الجنسية القلبين

صاحب العمل شركة رضايلات التجارية المعدودة

RESIDENT IDENTITY FERDINAND - MANDASOC NARON

の発売がある。

るのできない

Norme: Ferdinand - Mandagoc Narron.

2285590630

B-G A+ B-G

2285590630

position # Heary vehicle Brief