

REZAYAT GROUP Health and Safety



alth & Safety Initial Incident/Accident Rep

mital incluent/Accident Report					
Fill the Information Below					
Company: Rezayat Company Limited				Date: 2021-02-11	
Location: Jubail (Near to Camp)				Time: 05:45 Am	
Project/ Site Name: Improvement of Schools				Worst Potential Severity: 4 Actual Severity: 1	
Person(s) Involved:	Employee		Contractor	Others	
1. Atiq ur Rehman (30036928)		3.			
2.		Otl	ner(s).		
Type of Incident:					
MTC					
Injury Location by Body Par	ts (Select one or more if neces	sary):			
Head	Chest		Hand	Eyes	
Face	Leg	-	Arm	Hip	
Neck	Abdomen		Wrist	Ankle/Foot	
Back	Stomach		Elbow	Knee	
Nose/ Ears	Shoulder		Fingers/ Thumb	Toes	
Type of Injury Sustained (Select one or more if necessary):					
Fracture	Cut/Laceration	A STATE OF THE STA	Scalping	Bruising	
Loss of Sight	Loss of Consciousness		Heat	Amputation	
Dislocation	Crush Injury		Cold	Other(s)	
Abrasion	Suffocation		Burn		
Immediate Cause(s) (Select one or more if necessary):					
Safety Rule Violated	Lack of Resources		Drugs/ Alcohol Related	Inadequate Visibility	
Lack of Task Skill	Method Deviation		Poor Housekeeping	Employee Morale	
Lack of Supervision	Poor Weather Conditions		Inadequate Lighting	Employee Attitude	
Improper Lifting (MH)	Lack of Task Knowledge		Poor Team Work	Behavior Problem	
Not Paying Attention	Lack of Communication		No Risk Assessment	Poor Ground Conditions	
Human Error	Incorrect Tools/Equip		Defective Equipment	Improper Lifting (crane)	
Inadequate PPE	Defective Tools		Unprotected excavation	Unprotected Edge	
Animals	Violence	_	Horseplay	Improper/Poor Slinging	+
Heat Stress	STF Above Ground		STF on the Same Level	Manual Handling	X
Misuse of Hand Tools Hit by Static Machinery	Grinding/ Welding Heavy Equipment	-	Knives/ Sharps Splashes from C.P.O.L.	Hit by Vehicle Other(s)	_ A
Stress	Fatigue		Vandalism	Other(s)	1
Equipment(s) Involved:			a contraction to we make a contraction		
				Continue Plant Francisco	48.003
Light Vehicle:	Heavy Vehicle:	X	Plant Equipment:	Static Plant Equipment:	+
Building:	Structure:		Scaffold:	Excavation:	+
Other(s): Description of the Event:	to the state of th	J. S. C.	Marine Commission of the Commi		
Our RTE 1885 registered bus carrying our project employees from the Jubail camp at 5:30 am. When the driver took a left turn from the signal, which is nearer to our camp, one of the public buses struck against our bus (Rear Side). As a result of this incident, our bus indicator and danger light fixtures were damaged but No Injury to our employees.					
Immediate Action(s) Taken to Prevent Reoccurance (If Any):					
The bus driver called the Transportation coordinator and notified the NAJM for further process. Another bus was deployed to carry our project employees to the site.					
Person Created the Report:					
Name:	Position:		Signature:	Date:	SAMAGE
Praveen Kumar Thirumurugan	Safety Manager – 628 C34		, france	11/02/2021	