

Incident and Injury Investigation Report



Name of Employee	Hussain Gindi Ramadar	ussain Gindi Ramadan Farag Badge No. 30040448			Actual Severity:	3			
Safety Awareness Training Date	2/14/2019		Proof of Induction Training		Worst Potential Severity:	3			
Name of Line Manager	Sherif Ismail Fahmi Moh	amed Ay	Badge No.	30104097	Profession/ Designation		Sr.Engineer Civil		
Name of Supervisor	Ehsan Ahmad		Badge No.	30038473					
Division / Department	Civil Department		Project Name	097-C76 R	Project Location	JUC	JUC		
Place of the Incident/Injury	Sports Centre		Date of Incident	3/8/2021	Time of Incident	02:05 PM	02:05 PM		
Nature of the Incident/Injury	Occupational Incident/Injury		No	Near Miss Other, Pleas		e specify :			
	Road Traffic Incident/Injury	I	No	Yes					
Brief Description of the Incident/Injury Details of the Injury	space frame struct plywood removed property damage Injury /Accident.	from th	e tie rod a	nd fell down fi	rom the sec	ond floor no			
(Specify affected body parts)	N/A								
First Aid Given?									
	No	Name o	of First Aide	er					
Name of Hospital where patient was treated/transferred	No N/A	Name	of First Aide	Address/L of the hosp					
where patient was		Numbe Days	er of	Address/Lo	ital	No			
where patient was treated/transferred Medical leave given by administering Hospital/Clinic or	N/A	Numbe	er of ted tage	Address/Lo	tion Cost of				
where patient was treated/transferred Medical leave given by administering Hospital/Clinic or Doctor	N/A No	Numbe Days Estima percen	er of ted tage	Address/Lof the hosp Hospitaliza	tion Cost of SAR)	No			
where patient was treated/transferred Medical leave given by administering Hospital/Clinic or Doctor Property damage	N/A No No Type / Function of	Number Days Estimate percent of dam	er of ted tage	Address/Lof the hosp Hospitaliza Estimated of damaged (S	tion Cost of SAR)	No N/A			
where patient was treated/transferred Medical leave given by administering Hospital/Clinic or Doctor	N/A No No Type / Function of the property Name of	Number Days Estima percen of dam N/A	er of ted tage	Address/Lof the hosp Hospitaliza Estimated of damaged (S	tion Cost of SAR) affected	No N/A			



Incident and Injury Investigation Report



Was Pre- Task / Toolbox meeting conducted		Yes		Was the perequired Protective (PPE)	ersonal	Ye	es		
Specify the Personal Protective Equipment (PPE)			Helmet, saf	safety shoes, vest, gloves and goggles					
What was the injured p of the incident?	erson/employee do	ing at	the time	N/A					
What was the machine/equipment doing at the time of the incident?			NA						
What was the material, the incident		ng at t	he time of	Shutte	ering of Colur	nn work			
Immediate Cause/s of to During shuttering of col-		ood wa	s not secure	d prope	erly.				
	Paopla Worker n	ot naid	l attention v	while f	iving chutto	ing of solven			
Root Cause/s of the Incident/injury:	People: Worker not paid attention while fixing shuttering of column. Process / Procedure: Shuttering plywood was not secured properly.								
	Equipment: N/A								
	Workplace: Safe platform was not provided for the shuttering work. Downside work area was not barricaded properly.								
	Elimination: N/A								
Corrective Action to prevent reoccurrence:	Substitution: N/A								
	Engineering Control: Ensure to provide safe platform for shuttering works with columns. Ensure the plywood using for shuttering works must be secured properly.								
	Administrative Control: Ensure trained and competent people only perform shuttering work. Ensure proper supervision for the work. Ensure downside area properly barricaded all time during shuttering of column works.								
	PPE: Ensure to use all required ppe, s during shuttering of column works.								
Were there any witnesses?	None		Type of witness/s	Emp	loyee		Public		
Witness Details -				Badg Num		Mobile Number			



Incident and Injury Investigation Report



Witness Statement:


Initial Investigation Conducted by: Krishna Pillai

Noted by:

Date

3/8/2021

Additional Details:





Investigation Report Verified by:

Noted by:

Date 3/8/2021