Ref

RCL-HSE-FM-07 1

Version: 1.2

Rev Date. June 28, 2021

INITIAL ACCIDENT AND INCIDENT NOTIFICATION REPORT



Fill the Information Below	W				
Company: RCL		1		Date: 07/08/2022	
Company: RCL Location: Prime Abdul Majerd Stut Project/ Site Name: Coursion Refrair				Time: 10:30 Am	
Project Sim Name: Carriston Refrair				Worst Potential Severity: 6-3	
				Actual Severity: 01	
Person(s) Involved:	_	Employee	Contractor	Others	
1. Somi' Kumar			3.		
1. Somi' Kumar 2. Jais Alam			Other(s).		
Type of Incident:					
Ill-Health Deputy	dor	nage			
Injury Location by Body	Parts	(Select one or more if necessa	ry):		
Head		Chest	Hand	Eyes	
Face	_	Leg	Arm	Нір	
Neck		Abdomen	Wrist	Ankle/Foot	
Back	_	Stomach	Elbow	Knee	
Nose/Ears		Shoulder	Fingers/ Thumb	Toes	
Type of Injury Sustained	(Scle	ct one or more if necessary):			
Fracture	\perp	Cut/ Laceration	Scalping	Bruising	
Loss of Sight	+	Loss of Consciousness	Heat	Amputation	
Dislocation Abrasion	+	Crush Injury Suffocation	Cold Burn	Other(s)	
Immediate Cause(s) (Sele	at an		Burn		
	ct one				
Safety Rule Violated	+	Lack of Resources	Drugs/ Alcohol Related	Inadequate Visibility	
Lack of Task Skill Lack of Supervision	+	Method Deviation Poor Weather Conditions	Poor Housekeeping Inadequate Lighting	Employee Morale Employee Attitude	
Improper Lifting (MH)	+-	Lack of Task Knowledge	Poor Team Work	Behavior Problem	
Not Paying Attention	+	Lack of Communication	No Risk Assessment	Poor Ground Conditions	
Human Error	174	Incorrect Tools/Equip	Defective Equipment	Improper Lifting (crane)	
Inadequate PPE		Defective Tools	Unprotected excavation	Unprotected Edge	
Animals	\bot	Violence	Horseplay	Improper/ Poor Slinging	
Heat Stress	+	STF Above Ground	STF on the Same Level	Manual Handling	
Misuse of Hand Tools Hit by Static Machinery	+	Grinding/ Welding Heavy Equipment	Knives/ Sharps Splashes from C.P.O.L.	Hit by Vehicle Other(s):	
Stress	+	Fatigue	Vandalism	other(s):	
Equipment(s) Involved:		raagae	, and an		
	-	Harry Waltala	Plant Parisment	Add Chair Dlank Paris	
Light Vehicle:	+	Heavy Vehicle:	Plant Equipment: Scaffold:	Static Plant Equipment	
Building: Other(s):	+-	Structure:	Scanoia:	Excavation:	
Around 10:30 to	wm; Ro	while Concule of with dyna and and got don	suddenly Concrete nage	mixing Machine	
Immediate Action(s) Taken to Prevent Reoccurrence (If Any):					
* immediale Report to project manager					
A immediate concrete mire machine send to auto workshop for Repair					
Person Created the Repo	rt:	n 11 = 14:			
Name: Asharudom		Position: .f/E office.	Signature: Ala-OS	Date: 2000-07-09 8/8/2012	

Note: This form is to be submitted four (4) hours after the incident occurred.

Scanne Revision Dated: 22 July 2021
MOBILE SCANNER