

REZAYAT GROUP Health and Safety



Initial Incident/Accident Report

Cillaboration Bolo		incluei	it/Accident Report			
Fill the Information Below	N					
Company: Rezayat Company	Limited			Dat	te: 2/15/2021	
Location: Auditorium Part 2,				Tin	ne: 02:30 PM	
Project/ Site Name: Catering A	auditorium & Recreation Facilitie	s : 097 -	-C76R		orst Potential Severity: 2 ual Severity: 3	
Person(s) Involved:	✓ Employee		Contractor		Others	
1. Subash Giri (30038234)		3.				
1. Subasii Giri (50056254)		3.				
2.Mustafa Alshakhoori (3004	.0959)	Otl	her(s).			
Type of Incident:						
Near Miss						
	Parts (Select one or more if necess	carv):				
		sary j.				
Head	Chest		Hand		Eyes	
Face Neck	Leg Abdomen		Arm		Hip	_
Neck Back	Stomach	-	Wrist Elbow		Ankle/Foot Knee	_
Nose/ Ears	Shoulder		Fingers/ Thumb		Toes	_
	(Select one or more if necessary):		Tingers/ Thumb		1003	
Fracture	Cut/ Laceration		Scalping		Bruising	
Loss of Sight	Loss of Consciousness		Heat		Amputation	
Dislocation	Crush Injury		Cold		Other	
Abrasion	Suffocation		Burn			
Immediate Cause(s) (Selec	t one or more if necessary):					
Safety Rule Violated	✓ Lack of Resources		Drugs/ Alcohol Related		Inadequate Visibility	
Lack of Task Skill	Method Deviation		Poor Housekeeping		Employee Morale	
Lack of Supervision	Poor Weather Conditions		Inadequate Lighting		Employee Attitude	
Improper Lifting (MH)	Lack of Task Knowledge		Poor Team Work		Behavior Problem	
Not Paying Attention	Lack of Communication		No Risk Assessment		Poor Ground Conditions	
Human Error	✓ Incorrect Tools/Equip		Defective Equipment		Improper Lifting (crane)	
Inadequate PPE	Defective Tools		Unprotected excavation		Unprotected Edge	
Animals	Violence		Horseplay		Improper/ Poor Slinging	
Heat Stress	STF Above Ground		STF on the Same Level		Manual Handling	
Misuse of Hand Tools	Grinding/ Welding		Knives/ Sharps		Hit by Vehicle	_
Hit by Static Machinery	Heavy Equipment		Splashes from C.P.O.L. Vandalism		Other(s):	_
Stress	Fatigue		vanualism			
Equipment(s) Involved:						
Light Vehicle:	Heavy Vehicle:		Plant Equipment:		Static Plant Equipment:	
Building:	Structure:		Scaffold:	✓	Excavation:	
Other(s):						
Description of the Event:						
	orking Around 15 meter heig the hammer slipped from hinere.					j
Immediate Action(s) Tak	en to Prevent Reoccurrence	(If An	y):			
		<u> </u>	·			
 Always tie the haways at height 	ımmer with hand while					
Davida I. (La sa)						

- Barricade the area from downside.
- Always depute one person downside to monitor pedestrian access.

Person Created the Report:

Name: Mohammed Azharuddin Position: Safety Officer Signature: V Know Date: 2/15/2021

Note: This form is to be submitted four (4) hours after the incident occurred.



REZAYAT GROUP Health and Safety



Initial Incident/Accident Report

