

Incident and Injury Investigation Report



Name of Employee	Mohamed Abdalate Al Mo	bdelhalem	Badge No.	30040373		Actual Severity:	3
Safety Awareness Training Date	9/8/2019		Proof of Training	Induction		Worst Potential Severity:	3
Name of Line Manager	Ahmed Mohamed Elha Abdelmage	ady	Badge No.	30036668	Profession/ Designation	Eng. III - Civi	Const.
Name of Supervisor	Osama Eid Mohamed Badge 30036338 Kheriba No.						
Division / Department	Civil Department		Project Name	Catering Auditorium & Recreation Facilities	Project Location	JUC	
Place of the Incident/Injury	Sport center		Date of Incident	12/23/2020	Time of Incident	4.50PM	
Nature of the Incident/Injury	Occupational Incident/Injury	N	lo	Near Miss	Other, Please specify :		
	Road Traffic Incident/Injury At around 4.50pmN	_	lo	Yes			
Brief Description of the Incident/Injury	under the supervision. While doing the end it damage cable from the main utility clearance cereport.	xcavation e. Electric n distribu	by the excal enginee tion panel	cavator connect r and his team r . All document	ted to tempore the tempore to the te	orary electrication and disconne to dig, Electrication	l lilting cted the ical and
Property damage							
First Aid Given?	No	Name o	f First Aide				
Name of Hospital where patient was treated/transferred				Address/Lo of the hospi			
Medical leave given by administering Hospital/Clinic or Doctor	No	Number Days	rof	Hospitalizat	ion	No	
Property damage	No	Estimated percentage of damage		Estimated Cost of damaged (SAR)			
	Type / Function of	Location of affected property		iffected			
	the property		····	property			
				property		-	
Property Details	the property Name of			Plate Number	er		



Incident and Injury Investigation Report



Was Pre- Task / Toolbox meeting conducted		Yes	Was the per required Pe Protective E (PPE)	rsonal	Choose an item.		
Specify the Personal Pro	otective Equipment						
What was the injured po	erson/employee do	ing at the time					
What was the machine/incident?	equipment doing a	t the time of the					
What was the material/	s / substance/s doi	ng at the time of					
Immediate Cause/s of the							
Lack of Supervision							
Lack of Communica Method Deviation	tion						
Method Deviation							
	December 1						
	People: Excavator	operator was con	ipetent				
Root Cause/s of the	Process / Procedure- Not done the cable detection property and fail to identify the present cable						
Incident/injury:	Equipment: Equipment Was ok						
	Workplace: Work place not 0k for excavation as there were underground electrical cable						
	Elimination: N/A						
Corrective Action to prevent reoccurrence:	Substitution: N/A						
	·						
	Engineering Control: Any temporary cable laid underground should be notified to civil						
	department and should be noted by electrical department						
	Administrative Control: Should be provide proper training and inspection the proper procedure and policy also improve the quality of supervision						
	PPE: Use all site n	ecessary PEE's					
Were there any witnesses?	None	Type of witness/s	Employee		Public		
Witness Details	I	111111111	Badge	Mobile			
			Number	Number			
				<u> </u>	1		




Incident and Injury Investigation Report



Initial Investigation Conducted by: Krishna Pillai	Noted by: Mustafa Ali	Date	
1. Eust			10/2/21

Additional Details:





Investigation Report Verified by:	Noted by		
investigation Report verified by.	Noted by:	1 1	
		Date	