

REZAYAT GROUP Health and Safety



Initial Incident/Accident Report

Comment of the control of the contro				THE PARTY OF THE P				
Company: Rezayat Company Limited Location: Al Faiha						Date: 8/10/2022 Time: 10:00 Am		
Project/ Site Name: Sabic N	Mainten	ance - Vacant House				rual Severity: 2		
Person(s) Involved:	X	Employee		Contractor		Others		
1. Rifat Khan (30041205)			3.					
2.			Ot	her(s).				
			Ot	ner(s).				
Type of Incident:								
First Aid Case						The Mark Control of the Control		
Injury Location by Bod	y Part	S (Select one or more if necessa	ту):			and the second second	_	
Head		Chest		Hand		Eyes	+	
Face		Leg	X	Arm		Hip	+	
Neck		Abdomen		Wrist		Ankle/Foot	+	
Back		Stomach		Elbow		Knee	+	
Nose/ Ears		Shoulder		Fingers/Thumb		Toes	L	
Type of Injury Sustaine	ed (Sele	ect one or more if necessary):	SUSPI	THE PERSON NAMED IN COLUMN				
Fracture		THE RESERVE THE PERSON NAMED IN	X	Scalping		Bruising		
Loss of Sight		Cut/ Laceration Loss of Consciousness	A	Heat		Amputation	Г	
Dislocation	_		-	Cold	10	Other(s)	Г	
Abrasion	_	Crush Injury	-	Burn	1			
	Water Street	Suffocation	-	Buth				
Immediate Cause(s) (so	elect one	e or more if necessary):	-	THE UNITED IN A STATE		to to one the little	T	
Safety Rule Violated		Lack of Resources		Drugs/ Alcohol Related		Inadequate Visibility	+	
Lack of Task Skill		Method Deviation		Poor Housekeeping		Employee Morale	+	
Lack of Supervision		Poor Weather Conditions		Inadequate Lighting		Employee Attitude	+	
Improper Lifting (MH)		Lack of Task Knowledge		Poor Team Work		Behavior Problem	+	
Not Paying Attention	X	Lack of Communication		No Risk Assessment		Poor Ground Conditions	+	
Human Error		Incorrect Tools/Equip		Defective Equipment		Improper Lifting (crane)	+	
Inadequate PPE		Defective Tools	TO	Unprotected excavation		Unprotected Edge	+	
Animals		Violence		Horseplay		Improper/ Poor Slinging	+	
Heat Stress		STF Above Ground	1	STF on the Same Level		Manual Handling	\vdash	
Misuse of Hand Tools		Grinding/ Welding		Knives/ Sharps		Hit by Vehicle	+	
Hit by Static Machinery		Heavy Equipment		Splashes from C.P.O.L.		Other(s):	+	
Stress		Fatigue		Vandalism			_	
Equipment(s) Involved	:							
Section of the sectio		Heavy Vehicle:		Plant Equipment:		Static Plant Equipment:		
Light Vehicle:				Scaffold:		Excavation:		
Building:		Structure:		Cultoru				
Other(s):			_	y I had the little of the same		Talente property of the same		
Description of the Even						William William Control of the Contr		
the Mirror from his righ	t to his	all tiles at a vacant house. s left side by manual lifting of this incident, a minor o	g. A 9	sharp edge of the mirror	made a	on the floor, he try to reloc contact with his right while	att	
		o Prevent Reoccurrence (
He was taken to the C76	clinic	for first aid and first aid wa	is giv	en at the C76R project.				
Person Created the Rep	ort:				TO BY			
Name: Praveen Kumar		Position: SAFETY ENGINEER		Signature:		Date: 8/10/2022		
Thirumurugan		POSITION: SAFETT ENGINEER	•	Signature:		Dute. Of 20 factor		