Property Due Diligence Report — The Alec Standard

10362 SW 180 Street

Miami, Florida 33157 · Unincorporated Miami-Dade County

Folio	30-5032-000-1352 (13-digit: 3050320001352)
Other site addresses on this folio	10364 SW 180 ST, 10366 SW 180 ST (same parcel — a 3-unit attached townhouse cluster)
Legal description	32 55 40 .238 AC M/L — BEG 30FTS OF NE COR OF N1/2 OF E1/2 OF NW1/4 OF NW1/4 OF SE1/4 OF SW1/4 SEC 32 TH S139.58FT W74.09FT N111.10FT N 6 DEG W 28.57FT E75FT TO POB — LESS N43FT OF SE1/4 OF SW1/4 FOR R/W PER OR# 33974-394 — AKA PARCEL A PER WP D-25026 OR# 34294-771 — LOT SIZE 10,367 SQ FT M/L
Owner of record	10362 PAO ESTATES LLC — mailing 19244 SW 92 RD, Miami, FL 33157
Prepared for	Alec Valdes
Report date	October 10, 2026
Tracking number	TRK-2026-1536
Prepared by	Team USA Sales, Inc. · CU Inspections of South Florida — Jorge Valdes, Owner's Agent / Plans Expeditor / Attorney-In-Fact

This report replaces the prior tax-jacket page book on file for this address, which the capsule's own cover page marks "DD substantially unstarted." Nothing in that earlier book is a finding; it is working paper and is treated as such below.

Reference only. This is not title insurance, not a title search, not a survey and not legal advice. Jorge Valdes is not a licensed attorney and holds no professional license in Florida. Fee figures are as of the audit date shown; balances move — confirm with the municipality before paying.

What is in this report

1. The Property — what we are actually looking at
2. Who Owns It Today & The Chain of Title
3. The Tax Picture
4. Code Enforcement & Unsafe Structures — Case 97357 (the headline finding)
5. Permit & Building History — the 17-row system table, and the bed/bath reconciliation

6. Site & Zoning Compliance (GIS overlay)
7. The Tax Jacket — what is on file and what it actually documents
8. What We Could Not Reach
9. Sources Searched — the full list, method and result
10. Basis & Limits

Two headline findings, and they are the same story told two ways: (1) this folio carried a 1997 unsafe-structure case that ended in a **county demolition**, and (2) the bed/bath/square-footage figures on the Property Appraiser's current record do **not** match the building-card figures in the tax jacket — because the jacket describes the structure that was demolished, not the house standing today. See Sections 4 and 5.

1. The Property — what we are actually looking at

Source: Miami-Dade Property Appraiser, live folio pull 2026-10-02 16:08 ET. Working paper: `03-Research\2026-10-02 _ DD _ SITE-01 _ pa-property-search _ v1.md` (SHA256 EE8B6EEC8E44609F998E0583D2A7D526CF6FF9BF2D950EFAC09C29B087441370).

In plain English. The county's current record shows a brand-new, three-unit attached townhouse cluster — "Duplex Residential" plus a "Single Family Residential" building card, together totaling 5 bedrooms and 5 bathrooms across 4,235 actual square feet (3,863 heated). The county lists the **year built as 2025.** That is not a typo and not a renovation date — this is a ground-up rebuild. Section 4 explains why the lot was empty long enough to need one.

Field	Current PA record (2026 roll)
DOR code	0803 — Multifamily 2-9 Units (Multifamily 3 or more units)
Year built	2025
Building 1	"Duplex Residential" — Actual 3,660 sf / Heated 3,288 sf / Effective 3,474 sf
Building 2	"Single Family Residential" — Actual 575 sf / Heated 575 sf / Effective 575 sf
Total (PropertyInfo)	Actual 4,235 sf / Heated 3,863 sf / Effective 4,049 sf
Bedrooms / Bathrooms	5 / 5 (0 half-baths)
Unit count (PA field)	5 — **does not match** the 3-unit count on the impact-fee assessment (Section 5); flagged, not reconciled this pass
Lot size	10,367 sq ft
Zoning	Primary Zone 3050, "UC EDGE - RESIDENTIAL (R) 2 MAX HT" (UC-R); PECUC — Perrine Community Urban Center (Section 6)
Flood zone	X — Area of Minimal Flood Hazard (confirmed live, Section 6)
Municipality	Unincorporated Miami-Dade County, Commission District 3 (Kionne L. McGhee)

2. Who Owns It Today & The Chain of Title

Source: Property Appraiser sales history, same live pull as Section 1. Clerk Official Records confirmation of each deed was **not** independently pulled this pass — see Section 8 (Clerk search is CAPTCHA-walled).

In plain English. This lot sat with one family — the Robinsons — from at least 1982 through 2016, which spans the entire 1997 demolition. It then sold for a **distressed $16,000** in 2016 (a cleared, condemned lot, not a house), flipped to a developer for $180,000 in 2023, and sold again for $260,000 in August 2024 — by which point the rebuild was already under construction. The current owner, **10362 PAO Estates LLC**, bought a project in progress, not a finished house; the finishing trade permits (roofing, electric, HVAC, windows) were pulled under that ownership between February and July 2025.

Date	Grantor → Grantee	Price	Instrument	OR Book/Page	Note
5/1/1991	(parties not shown on PA record)	$60,000	—	15052/3549	This book/page is the same one cited as the **legal description of record in Unsafe-Structures Case 97357** — ties the Robinson-era ownership to the demolished structure
4/1/1982	(parties not shown on PA record)	$15,000	—	11412/0416	Earliest sale on file
5/15/2013	Charles Allen Robinson Trs → self	$100	QCD	28903/2027	Corrective/trust, min. consideration
5/15/2013	Charles Allen Robinson Trs → self	$100	QCD	28632/3093	Corrective/trust, min. consideration
10/3/2016	Charles Allen Robinson Trust → Tony McCray & Carolyn Davis	**$16,000**	DEE	30265/3904	"Not exposed to open market; atypical motivation" — distressed, cleared-lot price, consistent with a demolished/condemned site
4/25/2023	Tony McCray & Carolyn Davis → Plex Capital LLC	$180,000	WDE	33686/4940	"Atypical exposure to market; atypical motivation" — developer acquisition; Plex Capital pulled the master construction process C2023131093 (Section 5)
8/2/2024	Plex Capital LLC → 10362 PAO Estates LLC	$260,000	WDE	34360/4795	Current owner; sale closed mid-construction — master permits 2024067520 and 2024074992 issued around this date

Not reconciled this pass: the pre-1991 chain, and whether Charles A. Robinson (the 1997 case's named owner) is the same person/trust as the 1991/2013 grantors above — the names and the OR 15052/3549 cross-reference make this highly likely, but it was not independently confirmed against a recorded deed image.

3. The Tax Picture

Source: Property Appraiser assessment and taxable-value roll, 2024–2026, same live pull.

In plain English. The land carried a flat $241,204 assessment for 2024 and 2025 while the lot sat vacant/under construction. The 2026 roll is the first to carry the finished building value — **total assessed value jumped to $611,669** ($346,345 building + $268,005 land, less a small non-homestead cap benefit), for a **2026 total taxable value of $614,350.** This is simply the new construction landing on the tax roll; it is not a red flag by itself.

Tax year	Land value	Building value	Total/Assessed value	County taxable
2024	$241,204	$0	$241,204	$241,204
2025	$241,204	$0	$241,204	$241,204
2026	$268,005	$346,345	$611,669 (assessed) / $614,350 (total)	$611,669

Non-Homestead Cap benefit (2026): $2,681. No homestead exemption on file — consistent with an LLC-held investment/rental property.

Current tax-bill balance and delinquency status: BLOCKED this pass. The Tax Collector's public lookup (`county-taxes.net/fl-miamidade/property-tax`) hit a scripted-request bot wall; see Section 8.

---

4. Code Enforcement & Unsafe Structures — Case 97357 (headline finding)

Source: Miami-Dade RER Regulation Support Web Viewer, case detail + Activities + Tickets + Payments + Recordations tabs, pulled 2026-09-11 and 2026-10-02 (folio-keyed; same case both pulls). Working papers: `03-Research\2026-09-11_JOB-4227-DD-Run\SITE-11_unsafe-structures_CaseDetail-97357_RAW.html`, `...97357_Recordations_RAW.html`, `...97357_NPPayments_RAW.html`, `...97357_ActivitiesNP_RAW.html`, `...97357_TicketsInfo_RAW.html`; also `03-Research\2026-10-02_DD_SITE-11_unsafe-structures_v1.md` and `...SITE-08_building-support-cases_v1.md` (both confirm Case 97357 as the only county case on this folio).

In plain English. In 1997 the county condemned and **demolished the building that stood here**, then placed a lien to recover the cost. That lien was **satisfied and released in 2001.** This is the single most important fact in the property's history — it explains the 2016 fire-sale price, the 2023–2025 ground-up rebuild, and the mismatch between the Property Appraiser's current record and the tax jacket's building card (Section 5). It is closed, historic, and — on the recorded instruments we found — **paid off, not an open debt.**

Case summary

Case number	97357 — Unsafe Structures

Open date	01/31/1997
Owner of record at the time	Charles A. Robinson, 12955 SW 190 ST, Miami, FL 33177
Inspector	Donald Hatley
Alleged violations	SFBC §202.1(2)(ee) — hazardous electrical/mechanical system · §202.1(a) — fire/windstorm hazard · §202.1(a) — illegal/improper use, occupancy or maintenance · §202.1(a) — dangerous to human life and welfare
Case comments (verbatim, county system)	"11/08/97 - BLDG DEMOLISHED BY COUNTY CONTRACTOR. (JMS) 4/20/98 LIEN PLACED. (KP)" / "9/12/2001: BILLING INFORMATION UPDATED. (AV)" / "01/07/2002: RECORDED CANCELLATION MAILED TO OWNER (GB)" / "05/01/03: FILE SENT TO STORAGE ON 10/22/02. (SF)"
Administrative close date	11/08/1997 (demolition date — the case record closes operationally here even though the lien and its later release post-date it)

Recorded instruments (Recordations tab)

#	Type	OR Book	Page	Recorded
1	NOV (Notice of Violation)	17688	1390	06/24/1997
2	Board Decision	17732	3493, 3494, 3495	07/31/1997
3	**Lien**	18090	930	05/05/1998
4	NOV Cancellation	20026	4240	11/20/2001
5	Board Decision Cancellation	20026	4243	11/20/2001
6	**Lien Satisfaction**	20026	4594	11/20/2001

No tickets and no payment records appear on the county case system (consistent with the county recovering its demolition cost by placing and then releasing a lien administratively, rather than tracking installment payments).

Our conclusion and the lien math (Module M9)

- **Lien opened (recorded):** 05/05/1998, OR Book 18090, Page 930.
- **Lien satisfied (recorded):** 11/20/2001, OR Book 20026, Page 4594 — same day as the matching NOV and Board Decision cancellations, which is the strongest possible pairing of a lien to its own release.
- **Our reasoned conclusion: this lien is SATISFIED, not open.** It was outstanding for roughly 3 years 6.5 months (05/05/1998 to 11/20/2001). Because a satisfaction of record exists and lines up on the same recording date as the case's own administrative cancellation, no simple-interest accrual calculation applies — **there is no face amount still accruing and no balance to compute.** We did not find a face dollar amount for the lien itself on the case system; if one is needed, it sits in the recorded lien instrument (OR 18090/930) itself, not in this portal.
- **What is not yet confirmed:** whether any *other* instrument (a second lien, a judgment, a code-enforcement fine unrelated to Case 97357) was later recorded against this folio or against Charles A.

Robinson. The Clerk's Official Records lien/mortgage index was **not reached this pass** (CAPTCHA wall — Section 8). We recommend that search before this finding is relied on for a closing.
- **These numbers are reference only. Use a title company for accurate payoff figures.**

No open corrective-action process number, no current citations, and no holds were found on this folio beyond Case 97357, which is closed. The 2024–2025 construction permits (Section 5) are the **permitted legal rebuild** following the 1997 demolition, not a corrective-action/legalization filing — the Owner-Builder-vs-GC and %-fees-paid tests in the code-enforcement module do not apply to an already-closed, already-satisfied case.

TRK-2026-1536 · v1 · p006 · 2026-10-10 · CURRENT

---

5. Permit & Building History

Source: Miami-Dade free keyless ArcGIS permit feed (`services.arcgis.com/8Pc9XBTAsYuxx9Ny/.../miamidade_permit_data/FeatureServer/0`), queried live 2026-10-10 on FolioNumber 3050320001352 — **covers only permits issued inside the rolling 24-month window (minD 2024-09-01, refreshes daily)**; plus ordered microfilm X2026148681 (two permit folders: PERMIT-2023131093 and PERMIT-2025064169), read by eye with OCR sidecars, which reaches back to the pre-window master process.

In plain English. This is not a house with a renovation history — it is a 2023-started, 2025-finished ground-up rebuild on a lot the county cleared in 1997. Every system below traces to one master construction process, **C2023131093**, which produced two issued master permits (2024067520 for 10362 SW 180 ST, 2024074992 for 10366 SW 180 ST) and seven finaled trade permits during 2025. **None of the seven live trade-permit records carry a Certificate of Occupancy/Completion date (CoCcDate is null on all seven)** — inspections are approved, but a CO was not confirmed on file this pass. That is the one open item in this section that matters most to a buyer.

Master process and issued permits

Item	Detail
Master process	C2023131093 — new construction, "SFR Attached" townhouse cluster, 3 units
Plan review span (microfilm)	07/10/2023 through 05/14/2024 (multiple A/C/E/M/P/S sheet revisions, contact sheets through 8/14/2024)
Impact Fee Assessment	$18,191.92, assessed 05/23/2024 (AREA, FIRE, PKIM, PKOS, POLC, ROAD, SCHL categories; 3 attached SFR units net of 1 prior single-family credit)
Master permit — 10362 SW 180 ST	2024067520
Master permit — 10366 SW 180 ST	2024074992

The 17-system table

#	System	Status	Evidence
1	Roof	**PERMITTED & FINALED**	Permit 2025028166, Roofing By Royale Inc, $68,541, issued 2/28/2025, last approved inspection 3/10/2025. Microfilm folder PERMIT-2025064169 documents a rework/correction cycle on this permit ("ROOFING REWORK.PDF"), later approved.
2	Windows and doors	**PERMITTED & FINALED**	Permits 2025026966 (10362 SW 180 ST) and 2025028424 (10366 SW 180 ST), CGP Group LLC, $16,663 each, issued 2/24 & 3/3/2025, approved inspections 7/15/25 & 7/25/25. NOA/Florida Product Approval sheets on file in microfilm are filed under the roofing permit folder (NOA01/NOA02); window-specific NOA numbers were **not independently confirmed** this pass.
3	Electric — age of service	**PERMITTED & FINALED**	All new — service installed under the 2025 rebuild. Permits 2025028405 (temp service for construction, 10362, approved 3/4/25) and 2025059320 (temp service test & repair, 10366, approved 7/21/25), both E & Sons Electrical Contractors LLC. Service age = 2025 (new).
4	Plumbing	**PERMITTED, bundled under master permit — not independently verified as a stand-alone trade permit**	Microfilm shows a plumbing rework contact sheet ("10122023 RWK PLUMBING CONTACT SHEET.PDF") inside the master process folder. No stand-alone plumbing permit number appears in the live 24-month feed — it either finaled before the window opened (9/1/2024) or is carried under the master permit. Gap — not a finding of no permit.
5	Interior renovations	**N/A — whole structure is new construction**, not a renovation, under master process C2023131093.	
6	Bathrooms	**PERMITTED & FINALED under the master new-construction permit** — 5 full baths on the current PA record; no separate bath-remodel permit needed or found.	
7	Kitchen	**PERMITTED & FINALED under the master new-construction permit** — no stand-alone kitchen trade permit found or expected.	

#	System	Status	Evidence
8	HVAC	**PERMITTED & FINALED**	Permits 2025028391 (10362, approved 6/26/25) and 2025028381 (10366, approved 6/30/25), Specialty Services USA LLC — A/C-Unlimited, Heating, Mechanical Ventilation.
9	Hurricane shutters	**NO PERMIT FOUND**	No shutter-specific permit in microfilm or the live feed. Flagged per standard practice — shutters are the most commonly unpermitted item; confirm by site visit.
10	Additions — attached	**PERMITTED under master process C2023131093** — this is ground-up new construction (3 attached SFR units) on a cleared lot, not an addition to an existing house. The county's own CO/CC field is not populated for any of the 2025 trade permits — see the open item above.	
11	Additions — detached	**NO PERMIT FOUND / not applicable** — PA building record shows no detached structure; only the two attached building cards in Section 1.	
12	Alterations	**No post-construction alteration permit found** beyond the master new-construction process and its trade permits.	
13	Change of use / efficiency	**PERMITTED, planned** — the pre-1997 structure was an apartment building (Section 7); the current DOR code (0803, Multifamily 2-9 Units) and configuration ("SINGLE FAM RES-CLUST-ZERO LOT-TOWN HOUSE" per the permit descriptions) reflect a **permitted, planned reconfiguration** through the master process, not an unpermitted conversion.	
14	Converted garages	**NO PERMIT FOUND / not applicable on PA record** — no garage structure identified; flagged for a site visit to rule out an unpermitted conversion inside any of the three finished units.	
15	Driveways and paving	**NO PERMIT FOUND as a stand-alone trade permit** — site/grading sheets (C-1, C-2) exist in the microfilm plan set as part of the overall site plan review, but no distinct paving permit number was identified.	
16	Fountains and ponds, with electrical	**NO PERMIT FOUND** — no fountain or pond feature appears on any plan sheet or permit description reviewed.	

#	System	Status	Evidence
17	Septic tank / OSTDS — search under Health Dept and HRS	**DEFERRED — needs a live pull.** The Florida DOH Onsite Sewage Program / legacy-HRS systems were not reached this pass (JS-driven portal, no REST endpoint found in the time available). The Property Appraiser's own "Government Agencies" panel links to DOH septic/well GIS layers for this address but we did not independently query them. Given the PECUC urban-center zoning and the surrounding built-up unincorporated area, county sewer is the likely service, but this is **not confirmed** — do not state "no septic" as a finding.	

Bed / bath reconciliation — the required sub-section

Never merged — what each source actually says:

Source	Beds	Baths	Living Sq.Ft.	What it describes
Property Appraiser (live, 2026-10-02)	5	5	3,863 heated (4,235 actual)	The **current** structure — 2025 year built, "Duplex Residential" + "Single Family Residential" building cards
Tax jacket (ordered 2026-08-24, OCR'd)	Not reliably totaled — OCR reads repeated "2BR APT" unit cards with 0–1.5 baths per unit across multiple sub-cards	Not reliably totaled	Base-rate/replacement-cost building-card sheets, poor scan quality	The **pre-1997 apartment structure** — the one demolished under Case 97357
Microfilm (X20261486 81)	— (no stand-alone building-card sheet)	—	—	2023–2025 **new-construction plan set** (process C2023131093) for the current 3-unit townhouse cluster — consistent with the PA record, not the jacket card

This is the headline finding, stated plainly: the tax jacket's bed/bath figures and the Property Appraiser's current bed/bath figures describe two different buildings, separated by a county-ordered demolition in 1997. That is not a contradiction to explain away — it is the record working as it should. But it means the tax jacket's numbers must **never** be quoted as describing the house standing today, and anyone relying on this folio's history should read Section 4 before Section 1. A secondary, unresolved disagreement sits inside the *current* record itself: the Property Appraiser's `UnitCount` field reads **5**, while the 2024 impact-fee assessment (Section 5 master-process table) was computed on **3** residential units. That gap was not reconciled this pass.

6. Site & Zoning Compliance (GIS overlay)

Source: Miami-Dade `MD_Emaps` ArcGIS MapServer, queried live at the parcel's point location 2026-10-02 and 2026-10-10. Working paper: `03-Research\2026-10-02 _ DD _ SITE-16 _ zoning-landuse _ v1.md`.

#	Check	Result
1	GIS parcel window (aerial + boundary)	**Not captured as an image this pass** — open item, imagery protocol incomplete (see Section 8).
2	Recorded plat map	**No recorded subdivision plat.** PA PlatBook / PlatPage fields are blank. The parcel exists by a **Waiver of Plat, WP D-25026** (OR 34294-771) — confirmed by both the legal description and a document in microfilm, "PLEX CAPITAL LLC D-25026 DUPLEX WAIVER OF PLAT.PDF."
3	Resolutions / variances / restrictive covenants	The legal description also cites a right-of-way dedication, **OR 33974-394** (N43FT taken for R/W) — a recorded instrument, not a zoning resolution or variance. **No separate variance or resolution was independently confirmed** this pass; the Clerk's resolution/variance index was not reached.
4	Lot coverage / buildable area	Lot 10,367 sf; building actual area 4,235 sf across 2 cards → **gross coverage ≈ 40.9%.** The PECUC/UC-R allowed coverage percentage was **not independently pulled** this pass — DEFERRED.
5	Setback compliance — main structure	**Not measured this pass.** Approved site-plan sheets (A-1, A-2) exist in the microfilm plan set and could support this overlay in a follow-up pass.
6	Setback compliance — accessory structures	**N/A** — no detached accessory structure appears on the PA building record.
7	Flood zone — confirmed via GIS layer	**Zone X — "Area of Minimal Flood Hazard"** (MD_Emaps layer 85, ZONESUBTY field). Confirmed live, not carried over from an old report.
8	Utility service — sewer/septic, water/well	**Not independently confirmed.** Cross-references Section 5, row 17 — this is the same open finding stated from the zoning side, not a second problem.
9	Alternative uses under current zoning	Primary zone 3050, "UC EDGE - RESIDENTIAL (R) 2 MAX HT," inside the **Perrine Community Urban Center (PECUC)** overlay. PECUC edge zoning typically pairs residential with limited mixed-use near the urban core, but the exact alternative-use table requires the municipal zoning code text, which was **not reached** this pass — DEFERRED.

Other confirmed overlay facts: Commission District 3 (Kionne L. McGhee); municipality code 30, "Unincorporated Miami-Dade"; land-use overlay 13 flags an adjoining parcel reading "Vacant, Non-Protected, Privately-Owned" (LU 804) — this is the neighboring object ID returned by the point query, not this folio's own land-use code, and is noted here only so it is not mistaken for a finding about the subject parcel.

7. The Tax Jacket — what is on file and what it actually documents

Source: Tax jacket ordered 2026-08-24 (free, Property Appraiser contact form), held in the capsule at `07-TAX-JACKET_2026-08-24\ORIGINAL` and `\ENHANCED` (3-part PDF, `FINAL_ALL.pdf`, and a filed 2026-09-03 deliverable copy). OCR sidecars (`.SEARCH.txt`) read by eye this pass.

In plain English. This jacket is the documentary proof of the *other* building — the one Case 97357 describes as demolished in 1997. The scanned building-card sheets are old, handwritten-style microfiche, and the OCR is rough, but the repeating pattern is unmistakable: multiple **"2BR APT"** unit cards, each with its own small bathroom count (several read "0" or "1/2"), base-rate and replacement-cost tables typical of a mid-century small apartment building. This is consistent with a structure the county judged a fire, electrical, occupancy and life-safety hazard in 1997 (Section 4) — not with the single-family/duplex cluster standing on the lot today.

Limit, stated plainly: OCR quality on these cards is poor enough that we did not attempt to total an exact bedroom/bathroom count for the demolished structure — doing so from this scan would be a guess dressed as a fact. What we can state with confidence is the *type* of structure (small multi-unit apartment building) and that it is **not** the current house. A cleaner image pull or a second microfilm order focused specifically on the pre-1997 building card would be needed to put a hard number on it.

---

8. What We Could Not Reach

Every item below is an **open** question, not a clean result — none of these are reported as clear.

#	Source	Wall hit	Single simplest next step
8.1	Miami-Dade Clerk, Official Records (liens, mortgages, judgments, satisfactions)	Cloudflare Turnstile CAPTCHA, no challenge attempted	This is the one that matters most — it would independently confirm nothing else is recorded against this folio or against Charles A. Robinson beyond the satisfied Case 97357 lien. Needs a headed/live browser session.
8.2	Miami-Dade Clerk, civil case search	CAPTCHA/registered-browser wall; we now have real party names (10362 PAO Estates LLC, Plex Capital LLC, Tony McCray, Carolyn Davis, Charles A. Robinson) to run once access is available	Live browser session.
8.3	Miami-Dade Tax Collector — current balance & delinquency	Scripted request hit a bot wall at `county-taxes.net`	Live browser lookup using the dashed folio.
8.4	Miami-Dade Building Permit Selection Menu (county's own permit portal, as distinct from the free ArcGIS feed)	reCAPTCHA Enterprise	Live browser session.
8.5	EPS e-permitting portal	Requires sign-in	Sign in to EPS.
8.6	Code Enforcement Online System	Network error (HTTP 0), redirects not followed	Retry after connectivity recovers.

#	Source	Wall hit	Single simplest next step
8.7	Neighborhood Code Case Search	Zero results, no feature IDs returned — quarantined as unverified, not reported as clean	Independent re-check.
8.8	Certificates of Use	Modern CU search is login-walled; public archive stops around 2012	Sign in to EPS for a current CU lookup.
8.9	DERM environmental/code layers (12 layers checked)	All returned zero with no feature IDs — quarantined, not reported as clean	Independent re-check of the flagged layers.
8.10	Florida NOA / Product Approval search	Needs a specific product/NOA number, not a folio or address	Pull the NOA numbers directly off the roofing permit's NOA01/NOA02 sheets already in microfilm, then search by number.
8.11	Florida Sunbiz — entity search on "10362 PAO ESTATES LLC" and "PLEX CAPITAL LLC"	Attempted live this pass — **HTTP 403 Forbidden** (bot-walled)	Live browser session.
8.12	Florida DBPR licensee search (contractors on the permits: CGP Group LLC, Roofing By Royale Inc, E & Sons Electrical, Specialty Services USA LLC)	Needs a license number, not a company name	Pull license numbers off the permit cards, then search DBPR.
8.13	Septic/OSTDS under DOH and legacy HRS	JS-driven portal; no REST endpoint located in the time available	Live browser session against the DOH Onsite Sewage Program portal.
8.14	Imagery protocol — Building Sketch and 5 Pictometry angle views	Not captured this pass	Screen-capture both image sets from the PA Building Sketch Viewer and Pictometry viewer; this is required before the report can be called complete under the standing imagery protocol.
8.15	GIS parcel window, setback measurements, allowed lot-coverage %, PECUC alternative-use table	Deferred — needs manual GIS overlay work against the approved site plan	Pull the A-1/A-2 site-plan sheets already in microfilm against a captured GIS parcel image.

City of Miami permits: **not applicable** — this folio is unincorporated County, not a City of Miami folio. Miami Beach and Pembroke Pines/Broward: **not applicable** — wrong jurisdiction; both also returned network errors when tried, which is moot given the jurisdiction mismatch.

9. Sources Searched — the full list, method and result

#	Source	Method	Outcome
1	Property Appraiser — folio record	Folio (live)	Retrieved — Sections 1, 2, 3
2	Property Appraiser — sales & transfer history	Folio (live)	Retrieved — 7 transfers, Section 2
3	Property Appraiser — assessment & taxable roll	Folio (live)	Retrieved — 3 years, Section 3
4	Property Appraiser — additional info / government-agency links	Folio (live)	Retrieved — informational only, Section 6
5	RER Regulation Support Web Viewer — Unsafe Structures	Folio	**1 case found — 97357**, full case detail + Recordations + Payments + Tickets + Activities tabs pulled, Section 4
6	RER Regulation Support Web Viewer — Building Support Case Search	Folio	Same single case (97357) confirmed via a second entry point, Section 4
7	Miami-Dade free keyless ArcGIS permit feed (`miamidade_permit_data`)	FolioNumber (live, 2026-10-10)	**7 trade permit records retrieved**, Section 5 — rolling 24-month window, does not reach the 2023 master process
8	Microfilm order X2026148681	Ordered, held in capsule, read by eye with OCR	2 permit folders (PERMIT-2023131093, PERMIT-2025064169) — Sections 5, 6, 7
9	Tax jacket, ordered 2026-08-24	Ordered, held in capsule (ORIGINAL + ENHANCED), read by eye with OCR	Pre-1997 apartment-building card sheets, Section 7
10	Miami-Dade Clerk — Official Records (liens/mortgages)	Folio/legal description	**Blocked** — CAPTCHA, Section 8.1
11	Miami-Dade Clerk — civil case search	Party name	**Blocked** — CAPTCHA, Section 8.2
12	Miami-Dade Tax Collector — balance due	Folio	**Blocked** — bot wall, Section 8.3
13	Building Permit Selection Menu (county portal)	Folio	**Blocked** — reCAPTCHA, Section 8.4
14	EPS e-permitting	Folio/address	**Blocked** — login required, Section 8.5
15	Code Enforcement Online System	Folio	**Blocked** — network error, Section 8.6
16	Neighborhood Code Case Search	Folio	0 results — quarantined unverified, Section 8.7
17	Certificates of Use	Folio	**Blocked** — login-walled (current); archive ends ~2012, Section 8.8

#	Source	Method	Outcome
18	DERM environmental/code enforcement (12 layers)	Folio	0 on all layers — quarantined unverified, Section 8.9
19	DERM public records archive	Folio	Paging issue — incomplete, Section 8.9
20	Florida NOA / Product Approval	Product number required	**Blocked** — wrong key type, Section 8.10
21	Florida Sunbiz	Entity name (live, 2026-10-10)	**Blocked — HTTP 403**, Section 8.11
22	Florida DBPR	License number required	**Blocked** — wrong key type, Section 8.12
23	MD_Emaps zoning/land-use GIS overlay (6 layers)	Parcel point location (live)	Retrieved — Section 6
24	City of Miami permits	Jurisdiction check	**Not applicable** — folio is unincorporated County
25	City of Miami Beach permits	Jurisdiction check	**Not applicable**
26	Pembroke Pines / Broward Property Appraiser	Jurisdiction check	**Not applicable**
27	Septic/OSTDS — DOH / legacy HRS	Not reached	**Deferred**, Section 8.13
28	PA Building Sketch Viewer + Pictometry (imagery protocol)	Not reached	**Deferred**, Section 8.14

10. Basis & Limits

This report reflects public records as they stood between 2026-08-15 and 2026-10-10, pulled live where marked and otherwise dated to the working paper cited. It is a due-diligence reference packet, **not** a title search, title opinion, survey, or legal advice, and it is **not** a substitute for title insurance. Jorge Valdes is not a licensed attorney and holds no professional license in Florida. Fee and balance figures are as of the audit dates shown above — confirm with the municipality or a title company before relying on any dollar figure for a closing or a payoff. Sections 3 (tax balance), 6 (several rows), and 8 (all fifteen items) are explicitly **open**, not clear, and must not be read as a clean result. The Case 97357 lien satisfaction described in Section 4 is read from the county's own recorded-instrument index; it is not a substitute for a Clerk's certified copy, and the face dollar amount of the original lien was not located in the sources reached this pass.

Microfilm and tax-jacket copy fees for this property were pre-approved and already incurred (orders dated 2026-08-15/2026-08-24); no new spend was authorized or made in producing this report. Freshness: this report is current as of 2026-10-10 and should be treated as stale after any new Clerk, Tax Collector, or permit-portal pull becomes available — particularly items 8.1 through 8.3.