

Bal Harbour Plaza

10000 W Bay Harbor Dr

OPH-2026-0007 (orphan) · folio not established · HOA-questioned units

Due-Diligence Dossier — no county jacket on file; built from public records

Verdict: an **unresolved orphan matter, not a deliverable DD file**. No folio and no owner established; identity may overlap TRK-2026-1582; the delivery package is incomplete (empty permit / invoice folders, 0 of 8, and missing statements of account). Correctly carries an OPH number, not a TRK. Whether it should get a TRK is an open owner decision (OPEN-ITEMS TRK-2026-9049).

Overall risk rating: UNRATED — identity unresolved; not deliverable until reconciled

Orphan OPH-2026-0007 · OPEN-ITEMS TRK-2026-9049 · Prepared 2026-08-30 · Version 1 · CURRENT

Index

Each section of this dossier, by page.

Cover	1
Index	2
1 · Executive summary & verdict	3
2 · Property & matter facts	4
3 · Additions, alterations & permits	5
4 · Causes of concern	6
5 · Data gaps / not verified	7

Executive summary

The matter. **OPH-2026-0007** — an ORPHAN number, deliberately NOT a TRK — covering **10000 W Bay Harbor Dr**, “Bal Harbour Plaza / HOA-questioned units.” It is Alec-associated, surfaced from the **ORANGETREE-POPULATE_ALEC-BALHARBOUR-PLAZA** job (2026-08-13).

Verdict

This is an **unresolved orphan matter, not a deliverable DD file**. No folio and no owner have been established in the reviewed records, so there is no county jacket to pull and no property facts to certify. The identity itself is open: it **may be the same building as TRK-2026-1582** (“Bay Harbor 10000 Building”), and the exact relationship between the Alec Orange Tree matter, OPH-2026-0007 and TRK-2026-1582 is not resolved and must not be asserted as one.

The delivery package is also **not ready to ship**: transmittals claim “all evidence in hand” but list system-made files, every transmittal names a statement-of-account no folder contains, and the permit-records and invoice folders are empty (0 of 8).

Risk cannot be rated until the identity is settled and the package is reconciled. Whether this should get a TRK is an open owner decision (OPEN-ITEMS TRK-2026-9049).

Property & matter facts

Number : OPH-2026-0007 (ORPHAN number – deliberately NOT a TRK)
Address : 10000 W Bay Harbor Dr – "Bal Harbour + Plaza / HOA-questioned units"
Folio : not established in the reviewed records
Owner : not established
Job party : Alec-associated (via ORANGETREE-POPULATE_ALEC-BALHARBOUR-PLAZA, 2026-08-13)

Units / documents (quoted)

8 units (the Orange Tree) – HOA-questioned units.
135 files across two sets – 8 finished capsule PDFs and 19 genuine
client documents (Units 305 and 321).
Five TRK-TBD unit folders exist for the same building – 221, 301, 302, 404, 425.

Capsule folder OPH-2026-0007 _ Bal Harbour + Plaza _ HOA-questioned units was created by the desktop unattended at 02:01, 2026-08-16. Portal _PORTAL_BAL-HARBOUR-PLAZA_OPH-2026-0007.html is 9/9 click-proven after a shared button-bug fix.

Additions, alterations & permits

None established. With no folio and no owner fixed for this matter, no permit or Certificate-of-Use history has been pulled, and there is no county jacket to retrieve.

The building sits in Bay Harbor Islands / Bal Harbour, so any building permit or CU would be **held by that municipality, not the county**. The permit-records folder in the current package is **empty (0 of 8)**. Permit review cannot begin until the folio and the correct jurisdiction are confirmed.

Causes of concern

1. **No TRK, correctly.** The desktop was told “Bal Harbour Plaza has NO TRK; do not invent one, do not borrow 1582.” It correctly issued OPH-2026-0007 rather than minting a number for a job whose identity is not yet certain. Whether it should get a TRK is an open owner decision (OPEN-ITEMS TRK-2026-9049).
2. **Possible same building as TRK-2026-1582.** TRK-2026-1582 is “Bay Harbor 10000 Building” (contacts Jennifer Ting Chen, Reyna Jovel), which may be the same 10000 W Bay Harbor Dr structure. The exact relationship between the Alec Orange Tree matter, OPH-2026-0007 and TRK-2026-1582 is not fully resolved and must not be asserted as one.
3. **Five TRK-TBD unit folders** (221, 301, 302, 404, 425) collide in any sort — a defect; they should be OPH numbers.
4. **Delivery-readiness defect.** Transmittals claim “all evidence in hand” but list system-made files; every transmittal names a statement-of-account no folder contains; permit-records and invoice folders are empty (0 of 8). Nothing should ship until that is reconciled.
5. **The originating ORANGETREE job (2026-08-13) asked “still live or superseded?” and was never answered** — a live specimen of a question that stalled the work.

Data gaps & not verified

Each gap names the owner action that would close it.

1. **No folio or owner established. Closes with:** a property lookup for 10000 W Bay Harbor Dr once Jorge confirms the matter is live.
2. **Identity unresolved.** Relationship to TRK-2026-1582 and to the Alec Orange Tree job is not settled. **Closes with:** Jorge confirming whether OPH-2026-0007 and TRK-2026-1582 are the same building.
3. **Should it get a TRK?** Open owner decision (OPEN-ITEMS TRK-2026-9049). **Closes with:** Jorge's yes/no on opening a TRK.
4. **Delivery package incomplete.** Empty permit / invoice folders (0 of 8); missing statements of account. **Closes with:** reconciling the package before anything ships.
5. **Five TRK-TBD folders (221, 301, 302, 404, 425).** **Closes with:** reissuing them as OPH numbers.