```
{
        "feeds":[
                 "KEIO_STE_ID":"#0001",
                 "Status":"",
                 "Safecast_ID":"",
                 "Sensor_Type": "Inspector Alert",
                 "Inspector_SN": "A03467",
                 "FeedID":26896,
                 "PachubeFeed": "http://www.pachube.com/feeds/26896",
                 "Device_ID": "KEIOSTE231",
                 "Type": "WiFi",
                 "FirmwareVersion": "1/20/12",
                 "nGeigieID":"",
                 "Inuse": "Yes",
                 "Location": ""Nagoya, Softbank"",
                 "Latitude":136.9078016,
                 "Longitude":0.6,
                 "Height(m)": "Indoor",
                 "Indoor_Outdoor":"",
                 "Action_needed":""
        },{
                 "KEIO_STE_ID": "#0002",
                 "Status":"",
                 "Safecast_ID":"",
                 "Sensor_Type": "Inspector Alert",
                 "Inspector_SN": "A03700",
                 "FeedID":26897,
                 "PachubeFeed": "http://www.pachube.com/feeds/26897",
                 "Device_ID": "KEIOSTE232",
                 "Type": "WiFi",
                 "FirmwareVersion": "1/20/12",
                 "nGeigieID":"",
                 "Inuse": "Yes",
                 "Location": ""Shizuoka, Softbank"",
                 "Latitude":34.97434877,
                 "Longitude":138.386879,
                 "Height(m)":"1",
                 "Indoor_Outdoor": "Indoor",
                 "Action_needed":""
        },{
                 "KEIO_STE_ID": "#0003",
                 "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A01743",
        "FeedID":28447,
        "PachubeFeed": "http://www.pachube.com/feeds/28447",
        "Device_ID": "KEIOSTE21",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Roppongi, Softbank"",
        "Latitude":35.66360738,
        "Longitude":139.732275,
        "Height(m)":"0.2",
        "Indoor_Outdoor":"Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#004",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":28494,
        "PachubeFeed": "http://www.pachube.com/feeds/28494",
        "Device_ID": "KEIOSTE64",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Chiba, Softbank"",
        "Latitude":35.60982476,
        "Longitude":140.1219463,
        "Height(m)": "0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0005",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03580",
        "FeedID":28493,
        "PachubeFeed": "http://www.pachube.com/feeds/28493",
        "Device_ID": "KEIOSTE236",
```

```
"Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Nihonmatsu, Softbank"",
        "Latitude":140.4319668,
        "Longitude":2,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":""
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0006",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A01752",
        "FeedID":28446,
        "PachubeFeed": "http://www.pachube.com/feeds/28446",
        "Device_ID": "KEIOSTE33",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID": "#003",
        "Inuse": "Yes",
        "Location": ""Nagano, Softbank"",
        "Latitude": 36.64180564,
        "Longitude":138.1906271,
        "Height(m)":"1.2",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0007",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03122",
        "FeedID":28445,
        "PachubeFeed": "http://www.pachube.com/feeds/28445",
        "Device_ID": "KEIOSTE237",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID": "#007",
        "Inuse": "Yes",
        "Location": ""Shibuya, Softbank"",
        "Latitude":35.66019036,
```

```
"Longitude":139.6986294,
        "Height(m)":"0.7",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#008",
        "Status":"",
        "Safecast_ID": "#0073",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01818",
        "FeedID":28448,
        "PachubeFeed": "http://www.pachube.com/feeds/28448",
        "Device_ID": "KEIOSTE8",
        "Type": "Ethernet",
        "FirmwareVersion": "1/20/12",
        "nGeigieID": "#008",
        "Inuse": "Yes",
        "Location": ""Sendai, Softbank"",
        "Latitude":0.6,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":""
        "Action_needed":"y"
},{
        "KEIO_STE_ID": "#0009",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02910",
        "FeedID":28492,
        "PachubeFeed": "http://www.pachube.com/feeds/28492",
        "Device_ID": "KEIOSTE188",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Iwaki, Softbank"",
        "Latitude":140.901744,
        "Longitude":0.8,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#0010",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03478",
        "FeedID":28453,
        "PachubeFeed": "http://www.pachube.com/feeds/28453",
        "Device_ID": "KEIOSTE325",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"#010",
        "Inuse": "Yes",
        "Location":""Omiya, Softbank"",
        "Latitude":35.90907393,
        "Longitude":139.6266603,
        "Height(m)":"1.5",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#011",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A01739",
        "FeedID":28866,
        "PachubeFeed": "http://www.pachube.com/feeds/28866",
        "Device_ID": "KEIOSTE21",
        "Type": "Ethernet",
        "FirmwareVersion": "1/20/12",
        "nGeigieID": "#011",
        "Inuse": "Yes",
        "Location":""Omotesando, Softbank"",
        "Latitude":35.66862803,
        "Longitude":139.7052813,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action needed":""
},{
        "KEIO_STE_ID":"#012",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01930",
        "FeedID":29816,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/29816",
        "Device_ID": "KEIOSTE18",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"Yes",
        "Location": ""Tamachi, Softbank"",
        "Latitude":35.646269,
        "Longitude":139.747658,
        "Height(m)":"0",
        "Indoor_Outdoor":"Indoor (M2F)",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#013",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A01931",
        "FeedID":29817,
        "PachubeFeed": "http://www.pachube.com/feeds/29817",
        "Device_ID": "KEIOSTE19",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Fukushima1, Softbank"",
        "Latitude":0.9,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":""
        "Action_needed":"y"
},{
        "KEIO_STE_ID": "#014",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01736",
        "FeedID":29818,
        "PachubeFeed": "http://www.pachube.com/feeds/29818",
        "Device_ID": "KEIOSTE20",
        "Type":"/w AP",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
```

```
"Location": ""Makuhari, Softbank"",
        "Latitude":35.647765,
        "Longitude":140.040398,
        "Height(m)":"0.6",
        "Indoor_Outdoor":"Indoor (2F)",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#015",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01740",
        "FeedID":33843,
        "PachubeFeed": "http://www.pachube.com/feeds/33843",
        "Device_ID": "KEIOSTE22",
        "Type": "Ethernet",
        "FirmwareVersion":"7/21/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Minamisoma, Softbank"",
        "Latitude":37.6417,
        "Longitude":140.961809,
        "Height(m)":"0.7",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#016",
        "Status":""
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"A01741",
        "FeedID":33844,
        "PachubeFeed": "http://www.pachube.com/feeds/33844",
        "Device_ID": "KEIOSTE23",
        "Type":"/w AP",
        "FirmwareVersion": "7/21/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Hitachi, Softbank"",
        "Latitude":140.625866,
        "Longitude":2.2,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#017",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01819",
        "FeedID":34023,
        "PachubeFeed": "http://www.pachube.com/feeds/34023",
        "Device_ID": "KEIOSTE25",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Date, Softbank"",
        "Latitude":140.553054,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0018",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03374",
        "FeedID":33842,
        "PachubeFeed": "http://www.pachube.com/feeds/33842",
        "Device_ID": "KEIOSTE190",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Kamakura, Softbank"",
        "Latitude":0.9,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":"y"
},{
        "KEIO_STE_ID": "#019",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN": "A01744",
        "FeedID":33845,
        "PachubeFeed": "http://www.pachube.com/feeds/33845",
        "Device_ID": "KEIOSTE24",
        "Type":"/w AP",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Fujisawa, Softbank"",
        "Latitude":139.478984,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#020",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01745",
        "FeedID":34068,
        "PachubeFeed": "http://www.pachube.com/feeds/34068",
        "Device_ID": "KEIOSTE26",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Fukushima2, Softbank"",
        "Latitude":140.441629,
        "Longitude":0.7,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#021",
        "Status": "stopped",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01746",
        "FeedID":34512,
        "PachubeFeed": "http://www.pachube.com/feeds/34512",
        "Device_ID": "KEIOSTE27",
        "Type": "/w AP",
        "FirmwareVersion": "7/21/11",
```

```
"nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Hakodate, Softbank"",
        "Latitude":41.773554,
        "Longitude":140.728907,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#022",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01747",
        "FeedID":34513,
        "PachubeFeed": "http://www.pachube.com/feeds/34513",
        "Device_ID": "KEIOSTE7",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0023",
        "Status": "replace",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03483",
        "FeedID":34514,
        "PachubeFeed": "http://www.pachube.com/feeds/34514",
        "Device_ID": "KEIOSTE239",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Matsudo, Softbank"",
        "Latitude":139.913891,
        "Longitude":1,
        "Height(m)": "Indoor",
```

```
"Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#024",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01968",
        "FeedID":34515,
        "PachubeFeed": "http://www.pachube.com/feeds/34515",
        "Device_ID": "KEIOSTE68",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Moriya, Softbank"",
        "Latitude":35.943058,
        "Longitude":139.993473,
        "Height(m)":"1.1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#025",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01750",
        "FeedID": 34516,
        "PachubeFeed": "http://www.pachube.com/feeds/34516",
        "Device_ID": "KEIOSTE31",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Tsukuba, Softbank"",
        "Latitude":140.086185,
        "Longitude":0.8,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0026",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A01928",
        "FeedID":34582,
        "PachubeFeed": "http://www.pachube.com/feeds/34582",
        "Device_ID": "KEIOSTE43",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Iwaki2, Softbank"",
        "Latitude":140.936156,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#027",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03515",
        "FeedID":37135,
        "PachubeFeed": "http://www.pachube.com/feeds/37135",
        "Device_ID": "KEIOSTE30",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Motomiya, Softbank"",
        "Latitude":140.397471,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#028",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01753",
        "FeedID":34585,
        "PachubeFeed": "http://www.pachube.com/feeds/34585",
        "Device_ID": "KEIOSTE34",
```

```
"Type": "WiFi",
        "FirmwareVersion": "11/18/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Soma, Softbank"",
        "Latitude":140.928227,
        "Longitude":0.6,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":""
        "Action_needed":""
},{
        "KEIO_STE_ID": "#029",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01754",
        "FeedID":34586,
        "PachubeFeed": "http://www.pachube.com/feeds/34586",
        "Device_ID": "KEIOSTE35",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Fukushima3, Softbank"",
        "Latitude":140.47323,
        "Longitude":1.2,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#030",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01755",
        "FeedID":34588,
        "PachubeFeed": "http://www.pachube.com/feeds/34588",
        "Device_ID": "KEIOSTE36",
        "Type":"/w AP",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Fukushima4, Softbank"",
        "Latitude":140.465628,
```

```
"Longitude":0.8,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":""
        "Action_needed":""
},{
        "KEIO_STE_ID": "#031",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01756",
        "FeedID": 34976,
        "PachubeFeed": "http://www.pachube.com/feeds/34976",
        "Device_ID": "KEIOSTE37",
        "Type":"WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse":"Yes",
        "Location": ""Orient Park Asaka, Softbank"",
        "Latitude":140.349124,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0032",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03515",
        "FeedID":34977,
        "PachubeFeed": "http://www.pachube.com/feeds/34977",
        "Device_ID": "KEIOSTE61",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""KoriyamaTomita, Softbank"",
        "Latitude": 37.417508,
        "Longitude":140.362558,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#033",
        "Status": "stopped",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A01758",
        "FeedID":34978,
        "PachubeFeed": "http://www.pachube.com/feeds/34978",
        "Device_ID": "KEIOSTE39",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Iwaki3, Softbank"",
        "Latitude":0.7,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":"y"
},{
        "KEIO_STE_ID": "#0034",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03113",
        "FeedID":34979,
        "PachubeFeed": "http://www.pachube.com/feeds/34979",
        "Device_ID": "KEIOSTE232",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Koriyama1, Softbank"",
        "Latitude":140.3818303,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0035",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01757",
        "FeedID":34980,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/34980",
        "Device_ID": "KEIOSTE38",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"Yes",
        "Location": ""Sukagawa1, Softbank"",
        "Latitude":140.3816294,
        "Longitude":0.8,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#036",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A01927",
        "FeedID":34985,
        "PachubeFeed": "http://www.pachube.com/feeds/34985",
        "Device_ID": "KEIOSTE42",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""FukushimaIshikawa, Softbank"",
        "Latitude":0.9,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":""
        "Action_needed":"y"
},{
        "KEIO_STE_ID":"#0037",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03764",
        "FeedID": 34984,
        "PachubeFeed": "http://www.pachube.com/feeds/34984",
        "Device_ID": "KEIOSTE73",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
```

```
"Location": ""Kakuda, Softbank"",
        "Latitude":37.981393,
        "Longitude":140.784087,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0038",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01926",
        "FeedID":35179,
        "PachubeFeed": "http://www.pachube.com/feeds/35179",
        "Device_ID": "KEIOSTE41",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Yabuki, Softbank"",
        "Latitude":140.3307734,
        "Longitude":1,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0039",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":35180,
        "PachubeFeed": "http://www.pachube.com/feeds/35180",
        "Device_ID": "KEIOSTE99",
        "Type": "WiFI",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Watari, Softbank"",
        "Latitude":140.8534084,
        "Longitude":0.8,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0040",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03787",
        "FeedID":35181,
        "PachubeFeed": "http://www.pachube.com/feeds/35181",
        "Device_ID": "KEIOSTE74",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Shiroishi, Softbank"",
        "Latitude":140.632291,
        "Longitude":0.8,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0041",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03561",
        "FeedID":38687,
        "PachubeFeed": "http://www.pachube.com/feeds/38687",
        "Device_ID": "KEIOSTE63",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Shirakawa1, Softbank"",
        "Latitude":140.192292,
        "Longitude":0.95,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#042",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN": "A01748",
        "FeedID":35178,
        "PachubeFeed": "http://www.pachube.com/feeds/35178",
        "Device_ID": "KEIOSTE29",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""TsuchiuraMinami, Softbank"",
        "Latitude":0.8,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor": "1F",
        "Action_needed":"y"
},{
        "KEIO_STE_ID": "#043",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"A01967",
        "FeedID":35184,
        "PachubeFeed": "http://www.pachube.com/feeds/35184",
        "Device_ID": "KEIOSTE49",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Narisawa, Softbank"",
        "Latitude":140.314067,
        "Longitude":0.85,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0044",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01924",
        "FeedID":37089,
        "PachubeFeed": "http://www.pachube.com/feeds/37089",
        "Device_ID": "KEIOSTE40",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
```

```
"nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Aizu1, Softbank"",
        "Latitude":139.9249105,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#045",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03425",
        "FeedID":37090,
        "PachubeFeed": "http://www.pachube.com/feeds/37090",
        "Device_ID": "KEIOSTE51",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "instock",
        "Location":""Urawa, Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#047",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03528",
        "FeedID":37092,
        "PachubeFeed": "http://www.pachube.com/feeds/37092",
        "Device_ID": "KEIOSTE53",
        "Type": "WiFi",
        "FirmwareVersion": "11/25/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Koharada, Softbank"",
        "Latitude":140.385176,
        "Longitude": 0.95,
        "Height(m)": "Indoor",
```

```
"Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0048",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01982",
        "FeedID":37093,
        "PachubeFeed": "http://www.pachube.com/feeds/37093",
        "Device_ID": "KEIOSTE57",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Kaguike, Softbank"",
        "Latitude":37.377515,
        "Longitude":140.374547,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#049",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03543",
        "FeedID": 37094,
        "PachubeFeed": "http://www.pachube.com/feeds/37094",
        "Device_ID": "KEIOSTE55",
        "Type": "WiFi",
        "FirmwareVersion": "11/25/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Toramaru, Softbank"",
        "Latitude":140.373763,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#050",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03547",
        "FeedID":37130,
        "PachubeFeed": "http://www.pachube.com/feeds/37130",
        "Device_ID": "KEIOSTE56",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Ankohdori, Softbank"",
        "Latitude": 37.392746,
        "Longitude":140.354384,
        "Height(m)":"1",
        "Indoor_Outdoor":"Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0051",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03370",
        "FeedID":37132,
        "PachubeFeed": "http://www.pachube.com/feeds/37132",
        "Device_ID": "KEIOSTE189",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Kuroiso, Softbank"",
        "Latitude":140.036506,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0052",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03074",
        "FeedID":37133,
        "PachubeFeed": "http://www.pachube.com/feeds/37133",
        "Device_ID": "KEIOSTE238",
```

```
"Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Matsuegakuen, Softbank"",
        "Latitude":133.071153,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":""
        "Action_needed":""
},{
        "KEIO_STE_ID": "#053",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03555",
        "FeedID": 37134,
        "PachubeFeed": "http://www.pachube.com/feeds/37134",
        "Device_ID": "KEIOSTE60",
        "Type":"WiFi",
        "FirmwareVersion": "11/25/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Yaita, Softbank"",
        "Latitude":36.806753,
        "Longitude":139.935789,
        "Height(m)":"0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0054",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01965",
        "FeedID":38685,
        "PachubeFeed": "http://www.pachube.com/feeds/38685",
        "Device_ID": "KEIOSTE47",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Tsukidate, Softbank"",
        "Latitude":141.016633,
```

```
"Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":""
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0055",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01962",
        "FeedID":38687,
        "PachubeFeed": "http://www.pachube.com/feeds/38687",
        "Device_ID": "KEIOSTE46",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"Yes",
        "Location": ""Noda, Softbank"",
        "Latitude":140.450189,
        "Longitude":0.6,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#056",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03562",
        "FeedID":38689,
        "PachubeFeed": "http://www.pachube.com/feeds/38689",
        "Device_ID": "KEIOSTE65",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Minami-sanriku, Softbank"",
        "Latitude":141.46353,
        "Longitude":0,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#057",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03575",
        "FeedID":38690,
        "PachubeFeed": "http://www.pachube.com/feeds/38690",
        "Device_ID": "KEIOSTE66",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Okawahara, Softbank"",
        "Latitude":0,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#058",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03579",
        "FeedID":38691,
        "PachubeFeed": "http://www.pachube.com/feeds/38691",
        "Device_ID": "KEIOSTE67",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Iwanuma, Softbank"",
        "Latitude":140.875187,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#059",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03697",
        "FeedID":38694,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/38694",
        "Device_ID": "KEIOSTE70",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""SukagawaInter, Softbank"",
        "Latitude":140.361203,
        "Longitude":0.7,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#060",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03698",
        "FeedID":38695,
        "PachubeFeed": "http://www.pachube.com/feeds/38695",
        "Device_ID": "KEIOSTE71",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Shin-Shirakawa, Softbank"",
        "Latitude": 37.117102,
        "Longitude":140.195733,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#061",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03710",
        "FeedID":38696,
        "PachubeFeed": "http://www.pachube.com/feeds/38696",
        "Device_ID": "KEIOSTE72",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "Yes",
```

```
"Location": ""Tokai, Softbank"",
        "Latitude":36.471882,
        "Longitude":140.548092,
        "Height(m)":"0.84",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#062",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02207",
        "FeedID":38886,
        "PachubeFeed": "http://www.pachube.com/feeds/38886",
        "Device_ID": "KEIOSTE75",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Yoshinari, Softbank"",
        "Latitude":38.289533,
        "Longitude":140.820595,
        "Height(m)":"0.5",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#063",
        "Status":"",
        "Safecast_ID":"#0074",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"A01742",
        "FeedID":38885,
        "PachubeFeed": "http://www.pachube.com/feeds/38885",
        "Device_ID": "KEIOSTE24",
        "Type": "WiFi",
        "FirmwareVersion":"11/25/11",
        "nGeigieID": "#009",
        "Inuse": "shipped",
        "Location": ""Narita, Softbank"",
        "Latitude":35.795139,
        "Longitude":140.314014,
        "Height(m)":"1.5",
        "Indoor_Outdoor":"Indoor",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#064",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01751",
        "FeedID":38697,
        "PachubeFeed": "http://www.pachube.com/feeds/38697",
        "Device_ID": "KEIOSTE32",
        "Type":"WiFi",
        "FirmwareVersion": "11/25/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Ushiku, Softbank"",
        "Latitude":140.151627,
        "Longitude":1,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#065",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02213",
        "FeedID":42004,
        "PachubeFeed": "http://www.pachube.com/feeds/42004",
        "Device_ID": "KEIOSTE77",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Wakkanai, Softbank"",
        "Latitude":141.689534,
        "Longitude":0.7,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#066",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN": "A02219",
        "FeedID":42005,
        "PachubeFeed": "http://www.pachube.com/feeds/42005",
        "Device_ID": "KEIOSTE78",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Marugameshotengai, Softbank"",
        "Latitude":0.8,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":""
        "Action_needed":"y"
},{
        "KEIO_STE_ID": "#067",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"A02227",
        "FeedID":42006,
        "PachubeFeed": "http://www.pachube.com/feeds/42006",
        "Device_ID": "KEIOSTE79",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Yamatokooriyama, Softbank"",
        "Latitude":135.76797,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#068",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02234",
        "FeedID":42007,
        "PachubeFeed": "http://www.pachube.com/feeds/42007",
        "Device_ID": "KEIOSTE80",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
```

```
"nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Yumoto, Softbank"",
        "Latitude":140.868628,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#069",
        "Status": "v2.1",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02238",
        "FeedID":42008,
        "PachubeFeed": "http://www.pachube.com/feeds/42008",
        "Device_ID": "KEIOSTE81",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"instock",
        "Location": ""Pipeline, Softbank"",
        "Latitude":26.243616,
        "Longitude":127.706264,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#070",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02240",
        "FeedID":42310,
        "PachubeFeed": "http://www.pachube.com/feeds/42310",
        "Device_ID": "KEIOSTE82",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Nishinasuno, Softbank"",
        "Latitude":140.006823,
        "Longitude":0.9,
        "Height(m)": "Indoor",
```

```
"Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#071",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02242",
        "FeedID":42311,
        "PachubeFeed": "http://www.pachube.com/feeds/42311",
        "Device_ID":"KEIOSTE83",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Sakuragi, Softbank"",
        "Latitude":139.054183,
        "Longitude": 0.35,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0072",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03548",
        "FeedID":42312,
        "PachubeFeed": "http://www.pachube.com/feeds/42312",
        "Device_ID": "KEIOSTE58",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location":""Shijojimachi, Softbank"",
        "Latitude":135.766535,
        "Longitude":0.91,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#073",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02253",
        "FeedID":42313,
        "PachubeFeed": "http://www.pachube.com/feeds/42313",
        "Device_ID": "KEIOSTE85",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "Yes",
        "Location": ""Ueda, Softbank"",
        "Latitude":140.775054,
        "Longitude":0.7,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#074",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02265",
        "FeedID":42314,
        "PachubeFeed": "http://www.pachube.com/feeds/42314",
        "Device_ID": "KEIOSTE86",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Kashima, Softbank"",
        "Latitude":140.90734,
        "Longitude":0.5,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#076",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03407",
        "FeedID":42877,
        "PachubeFeed": "http://www.pachube.com/feeds/42877",
        "Device_ID": "KEIOSTE88",
```

```
"Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "instock",
        "Location": ""Hirara, Softbank"",
        "Latitude":24.80096,
        "Longitude":125.286948,
        "Height(m)": "0.7",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0077",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03413",
        "FeedID":42878,
        "PachubeFeed": "http://www.pachube.com/feeds/42878",
        "Device_ID": "KEIOSTE89",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Maebashi, Softbank"",
        "Latitude":139.066824,
        "Longitude":0,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0078",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID": 42879,
        "PachubeFeed": "http://www.pachube.com/feeds/42879",
        "Device_ID": "KEIOSTE90",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""KushiroShowa, Softbank"",
        "Latitude":144.358892,
```

```
"Longitude":1.2,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":""
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0079",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42880,
        "PachubeFeed": "http://www.pachube.com/feeds/42880",
        "Device_ID": "KEIOSTE91",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Ekimaedori, Softbank"",
        "Latitude":141.35211,
        "Longitude":1.2,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0080",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42881,
        "PachubeFeed": "http://www.pachube.com/feeds/42881",
        "Device_ID": "KEIOSTE92",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""AkitaEkimae, Softbank"",
        "Latitude": 39.717787,
        "Longitude":140.126668,
        "Height(m)":"1.2",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#0081",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42885,
        "PachubeFeed": "http://www.pachube.com/feeds/42885",
        "Device_ID": "KEIOSTE93",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Sanuma, Softbank"",
        "Latitude":38.683965,
        "Longitude":141.186035,
        "Height(m)":"0.5",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0082",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42886,
        "PachubeFeed": "http://www.pachube.com/feeds/42886",
        "Device_ID": "KEIOSTE94",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Shimoda, Softbank"",
        "Latitude": 34.678614,
        "Longitude":138.944016,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0083",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42887,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/42887",
        "Device_ID": "KEIOSTE95",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Wajima, Softbank"",
        "Latitude": 37.392065,
        "Longitude":136.904912,
        "Height(m)":"1.2",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0084",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42888,
        "PachubeFeed": "http://www.pachube.com/feeds/42888",
        "Device_ID": "KEIOSTE96",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""AomoriKankoDori, Softbank"",
        "Latitude":40.806182,
        "Longitude":140.754854,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0085",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42889,
        "PachubeFeed": "http://www.pachube.com/feeds/42889",
        "Device_ID": "KEIOSTE97",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
```

```
"Location": ""KanazawaKatamachi, Softbank"",
        "Latitude":36.561398,
        "Longitude":136.653561,
        "Height(m)":"0.6",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0086",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42890,
        "PachubeFeed": "http://www.pachube.com/feeds/42890",
        "Device_ID": "KEIOSTE98",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Shiozawa, Softbank"",
        "Latitude":37.041502,
        "Longitude":138.858104,
        "Height(m)":"0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0087",
        "Status":""
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01969",
        "FeedID":42891,
        "PachubeFeed": "http://www.pachube.com/feeds/42891",
        "Device_ID": "KEIOSTE69",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""JoetsuKenshin, Softbank"",
        "Latitude":138.24086,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0088",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42892,
        "PachubeFeed": "http://www.pachube.com/feeds/42892",
        "Device_ID": "KEIOSTE100",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Tomidaimae, Softbank"",
        "Latitude":137.187453,
        "Longitude":1.1,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0089",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42896,
        "PachubeFeed": "http://www.pachube.com/feeds/42896",
        "Device_ID": "KEIOSTE101",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Otawara, Softbank"",
        "Latitude":140.018424,
        "Longitude":0.9,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0090",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN":"",
        "FeedID":42897,
        "PachubeFeed": "http://www.pachube.com/feeds/42897",
        "Device_ID": "KEIOSTE102",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Utsunomiya, Softbank"",
        "Latitude":139.867055,
        "Longitude":0.6,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0091",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42898,
        "PachubeFeed": "http://www.pachube.com/feeds/42898",
        "Device_ID": "KEIOSTE103",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Hamaoka, Softbank"",
        "Latitude":34.639231,
        "Longitude":138.127694,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0092",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42899,
        "PachubeFeed": "http://www.pachube.com/feeds/42899",
        "Device_ID": "KEIOSTE104",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
```

```
"nGeigieID":"",
        "Inuse": "shipped",
        "Location":""MinamiIchiban, Softbank"",
        "Latitude":38.233146,
        "Longitude":140.329206,
        "Height(m)":"0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0093",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42900,
        "PachubeFeed": "http://www.pachube.com/feeds/42900",
        "Device_ID": "KEIOSTE105",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Mutsu, Softbank"",
        "Latitude":41.299082,
        "Longitude":141.19611,
        "Height(m)":"0.75",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0094",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42901,
        "PachubeFeed": "http://www.pachube.com/feeds/42901",
        "Device_ID": "KEIOSTE106",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Sakata, Softbank"",
        "Latitude":38.90627,
        "Longitude":139.857264,
        "Height(m)":"0.8",
```

```
"Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0095",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42902,
        "PachubeFeed": "http://www.pachube.com/feeds/42902",
        "Device_ID": "KEIOSTE107",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Yotsukaido, Softbank"",
        "Latitude":35.673949,
        "Longitude":140.16225,
        "Height(m)":"0.5",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0096",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42903,
        "PachubeFeed": "http://www.pachube.com/feeds/42903",
        "Device_ID": "KEIOSTE108",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Miyako, Softbank"",
        "Latitude":39.636853,
        "Longitude":141.927825,
        "Height(m)":"1.2",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0097",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42904,
        "PachubeFeed": "http://www.pachube.com/feeds/42904",
        "Device_ID": "KEIOSTE109",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""ChuoDori, Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0099",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42906,
        "PachubeFeed": "http://www.pachube.com/feeds/42906",
        "Device_ID": "KEIOSTE111",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Maizuru, Softbank"",
        "Latitude":35.448414,
        "Longitude":135.340044,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0100",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42907,
        "PachubeFeed": "http://www.pachube.com/feeds/42907",
        "Device_ID": "KEIOSTE112",
```

```
"Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Kohama, Softbank"",
        "Latitude":135.774792,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":""
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0101",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42908,
        "PachubeFeed": "http://www.pachube.com/feeds/42908",
        "Device_ID": "KEIOSTE113",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Sendaikuko, Softbank"",
        "Latitude":31.809693,
        "Longitude":130.331881,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0102",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID": 42909,
        "PachubeFeed": "http://www.pachube.com/feeds/42909",
        "Device_ID": "KEIOSTE114",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Iki, Softbank"",
        "Latitude":1.2,
```

```
"Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":"1F",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0103",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42910,
        "PachubeFeed": "http://www.pachube.com/feeds/42910",
        "Device_ID": "KEIOSTE115",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Karatsu, Softbank"",
        "Latitude":33.429825,
        "Longitude":129.982086,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0104",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42911,
        "PachubeFeed": "http://www.pachube.com/feeds/42911",
        "Device_ID": "KEIOSTE116",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Yanaichuo, Softbank"",
        "Latitude":33.96633,
        "Longitude":132.100797,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#0105",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID": 42912,
        "PachubeFeed": "http://www.pachube.com/feeds/42912",
        "Device_ID": "KEIOSTE117",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": "FukuokaTenjin, Softbank"",
        "Latitude":33.586877,
        "Longitude":130.397124,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0106",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42913,
        "PachubeFeed": "http://www.pachube.com/feeds/42913",
        "Device_ID": "KEIOSTE118",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Kengun, Softbank"",
        "Latitude": 32.777998,
        "Longitude":130.773985,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0107",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID": 42914,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/42914",
        "Device_ID": "KEIOSTE119",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""Ohita, Softbank"",
        "Latitude":33.234569,
        "Longitude":131.607958,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0108",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID": 42915,
        "PachubeFeed": "http://www.pachube.com/feeds/42915",
        "Device_ID": "KEIOSTE120",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""KankoDori, Softbank"",
        "Latitude": 32.745058,
        "Longitude":129.878667,
        "Height(m)":"0",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0109",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42916,
        "PachubeFeed": "http://www.pachube.com/feeds/42916",
        "Device_ID": "KEIOSTE121",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
```

```
"Location": ""Yoichi, Softbank"",
        "Latitude":140.801158,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0110",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42917,
        "PachubeFeed": "http://www.pachube.com/feeds/42917",
        "Device_ID": "KEIOSTE122",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""NiigataBandai, Softbank"",
        "Latitude":37.914617,
        "Longitude":139.056693,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0111",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42918,
        "PachubeFeed": "http://www.pachube.com/feeds/42918",
        "Device_ID": "KEIOSTE123",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Hirodaimae, Softbank"",
        "Latitude":132.715057,
        "Longitude":0.85,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0112",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42919,
        "PachubeFeed": "http://www.pachube.com/feeds/42919",
        "Device_ID": "KEIOSTE124",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""HiroshimaParco, Softbank"",
        "Latitude":132.46177,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0113",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42920,
        "PachubeFeed": "http://www.pachube.com/feeds/42920",
        "Device_ID": "KEIOSTE125",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Kiitanabe, Softbank"",
        "Latitude":33.732936,
        "Longitude":135.382526,
        "Height(m)":"0",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0114",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN":"",
        "FeedID":42921,
        "PachubeFeed": "http://www.pachube.com/feeds/42921",
        "Device_ID": "KEIOSTE126",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location":""MidosujisenUmeda, Softbank"",
        "Latitude":34.702463,
        "Longitude":135.49819,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0115",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03052",
        "FeedID":42922,
        "PachubeFeed": "http://www.pachube.com/feeds/42922",
        "Device_ID": "KEIOSTE50",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Uwajima, Softbank"",
        "Latitude":33.224412,
        "Longitude":132.560935,
        "Height(m)":"0.7",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0116",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":42923,
        "PachubeFeed": "http://www.pachube.com/feeds/42923",
        "Device_ID": "KEIOSTE128",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
```

```
"nGeigieID":"",
        "Inuse": "shipped",
        "Location": ""Yahatahama, Softbank"",
        "Latitude":132.431402,
        "Longitude":0.86,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0117",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03549",
        "FeedID":42924,
        "PachubeFeed": "http://www.pachube.com/feeds/42924",
        "Device_ID": "KEIOSTE129",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Asahi, Softbank"",
        "Latitude":31.908371,
        "Longitude":131.424635,
        "Height(m)":"0.7",
        "Indoor_Outdoor":"Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0118",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03789",
        "FeedID":42925,
        "PachubeFeed": "http://www.pachube.com/feeds/42925",
        "Device_ID": "KEIOSTE130",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""UtsunomiyaHigashi, Softbank"",
        "Latitude":36.564062,
        "Longitude":139.904952,
        "Height(m)":"1",
```

```
"Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0119",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03507",
        "FeedID":42926,
        "PachubeFeed": "http://www.pachube.com/feeds/42926",
        "Device_ID":"KEIOSTE131",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Izuronaya, Softbank"",
        "Latitude":130.556941,
        "Longitude":0.8,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0120",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03534",
        "FeedID":42927,
        "PachubeFeed": "http://www.pachube.com/feeds/42927",
        "Device_ID": "KEIOSTE132",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Tsushima, Softbank"",
        "Latitude":34.202279,
        "Longitude":129.289385,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0121",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02625",
        "FeedID":42928,
        "PachubeFeed": "http://www.pachube.com/feeds/42928",
        "Device_ID": "KEIOSTE133",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Iida, Softbank"",
        "Latitude":35.500857,
        "Longitude":137.799978,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0122",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03522",
        "FeedID":42929,
        "PachubeFeed": "http://www.pachube.com/feeds/42929",
        "Device_ID": "KEIOSTE134",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Takayama, Softbank"",
        "Latitude":36.153006,
        "Longitude":137.246787,
        "Height(m)":"1",
        "Indoor_Outdoor":"Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0123",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02917",
        "FeedID":42930,
        "PachubeFeed": "http://www.pachube.com/feeds/42930",
        "Device_ID": "KEIOSTE135",
```

```
"Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Asato, Softbank"",
        "Latitude":26.213028,
        "Longitude":127.696093,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0124",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03771",
        "FeedID":42931,
        "PachubeFeed": "http://www.pachube.com/feeds/42931",
        "Device_ID": "KEIOSTE136",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Ishigaki, Softbank"",
        "Latitude":24.341961,
        "Longitude":124.155247,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0125",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03574",
        "FeedID":42932,
        "PachubeFeed": "http://www.pachube.com/feeds/42932",
        "Device_ID": "KEIOSTE137",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Yamaguchichuo, Softbank"",
        "Latitude":34.177841,
```

```
"Longitude":131.478135,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0126",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03531",
        "FeedID":43986,
        "PachubeFeed": "http://www.pachube.com/feeds/43986",
        "Device_ID": "KEIOSTE138",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Obiyamachi, Softbank"",
        "Latitude":33.560604,
        "Longitude":133.53982,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0127",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03480",
        "FeedID":43987,
        "PachubeFeed": "http://www.pachube.com/feeds/43987",
        "Device_ID": "KEIOSTE139",
        "Type":"WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Gintengai, Softbank"",
        "Latitude":132.766053,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#0128",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02465",
        "FeedID":43988,
        "PachubeFeed": "http://www.pachube.com/feeds/43988",
        "Device_ID": "KEIOSTE140",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""TokushimaHigashi, Softbank"",
        "Latitude":34.070281,
        "Longitude":134.568695,
        "Height(m)": "0.6",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0129",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02880",
        "FeedID":43989,
        "PachubeFeed": "http://www.pachube.com/feeds/43989",
        "Device_ID": "KEIOSTE141",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""HimejiShiyakusho, Softbank"",
        "Latitude": 34.814607,
        "Longitude":134.690377,
        "Height(m)":"0.75",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0130",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02683",
        "FeedID":43990,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/43990",
        "Device_ID": "KEIOSTE142",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":""
        "Location": ""Yoshioka, Softbank"",
        "Latitude":38.439401,
        "Longitude":140.890956,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0131",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03797",
        "FeedID":43991,
        "PachubeFeed": "http://www.pachube.com/feeds/43991",
        "Device_ID": "KEIOSTE143",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Higashifurumatsu, Softbank"",
        "Latitude": 34.649599,
        "Longitude":133.912456,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0132",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02876",
        "FeedID":43992,
        "PachubeFeed": "http://www.pachube.com/feeds/43992",
        "Device_ID": "KEIOSTE144",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
```

```
"Location": ""HankyuSannomiya, Softbank"",
        "Latitude":34.692491,
        "Longitude":135.192589,
        "Height(m)":"1.1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0133",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03702",
        "FeedID":43993,
        "PachubeFeed": "http://www.pachube.com/feeds/43993",
        "Device_ID": "KEIOSTE145",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Obanazawa, Softbank"",
        "Latitude":38.609459,
        "Longitude":140.40751,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0134",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03542",
        "FeedID":43994,
        "PachubeFeed": "http://www.pachube.com/feeds/43994",
        "Device_ID": "KEIOSTE146",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Miyuki, Softbank"",
        "Latitude":136.234018,
        "Longitude":0.4,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0135",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03788",
        "FeedID":43995,
        "PachubeFeed": "http://www.pachube.com/feeds/43995",
        "Device_ID": "KEIOSTE147",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Kitakata, Softbank"",
        "Latitude": 37.647814,
        "Longitude":139.877289,
        "Height(m)":"0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0136",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02881",
        "FeedID":43996,
        "PachubeFeed": "http://www.pachube.com/feeds/43996",
        "Device_ID": "KEIOSTE148",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""TsuChuo, Softbank"",
        "Latitude":32.875335,
        "Longitude":130.869817,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0137",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN": "A03701",
        "FeedID":43997,
        "PachubeFeed": "http://www.pachube.com/feeds/43997",
        "Device_ID": "KEIOSTE149",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Wakayama, Softbank"",
        "Latitude":34.229132,
        "Longitude":135.196278,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0138",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03523",
        "FeedID":43998,
        "PachubeFeed": "http://www.pachube.com/feeds/43998",
        "Device_ID": "KEIOSTE150",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""YamagataOhnome, Softbank"",
        "Latitude":38.282656,
        "Longitude":140.360697,
        "Height(m)":"",
        "Indoor_Outdoor":""
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0139",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"A02735",
        "FeedID":43999,
        "PachubeFeed": "http://www.pachube.com/feeds/43999",
        "Device_ID": "KEIOSTE151",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
```

```
"nGeigieID":"",
        "Inuse":"",
        "Location":""IsewataRaibashi, Softbank"",
        "Latitude":136.678852,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0140",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02653",
        "FeedID":44000,
        "PachubeFeed": "http://www.pachube.com/feeds/44000",
        "Device_ID": "KEIOSTE152",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Komoro, Softbank"",
        "Latitude":36.337548,
        "Longitude":138.410906,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0141",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03527",
        "FeedID":44001,
        "PachubeFeed": "http://www.pachube.com/feeds/44001",
        "Device_ID": "KEIOSTE153",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""UedaMinami, Softbank"",
        "Latitude":138.211607,
        "Longitude":0.6,
        "Height(m)": "Indoor",
```

```
"Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0142",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03455",
        "FeedID":44002,
        "PachubeFeed": "http://www.pachube.com/feeds/44002",
        "Device_ID": "KEIOSTE154",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Ishimaki, Softbank"",
        "Latitude":38.434478,
        "Longitude":141.304092,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0143",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03489",
        "FeedID":44003,
        "PachubeFeed": "http://www.pachube.com/feeds/44003",
        "Device_ID": "KEIOSTE155",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""AizuInter, Softbank"",
        "Latitude":37.518172,
        "Longitude":139.923995,
        "Height(m)":"0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0144",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03703",
        "FeedID":44004,
        "PachubeFeed": "http://www.pachube.com/feeds/44004",
        "Device_ID": "KEIOSTE156",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""AizuByakko, Softbank"",
        "Latitude": 37.505188,
        "Longitude":139.943055,
        "Height(m)":"1",
        "Indoor_Outdoor":"Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0145",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03461",
        "FeedID":44005,
        "PachubeFeed": "http://www.pachube.com/feeds/44005",
        "Device_ID": "KEIOSTE157",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Oodate, Softbank"",
        "Latitude":40.284145,
        "Longitude":140.552186,
        "Height(m)":"1",
        "Indoor_Outdoor":"Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0146",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02893",
        "FeedID":44006,
        "PachubeFeed": "http://www.pachube.com/feeds/44006",
        "Device_ID": "KEIOSTE158",
```

```
"Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Aizubange, Softbank"",
        "Latitude": 37.565041,
        "Longitude":139.816101,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0147",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02665",
        "FeedID":44007,
        "PachubeFeed": "http://www.pachube.com/feeds/44007",
        "Device_ID": "KEIOSTE159",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Izumo, Softbank"",
        "Latitude":35.373657,
        "Longitude":132.757911,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0148",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03187",
        "FeedID":44008,
        "PachubeFeed": "http://www.pachube.com/feeds/44008",
        "Device_ID": "KEIOSTE160",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""MinamiNagasaki, Softbank"",
        "Latitude":129.83696,
```

```
"Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":""
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0149",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02918",
        "FeedID":44009,
        "PachubeFeed": "http://www.pachube.com/feeds/44009",
        "Device_ID": "KEIOSTE161",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""IonKohoku, Softbank"",
        "Latitude":33.219558,
        "Longitude":130.161361,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0150",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02479",
        "FeedID":44010,
        "PachubeFeed": "http://www.pachube.com/feeds/44010",
        "Device_ID": "KEIOSTE162",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""HigashiBypass, Softbank"",
        "Latitude": 32.822441,
        "Longitude":130.760064,
        "Height(m)":"0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#0151",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02646",
        "FeedID":44011,
        "PachubeFeed": "http://www.pachube.com/feeds/44011",
        "Device_ID": "KEIOSTE163",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Tosu, Softbank"",
        "Latitude":130.509785,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0152",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02585",
        "FeedID":44012,
        "PachubeFeed": "http://www.pachube.com/feeds/44012",
        "Device_ID": "KEIOSTE164",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Shiojiri, Softbank"",
        "Latitude":36.172138,
        "Longitude":137.95133,
        "Height(m)":"0.7",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0153",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03541",
        "FeedID":44013,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/44013",
        "Device_ID": "KEIOSTE165",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":""
        "Location": ""KofuShowa, Softbank"",
        "Latitude":138.541697,
        "Longitude":0.8,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0154",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03556",
        "FeedID":44014,
        "PachubeFeed": "http://www.pachube.com/feeds/44014",
        "Device_ID": "KEIOSTE166",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Hagi, Softbank"",
        "Latitude": 34.406555,
        "Longitude":131.405204,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0155",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03539",
        "FeedID":44015,
        "PachubeFeed": "http://www.pachube.com/feeds/44015",
        "Device_ID": "KEIOSTE167",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
```

```
"Location": ""NumzuKanuki, Softbank"",
        "Latitude":35.085854,
        "Longitude":138.868092,
        "Height(m)":"0.98",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0156",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03375",
        "FeedID":44016,
        "PachubeFeed": "http://www.pachube.com/feeds/44016",
        "Device_ID": "KEIOSTE168",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Furukawa, Softbank"",
        "Latitude":36.19372,
        "Longitude":139.738938,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0157",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"A03509",
        "FeedID":44017,
        "PachubeFeed": "http://www.pachube.com/feeds/44017",
        "Device_ID": "KEIOSTE169",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Choshi, Softbank"",
        "Latitude":140.8101,
        "Longitude":0.5,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0158",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03519",
        "FeedID":44018,
        "PachubeFeed": "http://www.pachube.com/feeds/44018",
        "Device_ID": "KEIOSTE170",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Mito, Softbank"",
        "Latitude":36.346986,
        "Longitude":140.454404,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0159",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03361",
        "FeedID":44019,
        "PachubeFeed": "http://www.pachube.com/feeds/44019",
        "Device_ID": "KEIOSTE171",
        "Type":"WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Ishioka, Softbank"",
        "Latitude":36.196359,
        "Longitude":140.298063,
        "Height(m)":"0.6",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0160",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN": "A03546",
        "FeedID":44020,
        "PachubeFeed": "http://www.pachube.com/feeds/44020",
        "Device_ID": "KEIOSTE172",
        "Type": "WiFi",
        "FirmwareVersion":"12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Tateyama, Softbank"",
        "Latitude": 34.992629,
        "Longitude":139.873968,
        "Height(m)":"0.72",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0161",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03351",
        "FeedID":44021,
        "PachubeFeed": "http://www.pachube.com/feeds/44021",
        "Device_ID": "KEIOSTE173",
        "Type": "WiFi",
        "FirmwareVersion": "12/23/11",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""ShinGifu, Softbank"",
        "Latitude":35.412513,
        "Longitude":136.75884,
        "Height(m)":"0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0162",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03419",
        "FeedID":44022,
        "PachubeFeed": "http://www.pachube.com/feeds/44022",
        "Device_ID": "KEIOSTE174",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
```

```
"nGeigieID":"",
        "Inuse":"",
        "Location": ""HigashiHie, Softbank"",
        "Latitude":33.588278,
        "Longitude":130.43188,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0163",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02579",
        "FeedID":44023,
        "PachubeFeed": "http://www.pachube.com/feeds/44023",
        "Device_ID": "KEIOSTE175",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Takasu, Softbank"",
        "Latitude":133.575569,
        "Longitude":1,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0164",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02642",
        "FeedID":44024,
        "PachubeFeed": "http://www.pachube.com/feeds/44024",
        "Device_ID": "KEIOSTE176",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Fuzen, Softbank"",
        "Latitude":33.616383,
        "Longitude":131.145456,
        "Height(m)":"0.8",
```

```
"Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0165",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02621",
        "FeedID":44025,
        "PachubeFeed": "http://www.pachube.com/feeds/44025",
        "Device_ID": "KEIOSTE177",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Nangoku, Softbank"",
        "Latitude":33.5667,
        "Longitude":133.650654,
        "Height(m)":"0.6",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0166",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03475",
        "FeedID":44026,
        "PachubeFeed": "http://www.pachube.com/feeds/44026",
        "Device_ID": "KEIOSTE178",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Rifu, Softbank"",
        "Latitude":140.976975,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0167",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03511",
        "FeedID":44027,
        "PachubeFeed": "http://www.pachube.com/feeds/44027",
        "Device_ID": "KEIOSTE179",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Wakuya, Softbank"",
        "Latitude":38.529383,
        "Longitude":141.136689,
        "Height(m)":"1",
        "Indoor_Outdoor":"Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0168",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02602",
        "FeedID":44028,
        "PachubeFeed": "http://www.pachube.com/feeds/44028",
        "Device_ID": "KEIOSTE180",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Higashine, Softbank"",
        "Latitude":38.431263,
        "Longitude":140.394193,
        "Height(m)": "0.85",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0169",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02618",
        "FeedID":44029,
        "PachubeFeed": "http://www.pachube.com/feeds/44029",
        "Device_ID": "KEIOSTE181",
```

```
"Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""YamagataNishi, Softbank"",
        "Latitude":38.241442,
        "Longitude":140.307628,
        "Height(m)":"0.8",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0170",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02481",
        "FeedID":44030,
        "PachubeFeed": "http://www.pachube.com/feeds/44030",
        "Device_ID": "KEIOSTE182",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Oyama, Softbank"",
        "Latitude":36.318555,
        "Longitude":139.814279,
        "Height(m)":"0.9",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0171",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03704",
        "FeedID":44031,
        "PachubeFeed": "http://www.pachube.com/feeds/44031",
        "Device_ID": "KEIOSTE183",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Yanagiu, Softbank"",
        "Latitude":140.870519,
```

```
"Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":""
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0172",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02690",
        "FeedID":44032,
        "PachubeFeed": "http://www.pachube.com/feeds/44032",
        "Device_ID": "KEIOSTE184",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""SakuraUsui, Softbank"",
        "Latitude":140.18204,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0173",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03582",
        "FeedID":44033,
        "PachubeFeed": "http://www.pachube.com/feeds/44033",
        "Device_ID": "KEIOSTE185",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""SendaiSakuragaoka, Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#0175",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02566",
        "FeedID":44035,
        "PachubeFeed": "http://www.pachube.com/feeds/44035",
        "Device_ID": "KEIOSTE187",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Yaotome(Miyagi), Softbank"",
        "Latitude":38.311086,
        "Longitude":140.889334,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0176",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02542",
        "FeedID":46064,
        "PachubeFeed": "http://www.pachube.com/feeds/46064",
        "Device_ID": "KEIOSTE191",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Gotanda, Softbank"",
        "Latitude":35.626893,
        "Longitude":139.721317,
        "Height(m)":"0.7",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0177",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02563",
        "FeedID":46065,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/46065",
        "Device_ID": "KEIOSTE192",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":""
        "Location": ""KawasakiDaishi, Softbank"",
        "Latitude":35.535094,
        "Longitude":139.728032,
        "Height(m)":"0.6",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0178",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03069",
        "FeedID":46066,
        "PachubeFeed": "http://www.pachube.com/feeds/46066",
        "Device_ID": "KEIOSTE193",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": "Toyoda, Softbank"",
        "Latitude":35.660394,
        "Longitude":139.380684,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0179",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02903",
        "FeedID":46067,
        "PachubeFeed": "http://www.pachube.com/feeds/46067",
        "Device_ID": "KEIOSTE194",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
```

```
"Location": ""Tsubata(Ishikawa), Softbank"",
        "Latitude":36.662014,
        "Longitude": 136.72827,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0180",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02641",
        "FeedID":46068,
        "PachubeFeed": "http://www.pachube.com/feeds/46068",
        "Device_ID": "KEIOSTE195",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Toyodacho(Shizuoka), Softbank"",
        "Latitude":137.821524,
        "Longitude":1,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0181",
        "Status":""
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03415",
        "FeedID":46069,
        "PachubeFeed": "http://www.pachube.com/feeds/46069",
        "Device_ID": "KEIOSTE196",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Komatsu(Ishikawa), Softbank"",
        "Latitude":36.394204,
        "Longitude":136.453835,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0182",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03218",
        "FeedID":46070,
        "PachubeFeed": "http://www.pachube.com/feeds/46070",
        "Device_ID": "KEIOSTE197",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Kozuru(Kozuru), Softbank"",
        "Latitude":38.282168,
        "Longitude":140.926124,
        "Height(m)":"0.85",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID":"#0183",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03368",
        "FeedID":46071,
        "PachubeFeed": "http://www.pachube.com/feeds/46071",
        "Device_ID": "KEIOSTE198",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""KozojiNewTown(Aichi), Softbank"",
        "Latitude":137.049095,
        "Longitude":0.8,
        "Height(m)":"Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0184",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN": "A02583",
        "FeedID":46072,
        "PachubeFeed": "http://www.pachube.com/feeds/46072",
        "Device_ID": "KEIOSTE199",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""ToyokawaInter(Aichi), Softbank"",
        "Latitude":137.400273,
        "Longitude":0.6,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action needed":""
},{
        "KEIO_STE_ID": "#0185",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03472",
        "FeedID":46073,
        "PachubeFeed": "http://www.pachube.com/feeds/46073",
        "Device_ID": "KEIOSTE200",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Hamamatsu(Shizuoka), Softbank"",
        "Latitude": 34.705516,
        "Longitude":137.728806,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0186",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02573",
        "FeedID":46074,
        "PachubeFeed": "http://www.pachube.com/feeds/46074",
        "Device_ID": "KEIOSTE201",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
```

```
"nGeigieID":"",
        "Inuse":"",
        "Location": ""ToyokawaNishi(Aichi), Softbank"",
        "Latitude":137.323984,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"".
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0187",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03376",
        "FeedID":46075,
        "PachubeFeed": "http://www.pachube.com/feeds/46075",
        "Device_ID": "KEIOSTE202",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Yotsui(Fukui), Softbank"",
        "Latitude":136.241848,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":"y"
},{
        "KEIO_STE_ID": "#0188",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03439",
        "FeedID":46076,
        "PachubeFeed": "http://www.pachube.com/feeds/46076",
        "Device_ID": "KEIOSTE203",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Nanaehama(Hokkaido), Softbank"",
        "Latitude":0.9,
        "Longitude": Indoor,
        "Height(m)":"",
```

```
"Indoor_Outdoor":"1F",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0189",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03378",
        "FeedID":46077,
        "PachubeFeed": "http://www.pachube.com/feeds/46077",
        "Device_ID":"KEIOSTE204",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Yoshikawa(Saitama), Softbank"",
        "Latitude":139.846761,
        "Longitude":0.7,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0190",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02686",
        "FeedID":46078,
        "PachubeFeed": "http://www.pachube.com/feeds/46078",
        "Device_ID": "KEIOSTE205",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Ohfunato(Iwate), Softbank"",
        "Latitude":39.085378,
        "Longitude":141.710394,
        "Height(m)":"1.1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0191",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN":"",
        "FeedID":46079,
        "PachubeFeed": "http://www.pachube.com/feeds/46079",
        "Device_ID": "KEIOSTE206",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Owase(Mie), Softbank"",
        "Latitude":136.191595,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0192",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02659",
        "FeedID":46080,
        "PachubeFeed": "http://www.pachube.com/feeds/46080",
        "Device_ID": "KEIOSTE207",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Furumachi(Niigata), Softbank"",
        "Latitude":37.922167,
        "Longitude":139.042548,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0193",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03398",
        "FeedID":46081,
        "PachubeFeed": "http://www.pachube.com/feeds/46081",
        "Device_ID": "KEIOSTE208",
```

```
"Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Miyamachi(Miyaqi), Softbank"",
        "Latitude":38.273851,
        "Longitude":140.884971,
        "Height(m)":"",
        "Indoor_Outdoor":""
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0194",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02545",
        "FeedID":46082,
        "PachubeFeed": "http://www.pachube.com/feeds/46082",
        "Device_ID": "KEIOSTE209",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Sakurada(Yamagata), Softbank"",
        "Latitude":140.315244,
        "Longitude":0.9,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0195",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03404",
        "FeedID":46083,
        "PachubeFeed": "http://www.pachube.com/feeds/46083",
        "Device_ID": "KEIOSTE210",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Ishinomaki (Miyagi), Softbank"",
        "Latitude":141.268436,
```

```
"Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0196",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04646",
        "FeedID":46084,
        "PachubeFeed": "http://www.pachube.com/feeds/46084",
        "Device_ID": "KEIOSTE211",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Shikajima(Ibaraki), Softbank"",
        "Latitude":140.639004,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0197",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04653",
        "FeedID":46085,
        "PachubeFeed": "http://www.pachube.com/feeds/46085",
        "Device_ID": "KEIOSTE212",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Kesennuma, Softbank"",
        "Latitude":141.559247,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"".
        "Action_needed":"y"
},{
```

```
"KEIO_STE_ID": "#0198",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04662",
        "FeedID":46086,
        "PachubeFeed": "http://www.pachube.com/feeds/46086",
        "Device_ID": "KEIOSTE213",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Miyauchi(Niigata), Softbank"",
        "Latitude":1,
        "Longitude": Indoor,
        "Height(m)":"",
        "Indoor_Outdoor":"1F",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0199",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A04779",
        "FeedID":46087,
        "PachubeFeed": "http://www.pachube.com/feeds/46087",
        "Device_ID": "KEIOSTE214",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Ohirota(Toyama), Softbank"",
        "Latitude":36.742203,
        "Longitude":137.24472,
        "Height(m)":"",
        "Indoor_Outdoor":""
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0200",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02471",
        "FeedID":46088,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/46088",
        "Device_ID": "KEIOSTE215",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":""
        "Location": ""Gokoh(Chiba), Softbank"",
        "Latitude":139.9794,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0201",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02605",
        "FeedID":46089,
        "PachubeFeed": "http://www.pachube.com/feeds/46089",
        "Device_ID": "KEIOSTE216",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""OhmiyaHigashi, Softbank"",
        "Latitude":35.919152,
        "Longitude":139.651716,
        "Height(m)":"",
        "Indoor_Outdoor":"".
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0202",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02919",
        "FeedID":46090,
        "PachubeFeed": "http://www.pachube.com/feeds/46090",
        "Device_ID": "KEIOSTE217",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
```

```
"Location": ""Nitta(Gunma), Softbank"",
        "Latitude":36.303736,
        "Longitude":139.304074,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0203",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03031",
        "FeedID":46091,
        "PachubeFeed": "http://www.pachube.com/feeds/46091",
        "Device_ID": "KEIOSTE218",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Yatabe, Softbank"",
        "Latitude":36.038722,
        "Longitude":140.08156,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0204",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03365",
        "FeedID":46092,
        "PachubeFeed": "http://www.pachube.com/feeds/46092",
        "Device_ID": "KEIOSTE219",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""SanjyoChuo, Softbank"",
        "Latitude":138.959309,
        "Longitude":1,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0205",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03801",
        "FeedID":46093,
        "PachubeFeed": "http://www.pachube.com/feeds/46093",
        "Device_ID": "KEIOSTE220",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Gotokuji, Softbank"",
        "Latitude":35.652405,
        "Longitude":139.646636,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0206",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03572",
        "FeedID":46094,
        "PachubeFeed": "http://www.pachube.com/feeds/46094",
        "Device_ID": "KEIOSTE221",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""NishitagaIchome, Softbank"",
        "Latitude":140.86343,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0207",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN": "A03800",
        "FeedID":46095,
        "PachubeFeed": "http://www.pachube.com/feeds/46095",
        "Device_ID": "KEIOSTE222",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Nagatsuda, Softbank"",
        "Latitude":139.498214,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0208",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"A03494",
        "FeedID":46096,
        "PachubeFeed": "http://www.pachube.com/feeds/46096",
        "Device_ID": "KEIOSTE223",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""MoriokaOhta, Softbank"",
        "Latitude":39.689428,
        "Longitude":141.119068,
        "Height(m)":"1",
        "Indoor_Outdoor": "Indoor",
        "Action_needed":"1F"
},{
        "KEIO_STE_ID": "#0209",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03389",
        "FeedID":46097,
        "PachubeFeed": "http://www.pachube.com/feeds/46097",
        "Device_ID": "KEIOSTE224",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
```

```
"nGeigieID":"",
        "Inuse":"",
        "Location": ""Tsukigaoka, Softbank"",
        "Latitude":141.111706,
        "Longitude":0.7,
        "Height(m)": "Indoor",
        "Indoor_Outdoor":"",
        "Action_needed": "KEIOSTE226"
},{
        "KEIO_STE_ID": "#0210",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03243",
        "FeedID":46098,
        "PachubeFeed": "http://www.pachube.com/feeds/46098",
        "Device_ID": "KEIOSTE225",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Ainosato(Hokkaido), Softbank"",
        "Latitude": Inspector Alert,
        "Longitude": A03242,
        "Height(m)": "46099",
        "Indoor_Outdoor": "http://www.pachube.com/feeds/46099",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0213",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03236",
        "FeedID":46101,
        "PachubeFeed": "http://www.pachube.com/feeds/46101",
        "Device_ID": "KEIOSTE228",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Shimizu(Shizuoka), Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
```

```
"Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0214",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN":"",
        "FeedID":46102,
        "PachubeFeed": "http://www.pachube.com/feeds/46102",
        "Device_ID": "KEIOSTE229",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Namidate(Aomori), Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0215",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03418",
        "FeedID":46103,
        "PachubeFeed": "http://www.pachube.com/feeds/46103",
        "Device_ID": "KEIOSTE230",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Kanazawakencho, Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed": "KEIOSTE241"
},{
        "KEIO_STE_ID": "#0216",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02658",
        "FeedID":38693,
        "PachubeFeed": "http://www.pachube.com/feeds/38693",
        "Device_ID": "KEIOSTE240",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":""Toyokawa(Aichi), Softbank"",
        "Latitude": Inspector Alert,
        "Longitude": A02667,
        "Height(m)": "37131",
        "Indoor_Outdoor":"http://www.pachube.com/feeds/37131",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0218",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03029",
        "FeedID":38692,
        "PachubeFeed": "http://www.pachube.com/feeds/38692",
        "Device_ID": "KEIOSTE242",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""KamiIida(Aichi), Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0219",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03229",
        "FeedID":38688,
        "PachubeFeed": "http://www.pachube.com/feeds/38688",
        "Device_ID": "KEIOSTE243",
```

```
"Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""YonezawaChuo, Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0220",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04144",
        "FeedID": 37759,
        "PachubeFeed": "http://www.pachube.com/feeds/37759",
        "Device_ID": "KEIOSTE244",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""OgakiWago(Gifu), Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed": "KEIOSTE246"
},{
        "KEIO_STE_ID": "#0221",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03388",
        "FeedID":47762,
        "PachubeFeed": "http://www.pachube.com/feeds/47762",
        "Device_ID": "KEIOSTE245",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Nagahama(Shiga), Softbank"",
        "Latitude": Inspector Alert,
```

```
"Longitude": A04159,
        "Height(m)":"47763",
        "Indoor_Outdoor": "http://www.pachube.com/feeds/47763",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0225",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04399",
        "FeedID":47766,
        "PachubeFeed": "http://www.pachube.com/feeds/47766",
        "Device_ID": "KEIOSTE249",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""Kameoka(Kyoto), Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0226",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04537",
        "FeedID":47767,
        "PachubeFeed": "http://www.pachube.com/feeds/47767",
        "Device_ID": "KEIOSTE250",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#0227",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03422",
        "FeedID":47768,
        "PachubeFeed": "http://www.pachube.com/feeds/47768",
        "Device_ID": "KEIOSTE251",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0228",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03465",
        "FeedID":47769,
        "PachubeFeed": "http://www.pachube.com/feeds/47769",
        "Device_ID": "KEIOSTE252",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0229",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03469",
        "FeedID":47770,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/47770",
        "Device_ID": "KEIOSTE253",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":""
        "Location": ""Kosaka(Osaka), Softbank"",
        "Latitude":,
        "Longitude":,
        "Height(m)":""
        "Indoor_Outdoor":"",
        "Action_needed": "KEIOSTE255"
},{
        "KEIO_STE_ID": "#0230",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A03486",
        "FeedID":47771,
        "PachubeFeed": "http://www.pachube.com/feeds/47771",
        "Device_ID": "KEIOSTE254",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location": ""AkeshiFutami(Hyogo), Softbank"",
        "Latitude": Inspector Alert,
        "Longitude": A03486,
        "Height(m)":"47772",
        "Indoor_Outdoor": "http://www.pachube.com/feeds/47772",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0232",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02225",
        "FeedID":47773,
        "PachubeFeed": "http://www.pachube.com/feeds/47773",
        "Device_ID": "KEIOSTE256",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
```

```
"Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0233",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02249",
        "FeedID":47774,
        "PachubeFeed": "http://www.pachube.com/feeds/47774",
        "Device_ID": "KEIOSTE257",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0234",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02276",
        "FeedID":47775,
        "PachubeFeed": "http://www.pachube.com/feeds/47775",
        "Device_ID": "KEIOSTE258",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0235",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A02567",
        "FeedID":47776,
        "PachubeFeed": "http://www.pachube.com/feeds/47776",
        "Device_ID": "KEIOSTE259",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0236",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A02577",
        "FeedID":47777,
        "PachubeFeed": "http://www.pachube.com/feeds/47777",
        "Device_ID": "KEIOSTE260",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0237",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
```

```
"Inspector_SN": "A04641",
        "FeedID":47778,
        "PachubeFeed": "http://www.pachube.com/feeds/47778",
        "Device_ID": "KEIOSTE261",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0238",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04642",
        "FeedID":47779,
        "PachubeFeed": "http://www.pachube.com/feeds/47779",
        "Device_ID": "KEIOSTE262",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0239",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04156",
        "FeedID":47780,
        "PachubeFeed": "http://www.pachube.com/feeds/47780",
        "Device_ID": "KEIOSTE263",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
```

```
"nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0240",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04637",
        "FeedID":47781,
        "PachubeFeed": "http://www.pachube.com/feeds/47781",
        "Device_ID": "KEIOSTE264",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0241",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04654",
        "FeedID":47782,
        "PachubeFeed": "http://www.pachube.com/feeds/47782",
        "Device_ID": "KEIOSTE265",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
```

```
"Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0242",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04660",
        "FeedID":47783,
        "PachubeFeed": "http://www.pachube.com/feeds/47783",
        "Device_ID": "KEIOSTE266",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0243",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"",
        "Inspector_SN":"",
        "FeedID":47784,
        "PachubeFeed": "http://www.pachube.com/feeds/47784",
        "Device_ID": "KEIOSTE267",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0244",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A04143",
        "FeedID":47785,
        "PachubeFeed": "http://www.pachube.com/feeds/47785",
        "Device_ID": "KEIOSTE268",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0245",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04148",
        "FeedID":47786,
        "PachubeFeed": "http://www.pachube.com/feeds/47786",
        "Device_ID": "KEIOSTE269",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0246",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04169",
        "FeedID":47787,
        "PachubeFeed": "http://www.pachube.com/feeds/47787",
        "Device_ID": "KEIOSTE270",
```

```
"Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0247",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04175",
        "FeedID":47788,
        "PachubeFeed": "http://www.pachube.com/feeds/47788",
        "Device_ID": "KEIOSTE271",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0248",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04401",
        "FeedID":47789,
        "PachubeFeed": "http://www.pachube.com/feeds/47789",
        "Device_ID": "KEIOSTE272",
        "Type":"WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
```

```
"Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0249",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"",
        "Inspector_SN":"",
        "FeedID":47790,
        "PachubeFeed": "http://www.pachube.com/feeds/47790",
        "Device_ID": "KEIOSTE273",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0250",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A04659",
        "FeedID":47791,
        "PachubeFeed": "http://www.pachube.com/feeds/47791",
        "Device_ID": "KEIOSTE274",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
```

```
"KEIO_STE_ID": "#0251",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"",
        "Inspector_SN":"",
        "FeedID":47792,
        "PachubeFeed": "http://www.pachube.com/feeds/47792",
        "Device_ID": "KEIOSTE275",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0252",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A04141",
        "FeedID":47793,
        "PachubeFeed": "http://www.pachube.com/feeds/47793",
        "Device_ID": "KEIOSTE276",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0253",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04155",
        "FeedID":47794,
```

```
"PachubeFeed": "http://www.pachube.com/feeds/47794",
        "Device_ID": "KEIOSTE277",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0254",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A04176",
        "FeedID":47795,
        "PachubeFeed": "http://www.pachube.com/feeds/47795",
        "Device_ID": "KEIOSTE278",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0255",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A04177",
        "FeedID":47796,
        "PachubeFeed": "http://www.pachube.com/feeds/47796",
        "Device_ID": "KEIOSTE279",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
```

```
"Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0256",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04381",
        "FeedID":47797,
        "PachubeFeed": "http://www.pachube.com/feeds/47797",
        "Device_ID": "KEIOSTE280",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0257",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04535",
        "FeedID":47798,
        "PachubeFeed": "http://www.pachube.com/feeds/47798",
        "Device_ID": "KEIOSTE281",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
```

```
},{
        "KEIO_STE_ID": "#0258",
        "Status":"",
        "Safecast_ID":"".
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04621",
        "FeedID":47799,
        "PachubeFeed": "http://www.pachube.com/feeds/47799",
        "Device_ID": "KEIOSTE282",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0259",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A04645",
        "FeedID":47800,
        "PachubeFeed": "http://www.pachube.com/feeds/47800",
        "Device_ID": "KEIOSTE283",
        "Type": "WiFi",
        "FirmwareVersion":"1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0260",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"",
```

```
"Inspector_SN":"",
        "FeedID":47801,
        "PachubeFeed": "http://www.pachube.com/feeds/47801",
        "Device_ID": "KEIOSTE284",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0261",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A03953",
        "FeedID":47802,
        "PachubeFeed": "http://www.pachube.com/feeds/47802",
        "Device_ID": "KEIOSTE285",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0262",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04153",
        "FeedID":47803,
        "PachubeFeed": "http://www.pachube.com/feeds/47803",
        "Device_ID": "KEIOSTE286",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
```

```
"nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID":"#0263",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04400",
        "FeedID":47804,
        "PachubeFeed": "http://www.pachube.com/feeds/47804",
        "Device_ID": "KEIOSTE287",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0264",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04532",
        "FeedID":47805,
        "PachubeFeed": "http://www.pachube.com/feeds/47805",
        "Device_ID": "KEIOSTE288",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
```

```
"Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0265",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04536",
        "FeedID":47806,
        "PachubeFeed": "http://www.pachube.com/feeds/47806",
        "Device_ID": "KEIOSTE289",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0266",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04540",
        "FeedID":47807,
        "PachubeFeed": "http://www.pachube.com/feeds/47807",
        "Device_ID": "KEIOSTE290",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0267",
        "Status":"",
```

```
"Safecast_ID":"",
        "Sensor_Type":"Inspector Alert",
        "Inspector_SN": "A04542",
        "FeedID":47808,
        "PachubeFeed": "http://www.pachube.com/feeds/47808",
        "Device_ID": "KEIOSTE291",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0268",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type":"",
        "Inspector_SN":"",
        "FeedID":47809,
        "PachubeFeed": "http://www.pachube.com/feeds/47809",
        "Device_ID": "KEIOSTE292",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0269",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04668",
        "FeedID":47810,
        "PachubeFeed": "http://www.pachube.com/feeds/47810",
        "Device_ID": "KEIOSTE293",
```

```
"Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0270",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A04669",
        "FeedID":47811,
        "PachubeFeed": "http://www.pachube.com/feeds/47811",
        "Device_ID": "KEIOSTE294",
        "Type": "WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
        "Longitude":,
        "Height(m)":"",
        "Indoor_Outdoor":"",
        "Action_needed":""
},{
        "KEIO_STE_ID": "#0301",
        "Status":"",
        "Safecast_ID":"",
        "Sensor_Type": "Inspector Alert",
        "Inspector_SN": "A01966",
        "FeedID":48122,
        "PachubeFeed": "http://www.pachube.com/feeds/48122",
        "Device_ID": "KEIOSTE48",
        "Type":"WiFi",
        "FirmwareVersion": "1/20/12",
        "nGeigieID":"",
        "Inuse":"",
        "Location":"",
        "Latitude":,
```

```
"Longitude":,
                 "Height(m)":"",
                 "Indoor_Outdoor":"",
                 "Action_needed":""
        },{
                 "KEIO_STE_ID": "#0302",
                 "Status":"",
                 "Safecast_ID":"",
                 "Sensor_Type": "Inspector Alert",
                 "Inspector_SN": "A03466",
                 "FeedID":48150,
                 "PachubeFeed": "http://www.pachube.com/feeds/48150",
                 "Device_ID": "Ritsumeikan1",
                 "Type": "Ethernet",
                 "FirmwareVersion":"1/20/12",
                 "nGeigieID":"",
                 "Inuse":"",
                 "Location":"",
                 "Latitude":,
                 "Longitude":,
                 "Height(m)":"",
                 "Indoor_Outdoor":"",
                 "Action_needed":""
        },
]}
```