Page 1 of 8

| Qty | Radiator Assembly SKU | Structural Panel Left | Structural Panel Right | Leveling Panel (x2) | Aesthetic Panel (x2) | Top Panel | Front Panel | Back Panel | Cover Panel Left | Cover Panel Right | Insul. | Xbee | Steam Traps | Radiator Id |
|-----|---------------------------------|--------------------------|---------------------------|------------------------|-------------------------|-----------|-------------|------------|------------------------|-------------------------|--------|---------|----------------|-------------------|
| 1 | 22_M_23.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP230075 | FP230240 | BP230160 | IGX | IBC | Board | Regular | None | 00018005019001000 |
| 1 | 22_M_23.0_11.5_30.0_GX_BC_B_R_N | SPL115300 | SPR115300 | LP115 | AP115300 | TP230115 | FP230300 | BP230220 | IGX | IBC | Board | Regular | None | 00018005020003000 |
| 2 | 22_M_23.0_11.5_42.0_BC_GX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP230115 | FP230420 | BP230340 | IBC | IGX | Board | Regular | None | 00018002009001000 |
| | 22_M_23.0_11.5_42.0_BC_GX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP230115 | FP230420 | BP230340 | IBC | IGX | Board | Regular | None | 00018005020001000 |
| 1 | 22_M_23.0_11.5_42.0_BC_GX_F_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP230115 | FP230420 | BP230340 | IBC | IGX | Fabric | Regular | None | 00018002009003000 |
| 2 | 22_M_23.0_11.5_42.0_GX_BC_B_P_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP230115 | FP230420 | BP230340 | IGX | IBC | Board | Pro | None | 00018000002000000 |
| | 22_M_23.0_11.5_42.0_GX_BC_B_P_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP230115 | FP230420 | BP230340 | IGX | IBC | Board | Pro | None | 00018000003002000 |
| 2 | 22_M_23.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP230115 | FP230420 | BP230340 | IGX | IBC | Board | Regular | None | 00018001004001000 |

| | 22_M_23.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP230115 | FP230420 | BP230340 | IGX | IBC | Board | Regular | None | 00018002008002000 |
|---|---------------------------------|-----------|-----------|-------|----------|----------|----------|----------|-----|-----|-------|---------|------|-------------------|
| 1 | 22_M_29.0_7.5_24.0_BC_GX_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP290075 | FP290240 | BP290160 | IBC | IGX | Board | Regular | None | 00018003012000000 |
| 2 | 22_M_29.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP290075 | FP290240 | BP290160 | IGX | IBC | Board | Regular | None | 00018000002002000 |
| | 22_M_29.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP290075 | FP290240 | BP290160 | IGX | IBC | Board | Regular | None | 00018005018006000 |
| 1 | 22_M_29.0_7.5_30.0_GX_BC_B_P_N | SPL075300 | SPR075300 | LP075 | AP075300 | TP290075 | FP290300 | BP290220 | IGX | IBC | Board | Pro | None | 00018001004002000 |
| 2 | 22_M_29.0_7.5_30.0_GX_BC_B_R_N | SPL075300 | SPR075300 | LP075 | AP075300 | TP290075 | FP290300 | BP290220 | IGX | IBC | Board | Regular | None | 00018002008000000 |
| | 22_M_29.0_7.5_30.0_GX_BC_B_R_N | SPL075300 | SPR075300 | LP075 | AP075300 | TP290075 | FP290300 | BP290220 | IGX | IBC | Board | Regular | None | 00018003012003000 |
| 1 | 22_M_29.0_7.5_30.0_GX_BX_B_R_N | SPL075300 | SPR075300 | LP075 | AP075300 | TP290075 | FP290300 | BP290220 | IGX | IBX | Board | Regular | None | 00018000000003000 |
| 1 | 22_M_29.0_9.5_24.0_BC_GX_B_R_N | SPL095240 | SPR095240 | LP095 | AP095240 | TP290095 | FP290240 | BP290160 | IBC | IGX | Board | Regular | None | 00018002009002000 |

| 1 22_M_29.0_11.5_30.0_BC_GX_B_R_N | SPL115300 | SPR115300 | LP115 | AP115300 | TP290115 | FP290300 | BP290220 | IBC | IGX | Board | Regular | None | 00018003013001000 |
|-----------------------------------|-----------|-----------|-------|----------|----------|----------|----------|-----|-----|--------|---------|------|-------------------|
| 1 22_M_29.0_11.5_42.0_BC_GX_B_P_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP290115 | FP290420 | BP290340 | IBC | IGX | Board | Pro | None | 00018001006000000 |
| 1 22_M_29.0_11.5_42.0_BX_GX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP290115 | FP290420 | BP290340 | IBX | IGX | Board | Regular | None | 00018000001001000 |
| 1 22_M_29.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP290115 | FP290420 | BP290340 | IGX | IBC | Board | Regular | None | 00018004015001000 |
| 1 22_M_29.0_11.5_42.0_GX_BX_F_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP290115 | FP290420 | BP290340 | IGX | IBX | Fabric | Regular | None | 00018002009004000 |
| 1 22_M_29.0_13.5_36.0_BC_GX_B_R_N | SPL135360 | SPR135360 | LP135 | AP135360 | TP290135 | FP290360 | BP290280 | IBC | IGX | Board | Regular | None | 00018004017002000 |
| 1 22_M_29.0_13.5_36.0_GX_BX_B_R_N | SPL135360 | SPR135360 | LP135 | AP135360 | TP290135 | FP290360 | BP290280 | IGX | IBX | Board | Regular | None | 00018004016004000 |
| 1 22_M_35.0_7.5_24.0_BC_GX_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP350075 | FP350240 | BP350160 | IBC | IGX | Board | Regular | None | 00018001005001000 |
| 1 22_M_35.0_7.5_24.0_BC_GX_F_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP350075 | FP350240 | BP350160 | IBC | IGX | Fabric | Regular | None | 00018001007000000 |

| 2 22_M_35.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP350075 | FP350240 | BP350160 | IGX | IBC | Board | Regular | None | 00018000000002000 |
|-----------------------------------|-----------|-----------|-------|----------|----------|----------|----------|-----|-----|-------|---------|------|-------------------|
| 22_M_35.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP350075 | FP350240 | BP350160 | IGX | IBC | Board | Regular | None | 00018004016003000 |
| 1 22_M_35.0_7.5_24.0_GX_BX_B_P_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP350075 | FP350240 | BP350160 | IGX | IBX | Board | Pro | None | 00018002008003000 |
| 1 22_M_35.0_9.5_24.0_GX_BC_B_R_N | SPL095240 | SPR095240 | LP095 | AP095240 | TP350095 | FP350240 | BP350160 | IGX | IBC | Board | Regular | None | 00018003012002000 |
| 1 22_M_35.0_11.5_24.0_GX_BC_B_P_N | SPL115240 | SPR115240 | LP115 | AP115240 | TP350115 | FP350240 | BP350160 | IGX | IBC | Board | Pro | None | 00018005018005000 |
| 1 22_M_35.0_11.5_24.0_GX_BC_B_R_N | SPL115240 | SPR115240 | LP115 | AP115240 | TP350115 | FP350240 | BP350160 | IGX | IBC | Board | Regular | None | 00018005018007000 |
| 1 22_M_35.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP350115 | FP350420 | BP350340 | IGX | IBC | Board | Regular | None | 00018005020002000 |
| 3 22_M_35.0_11.5_42.0_GX_BX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP350115 | FP350420 | BP350340 | IGX | IBX | Board | Regular | None | 00018000003000000 |
| 22_M_35.0_11.5_42.0_GX_BX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP350115 | FP350420 | BP350340 | IGX | IBX | Board | Regular | None | 00018001004003000 |

| | | | | | | . 0 | | | | | | | | |
|---|---------------------------------|-----------|-----------|-------|----------|----------|----------|----------|-----|-----|-------|---------|------|-------------------|
| | 22_M_35.0_11.5_42.0_GX_BX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP350115 | FP350420 | BP350340 | IGX | IBX | Board | Regular | None | 00018004015003000 |
| 1 | 22_M_41.0_7.5_24.0_BC_GX_B_P_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP410075 | FP410240 | BP410160 | IBC | IGX | Board | Pro | None | 00018003012001000 |
| 2 | 22_M_41.0_7.5_24.0_BC_GX_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP410075 | FP410240 | BP410160 | IBC | IGX | Board | Regular | None | 00018001005000000 |
| | 22_M_41.0_7.5_24.0_BC_GX_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP410075 | FP410240 | BP410160 | IBC | IGX | Board | Regular | None | 00018002008001000 |
| 2 | 22_M_41.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP410075 | FP410240 | BP410160 | IGX | IBC | Board | Regular | None | 00018001007002000 |
| | 22_M_41.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP410075 | FP410240 | BP410160 | IGX | IBC | Board | Regular | None | 00018003012004000 |
| 2 | 22_M_41.0_11.5_24.0_BC_GX_B_R_N | SPL115240 | SPR115240 | LP115 | AP115240 | TP410115 | FP410240 | BP410160 | IBC | IGX | Board | Regular | None | 00018005018001000 |
| | 22_M_41.0_11.5_24.0_BC_GX_B_R_N | SPL115240 | SPR115240 | LP115 | AP115240 | TP410115 | FP410240 | BP410160 | IBC | IGX | Board | Regular | None | 00018005018004000 |
| 1 | 22_M_41.0_11.5_42.0_BC_GX_B_P_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IBC | IGX | Board | Pro | None | 00018003013000000 |

| 3 22_M_41.0_11.5_42.0_BC_GX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IBC | IGX | Board | Regular | None | 00018001004000000 |
|-----------------------------------|-----------|-----------|-------|----------|----------|----------|----------|-----|-----|--------|---------|------|-------------------|
| 22_M_41.0_11.5_42.0_BC_GX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IBC | IGX | Board | Regular | None | 00018001007001000 |
| 22_M_41.0_11.5_42.0_BC_GX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IBC | IGX | Board | Regular | None | 00018005020000000 |
| 1 22_M_41.0_11.5_42.0_BC_GX_F_P_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IBC | IGX | Fabric | Pro | None | 00018004017000000 |
| 1 22_M_41.0_11.5_42.0_BX_GX_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IBX | IGX | Board | Regular | None | 00018000003001000 |
| 4 22_M_41.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IGX | IBC | Board | Regular | None | 00018000001000000 |
| 22_M_41.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IGX | IBC | Board | Regular | None | 00018000001002000 |
| 22_M_41.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IGX | IBC | Board | Regular | None | 00018002011000000 |
| 22_M_41.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP410115 | FP410420 | BP410340 | IGX | IBC | Board | Regular | None | 00018004017001000 |

| 1 | 22_M_47.0_7.5_24.0_BC_GX_B_P_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP470075 | FP470240 | BP470160 | IBC | IGX | Board | Pro | None | 00018000000001000 |
|---|---------------------------------|-----------|-----------|-------|----------|----------|----------|----------|-----|-----|--------|---------|------|--------------------|
| 1 | 22_M_47.0_7.5_24.0_BC_GX_F_P_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP470075 | FP470240 | BP470160 | IBC | IGX | Fabric | Pro | None | 00018004015000000 |
| 2 | 22_M_47.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP470075 | FP470240 | BP470160 | IGX | IBC | Board | Regular | None | 00018001005003000 |
| | 22_M_47.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP470075 | FP470240 | BP470160 | IGX | IBC | Board | Regular | None | 00018004016002000 |
| 1 | 22_M_47.0_11.5_24.0_GX_BC_B_R_N | SPL115240 | SPR115240 | LP115 | AP115240 | TP470115 | FP470240 | BP470160 | IGX | IBC | Board | Regular | None | 00018005018003000 |
| 1 | 22_M_47.0_11.5_42.0_GX_BC_B_R_N | SPL115420 | SPR115420 | LP115 | AP115420 | TP470115 | FP470420 | BP470340 | IGX | IBC | Board | Regular | None | 00018001006001000 |
| 1 | 22_M_53.0_7.5_24.0_BC_GX_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP530075 | FP530240 | BP530160 | IBC | IGX | Board | Regular | None | 00018004016001000 |
| 1 | 22_M_53.0_7.5_24.0_GX_BC_B_R_N | SPL075240 | SPR075240 | LP075 | AP075240 | TP530075 | FP530240 | BP530160 | IGX | IBC | Board | Regular | None | 000180000000000000 |
| 1 | 22_M_53.0_7.5_30.0_BC_GX_F_R_N | SPL075300 | SPR075300 | LP075 | AP075300 | TP530075 | FP530300 | BP530220 | IBC | IGX | Fabric | Regular | None | 00018001005002000 |

Page 8 of 8

| 1 22_M_53.0 | _9.5_24.0_GX_BC_B_P_N | SPL095240 | SPR095240 | LP095 | AP095240 | TP530095 | FP530240 | BP530160 | IGX | IBC | Board | Pro | None | 00018002010000000 |
|--------------------------|------------------------|-----------|-----------|-------|----------|----------|----------|----------|-----|-----|-------|---------|------|-------------------|
| 2 22_M_53.0 __ | _11.5_24.0_GX_BC_B_R_N | SPL115240 | SPR115240 | LP115 | AP115240 | TP530115 | FP530240 | BP530160 | IGX | IBC | Board | Regular | None | 00018003014001000 |
| 22_M_53.0 __ | _11.5_24.0_GX_BC_B_R_N | SPL115240 | SPR115240 | LP115 | AP115240 | TP530115 | FP530240 | BP530160 | IGX | IBC | Board | Regular | None | 00018004015002000 |
| 1 22_M_53.0 __ | _11.5_30.0_BC_GX_B_P_N | SPL115300 | SPR115300 | LP115 | AP115300 | TP530115 | FP530300 | BP530220 | IBC | IGX | Board | Pro | None | 00018005019000000 |
| 1 22_M_53.0 __ | _11.5_30.0_BX_GX_B_R_N | SPL115300 | SPR115300 | LP115 | AP115300 | TP530115 | FP530300 | BP530220 | IBX | IGX | Board | Regular | None | 00018000002001000 |
| 1 22_M_53.0 __ | _11.5_30.0_GX_BC_B_R_N | SPL115300 | SPR115300 | LP115 | AP115300 | TP530115 | FP530300 | BP530220 | IGX | IBC | Board | Regular | None | 00018005019002000 |