IGNITION (2RZ-FE, 3RZ-FE) SERVICE DATA

SS049-04

Spark plug	Recommended spark plug Recommended spark plug Correct electrode gap	DENSO made NGK made	K16R-U11 BKR5EYA-U 1.1 mm (0.043 in.)
Camshaft position sensor	Resistance		835 - 1,400 Ω 1,060 - 1,645 Ω
Crankshaft position sensor	Resistance	at cold NE+ – NE– at hot NE+ – NE–	

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 198