SFI (2RZ-FE, 3RZ-FE) SST (Special Service Tools)

PP2G3-0-

	09023–38400	Union Nut Wrench 14mm	Fuel line flare nut
	09268–41047	Injection Measuring Tool Set	
0 10	(09268–41091)	NO.7 Union	
	(90405–09015)	No.1 Union	
	09268-45014	EFI Fuel Pressure Gauge	
	(09268–41100)	Clamp	Except California Spec.
P	(09268–41300)	Clamp	California Spec.
	09816–30010	Oil Pressure Switch Socket	Knock sensor
	09842–30070	Wiring "F" EFI Inspection	
	09843–18040	Diagnosis Check Wire	

2003 TOYOTA TACOMA (RM1002U)

Author: Date:

66