PROPELLER SHAFT SERVICE DATA

SS05K-02

Propeller shaft runout		Max.	0.8 mm (0.031 in.)
Spider bearing axial play		Max.	0.05 mm (0.0020 in.)
Spider bearing selection		Mark	
Bearing cup outer diameter		None	29.008 – 29.021 mm (1.1420 – 1.1426 in.)
		Red	29.028 – 29.041 mm (1.1428 – 1.1433 in.)
Bearing hole inner diameter		None	29.000 – 29.020 mm (1.1417 – 1.1425 in.)
		Drill	29.021 – 29.042 mm (1.1426 – 1.1434 in.)
Snap ring thickness			
TMC made	Mark	Color	
	1	-	2.100 – 2.150 mm (0.0827 – 0.0846 in.)
	2	-	2.150 – 2.200 mm (0.0846 – 0.0866 in.)
	3	-	2.200 – 2.250 mm (0.0866 – 0.0886 in.)
	_	Brown	2.250 – 2.300 mm (0.0886 – 0.0906 in.)
	_	Blue	2.300 – 2.350 mm (0.0906 – 0.0925 in.)
	6	-	2.350 – 2.400 mm (0.0925 – 0.0945 in.)
	7	-	2.400 – 2.450 mm (0.0945 – 0.0965 in.)
	8	-	2.450 – 2.500 mm (0.0965 – 0.0984 in.)
DANA made		Color	
		Green	1.384 mm (0.0545 in.)
Red Black		1.435 mm (0.0565 in.)	
		1.486 mm (0.0585 in.)	
Copper			1.511 mm (0.0595 in.)
Silver		1.537 mm (0.0605 in.)	
Yellow Blue			1.588 mm (0.0625 in.)
			1.638 mm (0.0645 in.)

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 229