EQUIPMENT

PP09F-01

Dial indicator with magnetic base	Check drive plate runout
OBD II scan tool	
Straignt edge	Check torque converter clutch installation
Torque wrench	
Vernier calipers	Check torque converter clutch installation

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 120