AIR CONDITIONING SST (Special Service Tools)

PP3H8-0

07110-58060	Air Conditioner Service Tool Set	
(07117–58060)	Refrigerant Drain Service Valve	
(07117–58070)	T–Joint	
(07117–58080)	Quick Disconnect Adapter	
(07117–58090)	Quick Disconnect Adapter	
(07117–88060)	Refrigerant Charging Hose	
(07117–88070)	Refrigerant Charging Hose	
(07117–88080)	Refrigerant Charging Hose	
07112–66040	Magnetic Clutch Remover	
07112–76060	Magnetic Clutch Stopper	
09870-00025	A/C Quick Joint Puller No.2	Liquid tube
95416-00140	Gas Leak Detector <halogen detector="" leak=""> (DENSO Part No.)</halogen>	
	(07117–58070) (07117–58080) (07117–58090) (07117–88060) (07117–88070) (07117–88080) 07112–66040 07112–76060	(07117–58070) T–Joint (07117–58080) Quick Disconnect Adapter (07117–58090) Quick Disconnect Adapter (07117–88060) Refrigerant Charging Hose (07117–88070) Refrigerant Charging Hose (07117–88080) Refrigerant Charging Hose 07112–66040 Magnetic Clutch Remover 07112–76060 Magnetic Clutch Stopper 09870–00025 A/C Quick Joint Puller No.2 95416–00140 Gas Leak Detector <halogen detector="" leak=""></halogen>

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 165