INSPECTION

AC3FA-01

1. CHECK EVAPORATOR FINS FOR BLOCKAGE

If the fins are clogged, clean them with compressed air.

2. CHECK FITTING FOR CRACKS FOR SCRATCHES

If necessary repair or replace.

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 2514