
SA0BQ-02




REPLACEMENT

REPLACE COMPANION FLANGE DUST DEFLECTOR

(a) Using SST, a socket wrench and a press, remove the dust deflector.

SST 09950-00020



(b) Using SST and a press, install a new dust deflector. SST 09523–36010

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 2014