SFI (5VZ-FE) SST (Special Service Tools)

PP01D-13

| | 09023–38400 | Union Nut Wrench 14mm | Fuel line flare nut |
|----------|---------------|--|---------------------|
| | 09205–76030 | Cylinder Head Setting Bolt Tightening Adaptor | ECT sensor |
| | 09268–41047 | Injection Measuring Tool Set | |
| والمالية | (09268–41091) | NO.7 Union | |
| | (09268–52011) | Injection Measuring Attachment | |
| | 09268-45014 | EFI Fuel Pressure Gauge | |
| | 09817–16011 | Back-up Light Switch Tool | Knock sensor |
| | 09842–30070 | Wiring "F" EFI Inspection | |
| | 09843–18040 | Diagnosis Check Wire | |

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 69